

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

School: **P.S. 180 - BROOKLYN, 5601 16TH AVENUE, BROOKLYN, NY, 11204**

InspectionId	Inspection Type	Time In	Last Edited
1187022	MECHANICAL	2008-12-16 08:56AM	2009-05-08 10:49AM

***Asset Data***

Question	Answer
Heating Plant Oil Number	2
Have any Systems/Major Building Components been upgraded?	Systems: Heating plant and auxiliaries, climate control system, Gas fired DWH, sump pumps. Years: 2001 Systems: DX split system for MDF room Years: 2004

***Priority Condition***

No condition recorded

***Inspection***

Question	Response
<b>MECHANICAL</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Piping</b>	Does not exist
<b>Condenser Water Pump</b>	Does not exist
<b>Cooling Coils in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	UP TO 5 TONS:DEFECTIVE UNIT
Deficiency Location/Instance	MDF Room # 254
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Outdoor Unit</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Packaged / Rooftop Unit</b>	Does not exist
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not exist
<b>Window Type A/C</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>Damper Actuator</b>	Does not exist
<b>DDC Computer</b>	Does not exist
<b>Local Control Panel</b>	Does not exist
<b>Pneumatic PRV Station</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Pneumatic Tubing</b>	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>CLIMATE CONTROL SYSTEM</b>	
<b>Pneumatic Tubing</b>	
Deficiency	DEFECTIVE: LEAKS AIR
Deficiency Location/Instance	Room # 306,313
Deficiency Quantity	60
Quantity Uom	LF
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Refrigerated Air Dryer</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Air Compressor</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Thermostat</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Various locations
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Temperature Control Zone Valve</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement-1/3 for Audit
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Terminal Unit Thermostatic Valve</b>	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Various locations
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>COMPACTOR</b>	
Condition	Does not exist
<b>CONVEYING</b>	
Condition	Inspected
<b>Dumbwaiters</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Elevators</b>	
Condition	Does not exist
<b>Escalators</b>	
Condition	Does not exist
<b>Non-auditorium Handicap Lift</b>	
Condition	Does not exist
<b>Sidewalk / Ash Hoist</b>	
Condition	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>CONVEYING</b>	
<b>Sidewalk / Ash Hoist</b>	
Deficiency	No deficiencies recorded
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Does not exist
<b>Hydraulic/Pneumatic Booster System</b>	Inspected
<b>Domestic Cold Water Tank</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Pressure Booster Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Pressure Booster - Compressor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Service</b>	Inspected
<b>Service Piping (Water Main)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Main - Double Check Valve</b>	Does not exist
<b>Water Main - RPZ</b>	Does not exist
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Circulating Pump</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Basement-1/2- Bearings
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size	399 MBH/ 400 gal
Installation Year	2001
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out
Deficiency Quantity	3,000
Quantity Uom	L.F.

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Water Distribution Piping</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>House Trap</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Interior Floor Drain</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Interior Storm Piping</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out
Deficiency Quantity	1,250
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Sewage / Waste Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out
Deficiency Quantity	834
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LEAKS
Deficiency Location/Instance	Drinking fountain line from 5th to 1st floor,
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Sewage Ejector Pump</b>	
Does not exist	
<b>Sump Pump</b>	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Vent Piping</b>	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	
Does not exist	
<b>EMERGENCY GENERATOR</b>	
Does not exist	
<b>FIXTURES</b>	
Inspected	
<b>Staff And Other</b>	
Inspected	
<b>Boiler Room - Eye Wash</b>	
Does not exist	
<b>Janitor Sink</b>	
Inspected	
Condition	3- Fair
Deficiency	DEFECTIVE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Mechanical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Staff And Other</b>	
<b>Janitor Sink</b>	
Deficiency Location/Instance	3rd floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lavatory/Sink</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Student</b>	
Condition	Inspected
<b>Drinking Fountain</b>	
Condition	3- Fair
Deficiency	CLOGGED/DIRTY/LEAKING
Deficiency Location/Instance	4th floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lavatory/Sink</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	
Condition	3- Fair
Alternative Use	Yes
Deficiency	NOT IN USE
Deficiency Location/Instance	rooms# 660,3rd floor gym
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Sink And Fountain Combo Unit</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	5th floor,3rd floor
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Student</b>	
<b>Toilet</b>	
Violations	No violations recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Vent</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Pressure Booster</b>	Does not exist
<b>HEATING</b>	Inspected
<b>Baseboard/Fin Tube</b>	Does not exist
<b>Heating Coils In Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Hydronic Heating</b>	Does not exist
<b>Radiator / Convect</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out- some are newer
Deficiency Quantity	70
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MISSING GUARD/SHIELD
Deficiency Location/Instance	Rooms# 410,419,407 and 5th floor
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Various location-live steam after even changing element of thermo traps

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>F&amp;T/Steam Drip Trap</b>	
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>MER Steam and Condensate Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out
Deficiency Quantity	1,700
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return System</b>	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Steam Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	thru out
Deficiency Quantity	1,700
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Terminal Unit Thermostatic Trap</b>	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>STEAM SUPPLIED BY EXTERNAL SOURCES</b>	
Terminal Fan Coil Unit	Does not exist
Unit Heater/Cabinet Heater	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE CONTROL/SWITCH
Deficiency Location/Instance	4th floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Unit Heater/Cabinet Heater</b>	
Violations	No violations recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	12,996
Replacement Uom	MBH
<b>Boiler Auxiliaries</b>	Inspected
<b>Boiler Blowdown/Piping System</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Breeching</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Damper (In Breeching)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	Inspected
<b>Boiler Feedwater Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Tank</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Feedwater Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Gas Burner</b>	Does not exist
<b>Boiler Gas/Oil Burner</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Header Valve</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	Inspected
<b>Double Check Valves</b>	Does not exist
<b>RPZ</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Oil Burner</b>	Does not exist
<b>Boiler Room Steam And Condensate Piping</b>	Inspected
Condition	1- Good
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	under boiler #1
Deficiency Quantity	10
Quantity Uom	L.F.

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Room Steam And Condensate Piping</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Safety Valve</b>	
Inspected	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Burner Control Panel</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	flue smoke alarm is out
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler System</b>	
Inspected	Inspected
<b>Coal-fired Boiler</b>	
Does not exist	Does not exist
<b>Hot Water Boiler</b>	
Does not exist	Does not exist
<b>Modular Boiler</b>	
Does not exist	Does not exist
<b>Steam Boiler</b>	
Inspected	Inspected
Instance	Basement
Instance Condition	1- Good
Instance Quantity	6,498
Instance Quantity Uom	MBH
Manufacturer	A. L Eastmond
EquipmentId	7882-01
Capacity/Size	6498 MBH-Net
Installation Year	2001
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	1- Good
Instance Quantity	6,498
Instance Quantity Uom	MBH
Manufacturer	A L Eastmond
EquipmentId	7882-02
Capacity/Size	6498 MBH-Net
Installation Year	2001
Deficiency	No deficiencies recorded
<b>Fuel Systems</b>	
Inspected	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE ACTUATOR
Deficiency Location/Instance	Basement-1/2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CO/Gas Leak Detection</b>	
Inspected	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Fuel Systems</b>	
<b>CO/Gas Leak Detection</b>	
Deficiency	No deficiencies recorded
<b>Fuel Oil Heater</b>	
	Does not exist
<b>Fuel Oil Level Gauge</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Piping</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Fuel Oil Tank</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Fuel Transfer Pump</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Oil Leak Detector In Tank Room</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Overfill Alarm By Oil Fill</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
	Inspected
Instance	1st floor
<b>CO Detector</b>	
Instance on 1st floor	Does not exist
<b>CO/Gas Leak Detector</b>	
Instance on 1st floor	Does not exist
<b>Gas System</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on 1st floor	Does not exist
<b>Hood Exhaust Ductwork</b>	
Instance on 1st floor	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on 1st floor	Does not exist
<b>Hood Fire Suppression System</b>	
Instance on 1st floor	Does not exist
<b>Hot Water Temperature Booster</b>	
Instance on 1st floor	Does not exist
<b>Kitchen Sink</b>	
Instance on 1st floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K180**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Deluge Valve</b>	Does not exist
<b>Fire Booster Pump Assembly</b>	Does not exist
<b>Roof Tank</b>	Does not exist
<b>Siamese Connection</b>	Does not exist
<b>Sprinkler Alarm Valve Assembly</b>	Does not exist
<b>Sprinkler Head</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Does not exist
<b>Water Gong</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
<b>Duct- Register / Diffuser</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	5th floor gym
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	5th floor MER, 5th floor boys bath room, basement-3/10,
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	5th floor MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fire / Smoke Damper</b>	Does not exist
<b>Heating And Ventilating Unit</b>	Does not exist
<b>Metal Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Mechanical Inspection*

**K180**

Question	Response
<b>VENTILATION</b>	
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Thru out
Deficiency Quantity	85
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded