

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

School: **I.S. 35 - BROOKLYN, 272 MCDONOUGH STREET, BROOKLYN, NY, 11233**

InspectionId	Inspection Type	Time In	Last Edited
1196025	ELECTRICAL	2008-12-18 08:13AM	2009-01-13 03:02PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency and Exit Lights Years: 1996 and 2002 Systems: PA Tuner and Amplifiers Years: Approx. 1996 Systems: Intrusion Alarm Years: 1994 Systems: Fluorescent and HID Lighting Years: 1998 Systems: Most Outside Security Lights Years: 1999 Systems: LAN Years: 2003 Systems: PBX/ Intercom Years: 2007 Systems: Partial Motor Starters Years: 1998 and 2008 Systems: Partial Molded Case Panel Boards Years: 1998 Systems: Switchboard Years: 1996

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Water Penetration in to the Electrical room	Electrical Equipment	Electrical Room	Luis Seda - Fireman

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	Basement
House Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	NOT CONNECTED TO LOCAL SOUND SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Does not exist
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Replacement Quantity	3- Fair
Replacement Uom	113,000
Deficiency	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	
Instance	Inspected
Instance	Basement
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Does not exist
CAFETERIA/MULTIPURPOSE ROOM	
Instance on Basement	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Condition	Inspected
Lighting	
Condition	Inspected
Lighting Fixture - Fluorescent	
Condition	Inspected
Pendant Mounted	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Does not exist
Surface Mounted	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Condition	Does not exist
Lighting Fixture - Incandescent	
Condition	Inspected
Pendant Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	Inspected
Instance	Room 119
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Room 119	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 119	Inspected
Pendant Mounted	
Instance on Room 119	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 119	Does not exist
Surface Mounted	
Instance on Room 119	Does not exist
Lighting Fixture - HID	
Instance on Room 119	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 119	Does not exist
Raceway With Receptacles	
Instance on Room 119	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
Model	Gallagher
EquipmentId	Main Service Switch
Capacity/Size	2000 Amps
Installation Year	1966
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Room

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
ELECTRIC SERVICE SWITCH	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCH NAME PLATE IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	113,000
Replacement Uom	S.F.
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder Contactor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
FIRE ALARM SYSTEM	
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm Control Board
Capacity/Size	6 circuits
Installation Year	1966
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	5- Poor
Deficiency	REGISTER NOT OPERATIONAL
Deficiency Location/Instance	Custodians Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Capacity/Size	2 circuits
Installation Year	1966
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Punch Register Control Panel
Capacity/Size	2 circuits
Installation Year	1966
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance	Second Floor
Instance	Basement
Lighting	
Instance on Second Floor	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Second Floor	Inspected
Instance on Basement	Inspected
Pendant Mounted	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Recessed Mounted	
Instance on Second Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
Local Sound System	
Instance on Second Floor	Does not exist
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Scoreboard	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Second Floor	Does not exist
Instance on Basement	Does not exist
INTERCOM SYSTEM	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Surface Mounted	
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
KITCHEN/WARMING PANTRY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 328
Has LAN/Modem access	Yes
Instance	Room 112
Has LAN/Modem access	Yes
Lighting	
Instance on Room 328	Inspected
Instance on Room 112	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 328	Inspected
Instance on Room 112	Inspected
Pendant Mounted	
Instance on Room 328	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 328	Does not exist
Instance on Room 112	Does not exist
Surface Mounted	
Instance on Room 328	Does not exist
Instance on Room 112	Does not exist
Lighting Fixture - HID	
Instance on Room 328	Does not exist
Instance on Room 112	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 328	Does not exist
Instance on Room 112	Does not exist
Raceway With Receptacles	
Instance on Room 328	Does not exist
Instance on Room 112	Does not exist
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	15
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
LIGHTING - EXTERIOR SECURITY	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
LIGHTNING PROTECTION	
	Does not exist
LOCKER ROOM/SHOWER ROOM	
	Inspected
Instance	Second Floor Gym
Alternative Use	Yes
Instance	Basement Gym
Alternative Use	Yes
Lighting	
Instance on Second Floor Gym	Not required
Instance on Basement Gym	Not required
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Mechanical Rooms
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	
	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Mechanical Rooms
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	
	Does not exist
Fused Toggle Switch Type	
	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Corridors, Public Assembly Spaces and Mechanical Rooms
Deficiency Quantity	24
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	113,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors, Classrooms and Public Assembly Spaces
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	First Floor Corridor and Classrooms
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Inspected
Instance	Room 201
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Room 201	Does not exist
Emergency Shut-Off Power	
Instance on Room 201	Does not exist
Lighting	
Instance on Room 201	Not required
Power Supply	
Instance on Room 201	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
	Inspected
Replacement Quantity	113,000
Replacement Uom	S.F.
Intrusion Alarm	
	Inspected
Central Control Panel	
	Inspected
Instance	Custodians Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	VISTA 40

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
SECURITY	
Intrusion Alarm	
Central Control Panel	
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Condition	Does not exist
IPDVS/CCTV System	
Condition	Does not exist
SWIMMING POOL	
Condition	Does not exist
SWITCHBOARD	
Condition	Inspected
Air Circuit Breaker Type	
Condition	Does not exist
Fused Disconnect Switch Type	
Instance	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	N/A
Capacity/Size	500 Amps total, 1 section
Installation Year	1966
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	N/A
Capacity/Size	500 Amps total, 1 section
Installation Year	1966
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Power Panel PP-1
Capacity/Size	400 Amps total, 1 section
Installation Year	1966
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	MDP#1, MDP#2, MDP#3
Capacity/Size	2000 Amps total, 3 sections
Installation Year	1966
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K035

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Manufacturer	Cutler Hammer
EquipmentId	DP-EM
Capacity/Size	400 Amps total, 1 section
Installation Year	1996
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Does not exist
TELEPHONE	
	Inspected
PBX/Intercom	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
TRANSFORMER	
	Does not exist
TV SYSTEM	
	Inspected
Cable Service	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	
	Does not exist
Master Antenna System	
	Does not exist