

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

School: **I.S. 68 - BROOKLYN, 956 EAST 82 STREET, BROOKLYN, NY, 11236**

InspectionId	Inspection Type	Time In	Last Edited
1189133	MECHANICAL	2009-05-07 11:10AM	2009-05-26 04:42PM

***Asset Data***

Question	Answer
Heating Plant Oil Number	6
Have any Systems/Major Building Components been upgraded?	Systems: Rooftop / Packaged Units for Auditorium, Domestic water heat exchanger (instantaneous type) Years: 2000 Systems: Kitchen Fire Suppression System Years: 2007 Systems: Science Lab # 304 and Science Prep Room # 302 Years: 2005

***Priority Condition***

No condition recorded

***Inspection***

Question	Response
<b>MECHANICAL</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Piping</b>	Does not exist
<b>Condenser Water Pump</b>	Does not exist
<b>Cooling Coils in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>DX Split System</b>	Does not exist
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	Lower Roof
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	RTU-1 / RTU-2
Capacity/Size	25 Tons (each)
Installation Year	2000
Deficiency	No deficiencies recorded
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Does not exist
<b>Return Fan</b>	Does not exist
<b>Window Type A/C</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	2nd floor
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>Damper Actuator</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>CLIMATE CONTROL SYSTEM</b>	
<b>Damper Actuator</b>	
Deficiency Location/Instance	2nd floor fan room / Auditorium blower fresh air damper actuator
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>DDC Computer</b>	
	Does not exist
<b>Local Control Panel</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Pneumatic PRV Station</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Pneumatic Tubing</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Refrigerated Air Dryer</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Air Compressor</b>	
	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Temperature Control Thermostat</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Zone Valve</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Valve</b>	
	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 106 and Library
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>COMPACTOR</b>	
	Does not exist
<b>CONVEYING</b>	
	Inspected
<b>Dumbwaiters</b>	
	Does not exist
<b>Elevators</b>	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	FREIGHT:HYDRAULIC:OIL LEAK
Deficiency Location/Instance	Kitchen elevator machine room
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>CONVEYING</b>	
<b>Elevators</b>	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Escalators</b>	Does not exist
<b>Non-auditorium Handicap Lift</b>	Does not exist
<b>Sidewalk / Ash Hoist</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	HYDRAULIC:INOPERABLE
Deficiency Location/Instance	Room # B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
<b>Service Piping (Water Main)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Water Main - Double Check Valve</b>	Does not exist
<b>Water Main - RPZ</b>	Does not exist
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Circulating Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler room (2 of 3, piping connections and tube bundles of 2 heat exchangers permanently removed)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Does not exist
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>House Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Interior Floor Drain</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>Interior Floor Drain</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Interior Storm Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage / Waste Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan room B45
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Sump Pump</b>	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room and Room B17/19
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Vent Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	
	Does not exist
<b>EMERGENCY GENERATOR</b>	
	Does not exist
<b>FIXTURES</b>	
<b>Staff And Other</b>	
	Inspected
<b>Boiler Room - Eye Wash</b>	
	Does not exist
<b>Janitor Sink</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Student</b>	
	Inspected
<b>Drinking Fountain</b>	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Student</b>	
<b>Lavatory/Sink</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Inspected
Condition	3- Fair
Alternative Use	Yes
Deficiency	NOT IN USE
Deficiency Location/Instance	R160/ R146
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	CLOGGED/DIRTY/LEAKING
Deficiency Location/Instance	Various bathrooms
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not exist
<b>Gas Meter Room Vent</b>	Does not exist
<b>Gas Pressure Booster</b>	Does not exist
<b>HEATING</b>	Inspected
<b>Baseboard/Fin Tube</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heating Coils In Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	2nd floor fan room / Gym blower re-heat
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Hydronic Heating</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Radiator / Convect</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan room B45 and 2nd floor fan room
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Condensate Return System</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room and fan room B45 and room B17/19
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler room and fan room B45 and room B17/19
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Boiler room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Center of building rooms
Deficiency Quantity	20
Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>Terminal Unit Thermostatic Trap</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>STEAM SUPPLIED BY EXTERNAL SOURCES</b>	
<b>Terminal Fan Coil Unit</b>	Does not exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Rooms B2/B4/B6/B8/B12 (Basement shops)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>HEATING PLANT</b>	
Replacement Quantity	20,637
Replacement Uom	MBH
<b>Boiler Auxiliaries</b>	Inspected
<b>Boiler Blowdown/Piping System</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Breeching</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Damper (In Breeching)</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
<b>Boiler Feedwater Pump</b>	
Does not exist	
<b>Boiler Feedwater Tank</b>	
Does not exist	
<b>Feedwater Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	
Does not exist	
<b>Boiler Gas Burner</b>	
Does not exist	
<b>Boiler Gas/Oil Burner</b>	
Does not exist	
<b>Boiler Header Valve</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Does not exist	
<b>Boiler Make-up Water Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Oil Burner</b>	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Oil Burner</b>	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler room at boiler #3 (built-in oil heater)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Room Steam And Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Safety Valve</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Burner Control Panel</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler System</b>	Inspected
<b>Coal-fired Boiler</b>	Does not exist
<b>Hot Water Boiler</b>	Does not exist
<b>Modular Boiler</b>	Does not exist
<b>Steam Boiler</b>	Inspected
Instance	Basement Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,879
Instance Quantity Uom	MBH
Manufacturer	Burnham
EquipmentId	50863-1
Capacity/Size	8860 MBH Gross
Installation Year	1963
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement Boiler Room/ Boiler # 50863-1 (Tubes and staybolts recently replaced, insulation waiting to be installed)
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Steam Boiler</b>	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,879
Instance Quantity Uom	MBH
Manufacturer	Burnham
EquipmentId	50863-3
Capacity/Size	8860 MBH Gross
Installation Year	1963
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement Boiler Room / Boiler # 50863-3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	6,879
Instance Quantity Uom	MBH
Manufacturer	Burnham
EquipmentId	50863-2
Capacity/Size	8860 MBH Gross
Installation Year	1963
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement Boiler Room / Boiler # 50863-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED INSULATION
Deficiency Location/Instance	Basement Boiler Room / Boiler # 50863-2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Location/Instance	Basement Boiler Room / Boiler # 50863-2
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fuel Systems</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Fuel Systems</b>	
<b>Boiler Fresh Air Louver/Damper</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CO/Gas Leak Detection</b>	Does not exist
<b>Fuel Oil Heater</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room B31 (steam type heater and 2 electric, 3 of 6)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fuel Oil Level Gauge</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Tank</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Transfer Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	Does not exist
<b>Oil Leak Detector In Tank Room</b>	Does not exist
<b>Overfill Alarm By Oil Fill</b>	Does not exist
<b>KITCHEN</b>	Inspected
Instance	Basement
<b>CO Detector</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO/Gas Leak Detector</b>	
Instance on Basement	Does not exist
<b>Gas System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair

NYC Department of Education  
 Building Condition Assessment Survey 2008-2009

*Mechanical Inspection*

K068

Question	Response
<b>KITCHEN</b>	
<b>Hood Exhaust Ductwork</b>	
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on Basement	Inspected
Instance	Kitchen
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ansul
EquipmentId	N/A
Capacity/Size	4 Gallons
Installation Year	2007
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Kitchen Sink</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
Instance	Inspected
Instance	Room 201
Alternative Use	No
Instance	Rooms 104/204/301
Alternative Use	Yes
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room 201	Does not exist
Instance on Rooms 104/204/301	Does not exist
<b>Emergency Shower</b>	
Instance on Room 201	Does not exist
Instance on Rooms 104/204/301	Does not exist
<b>Eye Wash</b>	
Instance on Room 201	Does not exist
Instance on Rooms 104/204/301	Does not exist
<b>Laboratory Hood</b>	
Instance on Room 201	Does not exist
Instance on Rooms 104/204/301	Does not exist
<b>Laboratory Sink</b>	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 104/204/301	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Laboratory Sink</b>	
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Rooms 104/204/301 (1 each)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>SCIENCE LAB</b>	
	Inspected
Instance	Room 101
Alternative Use	No
Instance	Room 304
Alternative Use	No
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Does not exist
<b>CO/Gas Leak Detector</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Does not exist
<b>Emergency Shower</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Does not exist
<b>Eye Wash</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Does not exist
<b>Laboratory Hood</b>	
Instance on Room 101	Does not exist
Instance on Room 304	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	
Instance on Room 101	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 304	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	
Instance on Room 101	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Mechanical Inspection*

K068

Question	Response
<b>SCIENCE LAB</b>	
<b>Make-up Air Unit</b>	
Instance on Room 304	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance	Inspected
Alternative Use	Room 302
	No
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Emergency Shower</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Eye Wash</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Laboratory Hood</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	
Instance on Room 302	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>Deluge Valve</b>	Does not exist
<b>Fire Booster Pump Assembly</b>	Does not exist
<b>Roof Tank</b>	Does not exist
<b>Siamese Connection</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**K068**

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
Standpipe System	Does not exist
Water Gong	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
<b>Duct- Register / Diffuser</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fire / Smoke Damper</b>	Does not exist
<b>Heating And Ventilating Unit</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan room B45 (1/1) serving B56A/B56B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Metal Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Unit Ventilator</b>	Does not exist