

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

School: **I.S. 171 - BROOKLYN, 528 RIDGEWOOD AVENUE, BROOKLYN, NY, 11208**

InspectionId	Inspection Type	Time In	Last Edited
1294080	ELECTRICAL	2009-03-20 08:18AM	2009-03-26 11:51AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: CCTV Years: 2006 Systems: Exterior lights Years: 2006-07 Systems: Telephone /PBX / Intercom / LAN system Years: 2002-03 Systems: Interior lighting Years: 2000-01 Systems: Intrusion Alarm Years: 2000-01 Systems: Emergency /Exit lights Years: 1998-2000

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Replacement Quantity	86,000
Replacement Uom	S.F.
Deficiency	BELL NOT OPERATIONAL
Deficiency Location/Instance	West side Multipurpose room, 4th and 2nd Floor corridor
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BELL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Does not exist
CAFETERIA/MULTIPURPOSE ROOM	Inspected
Instance	Ground Floor (East)
Instance	Ground Floor (West)
Lighting	
Instance on Ground Floor (East)	Inspected
Instance on Ground Floor (West)	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor (East)	Inspected
Instance on Ground Floor (West)	Inspected
Pendant Mounted	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
Recessed Mounted	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
Surface Mounted	
Instance on Ground Floor (East)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
CAFETERIA/MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Ground Floor (West)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
Local Sound System	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
Theater Lighting System	
Instance on Ground Floor (East)	Does not exist
Instance on Ground Floor (West)	Does not exist
CITY FIRE ALARM SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Inspected
Pendant Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	Inspected
Instance	Room # 312
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Room # 312	Inspected
Lighting Fixture - Fluorescent	
Instance on Room # 312	Inspected
Pendant Mounted	
Instance on Room # 312	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room # 312	Does not exist
Surface Mounted	
Instance on Room # 312	Does not exist
Lighting Fixture - HID	
Instance on Room # 312	Does not exist
Lighting Fixture - Incandescent	
Instance on Room # 312	Does not exist
Raceway With Receptacles	
Instance on Room # 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical meter room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
Model	Federal Pacific
EquipmentId	Main Disc. SW,
Capacity/Size	1600 Amps
Installation Year	1972
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE POORLY MOUNTED
Deficiency Location/Instance	Stair D,4 th Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	86,000
Replacement Uom	S.F.
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Bell At Panel	
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler room/ Basement
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	NO ID
Capacity/Size	9 circuits
Installation Year	1970
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	5- Poor
Deficiency	REGISTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler room
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	"Edwards"
Model	5712B
EquipmentId	Fire Alarm Control for sprinkler
Capacity/Size	4 circuits
Installation Year	1990
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Register Control Board
Capacity/Size	2 circuits
Installation Year	1970
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Does not exist
KITCHEN/WARMING PANTRY	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
LIBRARY	
Instance	Room # 309
Has LAN/Modem access	Yes
Lighting	
Instance on Room # 309	Inspected
Lighting Fixture - Fluorescent	
Instance on Room # 309	Inspected
Pendant Mounted	
Instance on Room # 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room # 309	Does not exist
Surface Mounted	
Instance on Room # 309	Does not exist
Lighting Fixture - HID	
Instance on Room # 309	Does not exist
Lighting Fixture - Incandescent	
Instance on Room # 309	Does not exist
Raceway With Receptacles	
Instance on Room # 309	Does not exist
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	4
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE LENS/PROTECTIVE GUARD MISSING
Deficiency Location/Instance	Nichols ave entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS/PROTECTIVE GUARD
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room, Fan room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Inspected
Instance	Ground Floor
Lighting	
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist
Recessed Mounted	
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on Ground Floor	Inspected
Instance Condition	5- Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on Ground Floor	Inspected
Dimming System	
Instance on Ground Floor	Does not exist
Theater Lighting	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Corridors, Kitchen, Basement, Boiler room
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors 1st, 2nd,3rd and 4th Floor
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	86,000
Replacement Uom	S.F.
Instance	General office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane
Deficiency	AMPLIFIER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	General office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	General office

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors, offices, classrooms
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Room 403 and Room 407
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Inspected
Instance	Room # 403 Room # 406 Room # 407
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Room # 403 Room # 406 Room # 407	Does not exist
Emergency Shut-Off Power	
Instance on Room # 403 Room # 406 Room # 407	Does not exist
Lighting	
Instance on Room # 403 Room # 406 Room # 407	Not required
Power Supply	
Instance on Room # 403 Room # 406 Room # 407	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Replacement Quantity	86,000
Replacement Uom	S.F.
Intrusion Alarm	Inspected
Central Control Panel	Inspected
Instance	Custodian office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K171

Question	Response
SECURITY	
Intrusion Alarm	
Central Control Panel	
Model	Ademco/Vista 128B
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	SENSOR NOT OPERATIONAL
Deficiency Quantity	Multipurpose room(east- west), Computer Room #312
Quantity Uom	3
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 4
Violations	LEVEL 3
	No violations recorded
Panic Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Remote Annunciator	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	CAMERA NOT OPERATIONAL
Deficiency Quantity	Building entrance
Quantity Uom	2
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 4
Violations	LEVEL 3
	No violations recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
Instance	Inspected
Instance Condition	Electrical meter room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Federal Pacific
Capacity/Size	No ID
Installation Year	1600 Amps total, 2 sections
Deficiency	1972
Deficiency Quantity	SWITCHBOARD ID IS MISSING
Quantity Uom	1
Potential Action	EACH
Urgency of Action	MAINTENANCE
Purpose of Action	PRIORITY 2
Violations	LEVEL 2
	No violations recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K171

Question	Response
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Does not exist