

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

School: **P.S. 206 - BROOKLYN, 2200 GRAVESEND NECK RD., BROOKLYN, NY, 11229**

InspectionId	Inspection Type	Time In	Last Edited
1198091	MECHANICAL	2009-04-01 08:22AM	2009-04-29 01:41PM

Asset Data

Question	Answer
Heating Plant Oil Number	2
Have any Systems/Major Building Components been upgraded?	Systems: Heating plant, climate Control Years: 1998

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Piping	Does not exist
Condenser Water Pump	Does not exist
Cooling Coils in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Does not exist
Window Type A/C	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
Damper Actuator	Does not exist
DDC Computer	Does not exist
Local Control Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pneumatic PRV Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pneumatic Tubing	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Refrigerated Air Dryer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Temperature Control Air Compressor	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room (1 of 2 motor is defective)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Temperature Control Thermostat	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
CLIMATE CONTROL SYSTEM	
Temperature Control Thermostat	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Temperature Control Zone Valve	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Valve	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiters	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	1st-5th Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	SECURE OFF
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 1
Violations	No violations recorded
Elevators	Does not exist
Escalators	Does not exist
Non-auditorium Handicap Lift	Does not exist
Sidewalk / Ash Hoist	Inspected
Condition	3- Fair
Deficiency	TRACTION:NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Inspected
Roof Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Roof Penthouse
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REMOVE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 1
Violations	No violations recorded
Supply Pump	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Pressure Booster Pump	Inspected

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Mechanical Inspection

K206

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Hydraulic/Pneumatic Booster System	
Pressure Booster Pump	
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Water Pressure Booster - Compressor	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Water Service	Inspected
Service Piping (Water Main)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Main - Double Check Valve	Does not exist
Water Main - RPZ	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Circulating Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI.
EquipmentId	N/A
Capacity/Size	400 MBH/300 Gallons
Installation Year	1998
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	3,000
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
House Trap	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Interior Floor Drain	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Interior Storm Piping	
Condition	Inspected
Deficiency	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	1,250
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage / Waste Piping	
Condition	Inspected
Deficiency	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	850
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	
Condition	Does not exist
Sump Pump	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Vent Piping	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
Condition	Does not exist
EMERGENCY GENERATOR	
Condition	Does not exist
FIXTURES	
Staff And Other	
Condition	Inspected
Boiler Room - Eye Wash	
Condition	Does not exist
Janitor Sink	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	Inspected
Deficiency	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Rooms 256 and 354
Deficiency Quantity	4
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
FIXTURES	
Staff And Other	
Toilet	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room 311 (Abandoned hand Sink in old Art Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REMOVE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 1
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Rooms 108, 109, 201,202,203, 204,259, 260, 355, 456 and 459
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Rooms 109, 355 and 459
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	
Gas Distribution Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
GAS SERVICE	
Gas Meter Room Vent	
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
HEATING	
Baseboard/Fin Tube	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heating Coils In Ductwork	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement Fan Area
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydronic Heating	Does not exist
Radiator / Convectector	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	160
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement Fan Area
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement Fan Area
Deficiency Quantity	250
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	1,700
Quantity Uom	L.F.

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
HEATING	
Steam Heating	
Steam Condensate Return Piping	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LEAKS
Deficiency Location/Instance	Boy's Room 459
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return System	
Inspected	
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	
Inspected	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	1,700
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	
Inspected	
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 514 and Hallway across room 551
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
STEAM SUPPLIED BY EXTERNAL SOURCES	
Does not exist	
Terminal Fan Coil Unit	
Does not exist	
Unit Heater/Cabinet Heater	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
HEATING PLANT	
Inspected	
Replacement Quantity	12,996
Replacement Uom	MBH
Boiler Auxiliaries	
Inspected	
Boiler Blowdown/Piping System	
Inspected	
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Blowdown/Piping System	
Deficiency	No deficiencies recorded
Boiler Breeching	
Condition	Inspected
Deficiency	2- Between Good and Fair
Boiler Damper (In Breeching)	
Condition	Inspected
Deficiency	2- Between Good and Fair
Boiler Emergency Stop Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
Boiler Feedwater System	
Boiler Feedwater Pump	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Location/Instance	DEFECTIVE PUMP
Deficiency Quantity	Boiler Room
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Boiler Feedwater Tank	
Condition	Inspected
Deficiency	2- Between Good and Fair
Feedwater Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
Boiler Feedwater Treatment(Automatic)	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DEFECTIVE
Deficiency Quantity	Boiler Room (Does not operate on Auto)
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Boiler Gas Burner	
Condition	No violations recorded
Boiler Gas/Oil Burner	
Condition	Does not exist
Deficiency	Inspected
Deficiency	2- Between Good and Fair
Boiler Header Valve	
Condition	Inspected
Deficiency	2- Between Good and Fair
Boiler Make-up Water Backflow Preventer	
Double Check Valves	
Condition	Inspected
RPZ	
Condition	Does not exist
Deficiency	Inspected
Deficiency	2- Between Good and Fair
Boiler Make-up Water Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Oil Burner	Does not exist
Boiler Room Steam And Condensate Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Burner Control Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler System	Inspected
Coal-fired Boiler	Does not exist
Hot Water Boiler	Does not exist
Modular Boiler	Does not exist
Steam Boiler	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH
Manufacturer	Easco
EquipmentId	7906-01
Capacity/Size	6498 MBH Net
Installation Year	1998
Deficiency	PLUGGED TUBES
Deficiency Location/Instance	Boiler Room/ Boiler #1
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH
Manufacturer	Easco
EquipmentId	7906-02
Capacity/Size	6498 MBH Net
Installation Year	1998
Deficiency	PLUGGED TUBES
Deficiency Location/Instance	Boiler Room/ Boiler #2
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Systems	Inspected
Boiler Fresh Air Louver/Damper	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
HEATING PLANT	
Fuel Systems	
CO/Gas Leak Detection	
Deficiency	No deficiencies recorded
Fuel Oil Heater	
	Does not exist
Fuel Oil Level Gauge	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fuel Oil Piping	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fuel Oil Tank	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fuel Transfer Pump	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Oil Leak Detector In Tank Room	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Overfill Alarm By Oil Fill	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	
	Inspected
Instance	1st Floor
CO Detector	
Instance on 1st Floor	Does not exist
CO/Gas Leak Detector	
Instance on 1st Floor	Does not exist
Gas System	
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Kitchen (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
KITCHEN	
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	3rd Floor Setback
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Inspected
Instance	Room 507
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 507	Does not exist
CO Detector	
Instance on Room 507	Does not exist
CO/Gas Leak Detector	
Instance on Room 507	Does not exist
Emergency Shower	
Instance on Room 507	Does not exist
Eye Wash	
Instance on Room 507	Does not exist
Hood Exhaust Ductwork	
Instance on Room 507	Does not exist
Hood Exhaust Fan	
Instance on Room 507	Does not exist
Laboratory Hood	
Instance on Room 507	Does not exist
Laboratory Sink	
Instance on Room 507	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 507	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
	Inspected
Deluge Valve	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Alarm Valve Assembly	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K206

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Duct- Register / Diffuser	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire / Smoke Damper	Does not exist
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	Basement Fan Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE CONTROL/SWITCH
Deficiency Location/Instance	Library and classrooms
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Classrooms
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Mechanical Inspection

K206

Question

Response

VENTILATION

Unit Ventilator

Violations

No violations recorded