

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

School: **I.S. 265 - BROOKLYN, 101 PARK AVENUE, BROOKLYN, NY, 11205**

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 1196044 | ELECTRICAL | 2009-01-21 08:13AM | 2009-04-23 03:18PM |

Asset Data

| Question | Answer |
|---|--|
| Have any Systems/Major Building Components been upgraded? | Systems: Partial Emergency and Exit Lights Years: 2003 Systems: PA and Local Sound Systems Years: Approx. 1990 Systems: Intrusion Alarm Years: 2002 Systems: Fluorescent Lighting in Bathrooms, Locker Rooms and Partial Stairwells Years: 2002 Systems: Most Outside Security Lights Years: 1998 Systems: LAN and PBX/ Intercom Years: 2002 Systems: Motor Starters Years: 1978 Systems: Gym Scoreboards Years: 2000 Systems: HID Lighting in Gym Years: 2008 Systems: Switchboard Years: 1996 |

Priority Condition

| Condition Description | Component Affected | Location Description | Person(s) Notified |
|-----------------------|--------------------|----------------------|--------------------------|
| Not Operational | PA System | Most of Building | Paula Holmes - Principal |

Inspection

| Question | Response |
|--|---|
| ELECTRICAL | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Inspected |
| Instance | First Floor |
| House Lighting | |
| Instance on First Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on First Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on First Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on First Floor | Inspected |
| Pendant Mounted | |
| Instance on First Floor | Does not exist |
| Recessed Mounted | |
| Instance on First Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 49 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| AUDITORIUM | |
| House Lighting | |
| Lighting Fixture - Incandescent | |
| Recessed Mounted | |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW LAMP |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| Instance on First Floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW LAMP |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Local Sound System | |
| Instance on First Floor | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | MICROPHONE NOT OPERATIONAL |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Projection System | |
| Instance on First Floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | NOT CONNECTED TO LOCAL SOUND SYSTEM |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL CONNECTION |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| AUDITORIUM | |
| Theater Lighting System | |
| Instance on First Floor | Inspected |
| Dimming System | |
| Instance on First Floor | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | LIGHT CONSOLE NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Theater Lighting | |
| Instance on First Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 125 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| AUXILIARY SIGNAL/BELL SYSTEM | |
| Condition | 3- Fair |
| Replacement Quantity | 139,000 |
| Replacement Uom | S.F. |
| Deficiency | INDICATOR PANEL NOT OPERATIONAL |
| Deficiency Location/Instance | Custodians Office and Boiler Room |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| CAFETERIA | |
| Instance | Inspected |
| Instance | Basement - Students |
| Instance | Basement Room B39 - Teachers |
| Lighting | |
| Instance on Basement - Students | Inspected |
| Instance on Basement Room B39 - Teachers | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement - Students | Inspected |
| Instance on Basement Room B39 - Teachers | Inspected |
| Pendant Mounted | |
| Instance on Basement - Students | Does not exist |
| Instance on Basement Room B39 - Teachers | Does not exist |
| Recessed Mounted | |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on Basement - Students | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 69 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Basement Room B39 - Teachers | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement - Students | Does not exist |
| Instance on Basement Room B39 - Teachers | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement - Students | Does not exist |
| Instance on Basement Room B39 - Teachers | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement - Students | Does not exist |
| Instance on Basement Room B39 - Teachers | Does not exist |
| Local Sound System | |
| Instance on Basement - Students | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Basement Room B39 - Teachers | Does not exist |
| CAFETERIA/MULTIPURPOSE ROOM | Does not exist |
| CITY FIRE ALARM SYSTEM | Inspected |
| Condition | 5- Poor |
| Deficiency | NOT OPERATIONAL |
| Deficiency Location/Instance | First Floor Corridor |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 850 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| Condition | Inspected |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 240 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lighting Fixture - HID | |
| Does not exist | |
| Lighting Fixture - Incandescent | |
| Inspected | |
| Pendant Mounted | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 40 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| COMPUTER LAB | |
| Inspected | |
| Instance | Room B2 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| COMPUTER LAB | |
| Has LAN/Modem access | Yes |
| Power Panel? | Yes |
| Lighting | |
| Instance on Room B2 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room B2 | Inspected |
| Pendant Mounted | |
| Instance on Room B2 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 24 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Instance on Room B2 | Does not exist |
| Surface Mounted | |
| Instance on Room B2 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room B2 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room B2 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room B2 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| ELECTRIC SERVICE SWITCH | |
| Instance | Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | N/A |
| Model | N/A |
| EquipmentId | Main Service Switch A |
| Capacity/Size | N/A |
| Installation Year | 1957 |
| Deficiency | SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | SWITCH NAME PLATE IS MISSING |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| ELECTRIC SERVICE SWITCH | |
| Instance | Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | N/A |
| Model | N/A |
| EquipmentId | Main Service Switch B |
| Capacity/Size | N/A |
| Installation Year | 1957 |
| Deficiency | SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | SWITCH NAME PLATE IS MISSING |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Basement and First Floors |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Connected To Emergency Generator System | Does not exist |
| Connected To Emergency Light/Exit Light Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Relay Test Switch | Inspected |
| Condition | 4- Between Fair and Poor |
| Deficiency | NOT OPERATIONAL |
| Deficiency Location/Instance | Boys and Girls Locker Rooms |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|--|
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Connected To Emergency Generator System | Does not exist |
| Connected To Emergency Light/Exit Light Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 139,000 |
| Replacement Uom | S.F. |
| Area Smoke Detector | Does not exist |
| Bell/Horn | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Does not exist |
| Elevator Recall | Does not exist |
| Fan Shutdown Control | Does not exist |
| Fire Alarm Digital Communicator | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Heat Detector | Does not exist |
| Magnetic Door Holder Contactor | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Does not exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | ACME |
| EquipmentId | Fire Alarm |
| Capacity/Size | 11 circuits |
| Installation Year | 1957 |
| Deficiency | PANEL BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Manual Pull Station | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Does not exist |
| Printer | Does not exist |
| Punch Register | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|--|
| FIRE ALARM SYSTEM | |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Does not exist |
| Sub-Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Does not exist |
| Fire Alarm Control Panel (Standard) | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | ACME |
| EquipmentId | Register Control Board |
| Capacity/Size | 3 circuits |
| Installation Year | 1957 |
| Deficiency | PANEL BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | ACME |
| EquipmentId | Sprinkler Alarm |
| Capacity/Size | 2 circuits |
| Installation Year | 1957 |
| Deficiency | PANEL BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Inspected |
| Instance | First Floor |
| Lighting | |
| Instance on First Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on First Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on First Floor | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K265

| Question | Response |
|--|---|
| GYMNASIUM | |
| Lighting | |
| Lighting Fixture - HID | |
| Pendant Mounted | |
| Instance on First Floor | Does not exist |
| Recessed Mounted | |
| Instance on First Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on First Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on First Floor | Inspected |
| Pendant Mounted | |
| Instance on First Floor | Does not exist |
| Recessed Mounted | |
| Instance on First Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 15 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| Instance on First Floor | Does not exist |
| Local Sound System | |
| Instance on First Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Scoreboard | |
| Instance on First Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on First Floor | Does not exist |
| INTERCOM SYSTEM | |
| | Does not exist |
| KITCHEN/WARMING PANTRY | |
| | Inspected |
| Lighting | |
| | Inspected |
| Lighting Fixture - Fluorescent | |
| | Inspected |
| Pendant Mounted | |
| | Does not exist |
| Recessed Mounted | |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 25 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| | Does not exist |
| Lighting Fixture - HID | |
| | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|---|---|
| KITCHEN/WARMING PANTRY | |
| Lighting | |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Does not exist |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 23 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | Does not exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIBRARY | Inspected |
| Instance | Room 225 |
| Has LAN/Modem access | Yes |
| Lighting | |
| Instance on Room 225 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 225 | Inspected |
| Pendant Mounted | |
| Instance on Room 225 | Does not exist |
| Recessed Mounted | |
| Instance on Room 225 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 15 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | |
| Instance on Room 225 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 225 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 225 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 225 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| LIGHTING - EXTERIOR SECURITY | Inspected |
| Condition | 3- Fair |
| Replacement Quantity | 25 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|--|
| LIGHTING - EXTERIOR SECURITY | |
| Replacement Uom | EACH |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not exist |
| LOCKER ROOM/SHOWER ROOM | Inspected |
| Instance | Basement - Boys |
| Alternative Use | No |
| Instance | Basement - Girls |
| Alternative Use | No |
| Lighting | |
| Instance on Basement - Boys | Inspected |
| Instance on Basement - Girls | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement - Boys | Inspected |
| Instance on Basement - Girls | Inspected |
| Pendant Mounted | |
| Instance on Basement - Boys | Does not exist |
| Instance on Basement - Girls | Does not exist |
| Recessed Mounted | |
| Instance on Basement - Boys | Does not exist |
| Instance on Basement - Girls | Does not exist |
| Surface Mounted | |
| Instance on Basement - Boys | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Basement - Girls | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Basement - Boys | Does not exist |
| Instance on Basement - Girls | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement - Boys | Does not exist |
| Instance on Basement - Girls | Does not exist |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 4- Between Fair and Poor |
| Deficiency | MOTOR STARTER NOT OPERATIONAL |
| Deficiency Location/Instance | Second Floor Fan Room H2 , H7 , H8 and Boiler Room Vacuum Pump and Air Compressor |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| MULTIPURPOSE ROOM | Does not exist |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Does not exist |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 2 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|---|--|
| PANEL BOARD | |
| Fused Toggle Switch Type | |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Molded Case Circuit Breaker Type | |
| Condition | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Corridors, Mechanical and Public Assembly Spaces |
| Deficiency Quantity | 23 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| Replacement Quantity | Inspected |
| Replacement Uom | 139,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 5- Poor |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Dukane 250 |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Location/Instance | General Office |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Deficiency | MASTER CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | General Office |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SCIENCE DEMO ROOM | |
| Instance | Inspected |
| Instance | Rooms 202 and 208 |
| Has LAN/Modem access | Yes |
| Power Panel? | No |
| Alternative Use | No |
| Instance | Room 317, 319 |
| Has LAN/Modem access | Yes |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance | Room 210 |
| Has LAN/Modem access | Yes |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance | Rooms 204, 104 and 108 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|---------------------------------------|---|
| SCIENCE DEMO ROOM | |
| Has LAN/Modem access | Yes |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance | Room 205 |
| Has LAN/Modem access | Yes |
| Power Panel? | Yes |
| Alternative Use | Yes |
| Emergency Gas Shut-Off Valve | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 204, 104 and 108 | Does not exist |
| Instance on Room 205 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | NOT IN USE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | NO ACTION |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 1 |
| Violations | No violations recorded |
| Emergency Shut-Off Power | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Instance on Rooms 204, 104 and 108 | Does not exist |
| Instance on Room 205 | Does not exist |
| Lighting | |
| Instance on Rooms 202 and 208 | Inspected |
| Instance on Room 317, 319 | Inspected |
| Instance on Room 210 | Inspected |
| Instance on Rooms 204, 104 and 108 | Not required |
| Instance on Room 205 | Not required |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 202 and 208 | Inspected |
| Instance on Room 317, 319 | Inspected |
| Instance on Room 210 | Inspected |
| Pendant Mounted | |
| Instance on Rooms 202 and 208 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 54 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 317, 319 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Deficiency Quantity | 36 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 210 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 18 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Surface Mounted | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Power Supply | |
| Instance on Rooms 202 and 208 | Does not exist |
| Instance on Room 317, 319 | Does not exist |
| Instance on Room 210 | Does not exist |
| Instance on Rooms 204, 104 and 108 | Does not exist |
| Instance on Room 205 | Does not exist |
| SCIENCE LAB | Does not exist |
| SCIENCE PREP ROOM | Inspected |
| Instance | Rooms 106 and 206 |
| Has LAN/Modem access | Yes |
| Power Panel? | No |
| Alternative Use | Yes |
| Emergency Gas Shut-Off Valve | |
| Instance on Rooms 106 and 206 | Does not exist |
| Emergency Shut-Off Power | |
| Instance on Rooms 106 and 206 | Does not exist |
| Lighting | |
| Instance on Rooms 106 and 206 | Not required |
| Power Supply | |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|---|---------------------------|
| SCIENCE PREP ROOM | |
| Power Supply | |
| Instance on Rooms 106 and 206 | Does not exist |
| SECURITY | |
| Replacement Quantity | 139,000 |
| Replacement Uom | S.F. |
| Intrusion Alarm | |
| Central Control Panel | |
| Instance | Inspected |
| Instance Condition | Electrical Room |
| Instance Quantity | 2- Between Good and Fair |
| Instance Quantity Uom | 1 |
| Model | EACH |
| Deficiency | VISTA 128B |
| | No deficiencies recorded |
| Infrared Sensor | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| | No deficiencies recorded |
| Panic Switch | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| | No deficiencies recorded |
| Remote Annunciator | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| | No deficiencies recorded |
| Siren/Strobe | |
| Condition | Inspected |
| Deficiency | 2- Between Good and Fair |
| | No deficiencies recorded |
| Ultrasonic Sensor | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| Deficiency Location/Instance | SENSOR NOT IN USE |
| Deficiency Quantity | Kitchen Office |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | NO ACTION |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 1 |
| | No violations recorded |
| IPDVS/CCTV System | |
| | Does not exist |
| SWIMMING POOL | |
| | Does not exist |
| SWITCHBOARD | |
| Air Circuit Breaker Type | Inspected |
| Fused Disconnect Switch Type | Does not exist |
| Instance | Inspected |
| Instance Condition | Electrical Room |
| Instance Quantity | 3- Fair |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | General Electric |
| Capacity/Size | DPEM IS265 |
| Installation Year | 400 Amps total, 1 section |
| Deficiency | 1996 |
| | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Instance | Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|---|--|
| SWITCHBOARD | |
| Molded Case Circuit Breaker Type | |
| Instance Quantity Uom | EACH |
| Manufacturer | N/A |
| EquipmentId | Main Switchboard A |
| Capacity/Size | N/A, 2 sections |
| Installation Year | 1957 |
| Deficiency | SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | SWITCHBOARD NAME PLATE IS MISSING |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | N/A |
| EquipmentId | Main Switchboard B |
| Capacity/Size | N/A, 2 sections |
| Installation Year | 1957 |
| Deficiency | SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | SWITCHBOARD NAME PLATE IS MISSING |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| TELEPHONE | Inspected |
| PBX/Intercom | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K265

| Question | Response |
|--|---|
| TOILET ROOM - STAFF | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not exist |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Does not exist |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| TRANSFORMER | Does not exist |
| TV SYSTEM | Inspected |
| Cable Service | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack | Does not exist |
| Master Antenna System | Inspected |
| Condition | 3- Fair |
| Deficiency | ANTENNA NOT IN USE |
| Deficiency Location/Instance | Roof |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | NO ACTION |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 1 |
| Violations | No violations recorded |