

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

**School: P.S. 307 - BROOKLYN, 209 YORK STREET, BROOKLYN, NY, 11201**

InspectionId	Inspection Type	Time In	Last Edited
2230025	MECHANICAL	2010-10-29 08:00AM	2010-11-03 03:31PM

***Asset Data***

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Electric domestic water heater , Exhaust fans & Safety valves for Boiler #1. Years: 2007 Systems: Sump pumps & DX split system for MDF room Years: 2005 Systems: Science lab room # 347 Years: 2010
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0

***Priority Condition***

No condition recorded

***Inspection***

Question	Response
<b>MECHANICAL</b>	
<b>AIR CONDITIONING</b>	Does not exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>DDC SYSTEM</b>	Does not exist
<b>ELECTRIC SYSTEM</b>	Does not exist
<b>HYBRID SYSTEM</b>	Does not exist
<b>PNEUMATIC SYSTEM</b>	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Inspected
<b>ASH HOIST</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Basement area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>DUMBWAITERS</b>	Does not exist
<b>ELEVATORS</b>	Does not exist
<b>ESCALATORS</b>	Does not exist
<b>Non-auditorium Handicap Lift - Stair</b>	Does not exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Does not exist
<b>SIDEWALK ELEVATOR</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>DOMESTIC COLD WATER SYSTEM</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>DOMESTIC COLD WATER SYSTEM</b>	
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
<b>Service Piping (Water Main)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Main - Double Check Valve</b>	Does not exist
<b>Water Main - RPZ</b>	Does not exist
<b>DOMESTIC HOT WATER SYSTEM</b>	Inspected
<b>Domestic Hot Water Circulating Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE TEMPERATURE REGULATOR
Deficiency Location/Instance	Basement boiler room - leaks
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Electric Domestic Water Heater</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Fired Domestic Water Heater</b>	Does not exist
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>DOMESTIC WATER DISTRIBUTION PIPING</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>HOUSE TRAP</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>INTERIOR FLOOR DRAIN</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>INTERIOR STORM PIPING</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SEWAGE / WASTE PIPING</b>	Inspected
Condition	3- Fair
Deficiency	CLOGGED
Deficiency Location/Instance	Cafeteria from drinking fountain
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SEWAGE EJECTOR PUMP</b>	Does not exist
<b>SUMP PUMP</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>SUMP PUMP</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>VENT PIPING</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>FIXTURES</b>	Inspected
<b>STAFF AND OTHER</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Staff woman's room 219
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>STUDENT</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Gym
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Inaccessible
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	1st & 2nd floors - mixing valves
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>STUDENT</b>	
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boy's bath room #238
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>CO/GAS LEAK DETECTION</b>	Does not exist
<b>GAS DISTRIBUTION PIPING</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS METER ROOM EXHAUST FAN</b>	Does not exist
<b>GAS METER ROOM VENT</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS PRESSURE BOOSTER</b>	Does not exist
<b>HEATING</b>	Inspected
<b>BASEBOARD/FIN TUBE</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HEATING COILS IN DUCTWORK</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HYDRONIC HEATING</b>	Does not exist
<b>RADIATOR / CONVECTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>STEAM HEATING</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan room 221
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Condensate Return Pumping System</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>STEAM HEATING</b>	
<b>Steam Condensate Return Pumping System</b>	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement boiler room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Basement boiler room 1 of 2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TANK
Deficiency Location/Instance	Basement boiler room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Various Locations
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>STEAM SUPPLIED BY EXTERNAL SOURCES</b>	Does not exist
<b>UNIT HEATER/CABINET HEATER</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Rooms 130 , 132 , 134 , 136
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	9,440
Replacement Uom	MBH
Instance	Basement
Burner Type	Oil

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
Heating Plant Oil Number	4
<b>BOILER AUXILIARIES</b>	
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Does not exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Does not exist
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Does not exist
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Safety Valve</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>BOILER SYSTEM</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not exist
<b>Modular Boiler</b>	
Instance on Basement	Does not exist
<b>Steam Boiler</b>	
Instance on Basement	Inspected
Instance	Basement boiler room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH
Manufacturer	Federal
EquipmentId	51944-01
Capacity/Size	4720 Net MBH
Installation Year	1965

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>BOILER SYSTEM</b>	
<b>Steam Boiler</b>	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement boiler room
Instance Condition	3- Fair
Instance Quantity	4,720
Instance Quantity Uom	MBH
Manufacturer	Federal
EquipmentId	51944-02
Capacity/Size	4720 Net MBH
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>FUEL SYSTEMS</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BURNER CONTROL PANEL:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement boiler room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	OIL BURNER:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement boiler room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>FUEL SYSTEMS</b>	
<b>Burner/Burner Control Panel</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL TRANSFER PUMP:DEFECTIVE PUMP
Deficiency Location/Instance	Basement boiler room - leaks 2 of 2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Does not exist
<b>IDF (ENCLOSED ROOMS)</b>	Inspected
Instance	Rooms 120 , 218 & 318
<b>A/C EQUIPMENT</b>	
Instance on Rooms 120 , 218 & 318	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Rooms 120 , 218 & 318
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>VENTILATION EQUIPMENT</b>	
Instance on Rooms 120 , 218 & 318	Does not exist
<b>KITCHEN</b>	Inspected
Instance	1st floor
<b>CO DETECTOR</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS SYSTEM</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GREASE TRAP</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HOOD</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HOOD EXHAUST DUCTWORK</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>HOOD EXHAUST DUCTWORK</b>	
Deficiency	No deficiencies recorded
<b>HOOD EXHAUST FAN</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HOOD FIRE SUPPRESSION SYSTEM</b>	
Instance on 1st floor	Does not exist
<b>HOT WATER TEMPERATURE BOOSTER</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement boiler room above HWHE - Leaks
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>KITCHEN SINK</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	MISSING INDIRECT WASTE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	21280
<b>MDF ROOM</b>	
Instance	Inspected
Instance	Room 247
<b>A/C EQUIPMENT</b>	
Instance on Room 247	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>VENTILATION EQUIPMENT</b>	
Instance on Room 247	Does not exist
<b>SCIENCE DEMO ROOM</b>	
Instance on Room 247	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 347	Inspected
Alternative Use	No
<b>ACID WASTE NEUTRALIZING TANK</b>	
Instance on Room 347	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>CO DETECTOR</b>	
Instance on Room 347	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>EMERGENCY SHOWER</b>	
Instance on Room 347	Does not exist
<b>EYE WASH</b>	
Instance on Room 347	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>EYE WASH</b>	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>FIXED LABORATORY HOOD</b>	
Instance on Room 347	Does not exist
<b>HOOD EXHAUST DUCTWORK</b>	
Instance on Room 347	Does not exist
<b>HOOD EXHAUST FAN</b>	
Instance on Room 347	Does not exist
<b>LABORATORY SINK</b>	
Instance on Room 347	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>MAKE-UP AIR UNIT</b>	
Instance on Room 347	Does not exist
<b>PORTABLE LABORATORY HOOD</b>	
Instance on Room 347	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	
	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>DELUGE VALVE</b>	
	Does not exist
<b>FIRE BOOSTER PUMP ASSEMBLY</b>	
	Does not exist
<b>ROOF TANK</b>	
	Does not exist
<b>SIAMESE CONNECTION</b>	
Condition	3- Fair
Deficiency	MISSING CAPS
Deficiency Location/Instance	York St.@ main entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SPRINKLER ALARM VALVE ASSEMBLY</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SPRINKLER HEAD</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SPRINKLER PIPING</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>STANDPIPE SYSTEM</b>	
	Does not exist
<b>WATER GONG</b>	
	Does not exist
<b>SWIMMING POOL</b>	
	Does not exist
<b>VENTILATION</b>	
	Inspected
<b>EXHAUST FAN</b>	
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Main roof -1 of 10 - bad bearing
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**K307**

<b>Question</b>	<b>Response</b>
<b>VENTILATION</b>	
<b>EXHAUST FAN</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>HEATING AND VENTILATING UNIT</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Cafeteria fan room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>METAL DUCTWORK</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SUPPLY FAN</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>UNIT VENTILATOR</b>	
	Does not exist