

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

School: P.S. 132 - MANHATTAN, 185 WADSWORTH AVENUE, MANHATTAN, NY, 10033

InspectionId	Inspection Type	Time In	Last Edited
1530142	ELECTRICAL	2011-03-18 08:48AM	2011-05-09 05:50AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Library Years: 2010 Systems: Local Sound System, Projection System in Auditorium Years: 2010 Systems: Smart Boards Years: 2008 Systems: Telephone System Years: 2008 Systems: Security Lights Years: 2008 Systems: Fluorescent Lighting Years: 2006 Systems: Local Sound System in Cafeteria, PA System Years: 2006 Systems: LAN Years: 2003 Systems: Exit, Emergency Lights, Emergency Lighting Panel Years: 2003 Systems: Service Switch, Switchboard, Grounding System, Most Motor Starters Years: 2000 Systems: Intrusion Alarm System Years: 1993 Systems: Molded Case Circuit Breaker Panel Boards (partial) Years: 1999, 2000, 2003, 2009, 2010 Type of Service Below Ground

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Chain Missing	Fire Alarm System Tamper Flow Switch/Chain	All Sprinkler Valves	Fireman - David Riley
Not Operational	Fire Alarm System Manual Pull Station	Outside Room 511	Fireman - David Riley
Cover Missing, Lock Missing	Panel Boards Molded Case Circuit Breaker Type	5th Floor Corridor in West Building near Staircase C/D, Staircase A/B	Fireman - David Riley

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	1st Floor
HOUSE LIGHTING	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
AUDITORIUM	
HOUSE LIGHTING	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
LOCAL SOUND SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
PROJECTION SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
THEATER LIGHTING SYSTEM	
Instance on 1st Floor	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	BELL TRANSFORMER PANEL NOT OPERATIONAL Basement - West Building
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	
Instance	Inspected
Instance	1st Floor
LIGHTING	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
CAFETERIA	
LOCAL SOUND SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
LIGHTING	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
SMART BOARD	
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	
Instance	Room 510
Has LAN/Modem access	Yes
Power Panel?	No
LIGHTING	
Instance on Room 510	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
COMPUTER LAB	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on Room 510	Inspected
Pendant Mounted	
Instance on Room 510	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 510	Does not exist
Surface Mounted	
Instance on Room 510	Does not exist
Lighting Fixture - HID	
Instance on Room 510	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 510	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
BATTERY PACK	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
BATTERY PACK	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
AREA SMOKE DETECTOR	Does not exist
BELL/HORN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUCT SMOKE DETECTOR	Does not exist
ELEVATOR RECALL	Does not exist
FAN SHUTDOWN CONTROL	Does not exist
FIRE ALARM DIGITAL COMMUNICATOR	Does not exist
FUSED CUTOFF PANEL	Inspected
Condition	3- Fair
Deficiency	PANEL ID IS MISSING
Deficiency Location/Instance	Closet inside Cafeteria
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
FIRE ALARM SYSTEM	
FUSED CUTOOUT PANEL	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
HEAT DETECTOR	
Does not exist	
MAGNETIC DOOR HOLDER CONTACTOR	
Does not exist	
MAIN PANEL	
Inspected	
Bell At Panel	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
Does not exist	
Fire Alarm Control Panel (Standard)	
Inspected	
Instance	Basement - West Building
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm Control Board
Capacity/Size	6 circuits
Installation Year	1979
Source of Installation Year	Documented
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	81,000
Quantity Uom	S.F.
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
MANUAL PULL STATION	
Inspected	
Condition	3- Fair
Deficiency	PULL STATION NOT OPERATIONAL
Deficiency Location/Instance	Outside Room 511
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
REMOTE ANNUNCIATOR	
Does not exist	
SPRINKLER FLOW/AIR PRESSURE SWITCH	
Does not exist	
STROBE	
Does not exist	
SUB-PANEL	
Inspected	
Bell At Panel	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
Does not exist	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
FIRE ALARM SYSTEM	
SUB-PANEL	
Fire Alarm Control Panel (Standard)	Inspected
Instance	Basement - West Building
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	N/A
Capacity/Size	2 circuits
Installation Year	1949
Source of Installation Year	Documented
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
TAMPER FLOW SWITCH/CHAIN	Inspected
Condition	5- Poor
Deficiency	CHAIN MISSING
Deficiency Location/Instance	All Sprinkler Valves - Throughout the Building
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	INSTALL CHAIN
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
GROUNDING SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Room 511
LIGHTING	
Instance on Room 511	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 511	Inspected
Pendant Mounted	
Instance on Room 511	Does not exist
Recessed Mounted	
Instance on Room 511	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
GYMNASIUM	
LIGHTING	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 511	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 511	Does not exist
LOCAL SOUND SYSTEM	
Instance on Room 511	Does not exist
SCOREBOARD	
Instance on Room 511	Does not exist
THEATER LIGHTING SYSTEM	
Instance on Room 511	Does not exist
INTERCOM SYSTEM	Does not exist
KITCHEN/WARMING PANTRY	Inspected
Instance	1st Floor
LIGHTING	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
LAN	Inspected
LOCAL DISTRIBUTION FRAME (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MAIN EQUIPMENT RACK (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 213
Has LAN/Modem access	Yes
LIGHTING	
Instance on Room 213	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
LIBRARY	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on Room 213	Inspected
Pendant Mounted	
Instance on Room 213	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 213	Does not exist
Surface Mounted	
Instance on Room 213	Does not exist
Lighting Fixture - HID	
Instance on Room 213	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 213	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 213	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SMART BOARD	
Instance on Room 213	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTING - SECURITY LIGHTS	Inspected
Condition	1- Good
Replacement Quantity	14
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement - East Building
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
FUSED DISCONNECT SWITCH TYPE	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Warming Pantry
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
PANEL BOARD	
FUSED KNIFE SWITCH TYPE	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement - East Building, Basement - West Building, Oil Pump Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUSED TOGGLE SWITCH TYPE	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	1st, 2nd, 3rd Floor Corridor - East Building, 2nd, 3rd Floor Corridor - West Building, Cafeteria
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Basement - West Building, Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	5th Floor Corridor
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Main Office, Basement - East Building, 1st Floor Corridor - East Building
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	5th Floor Corridor - West Building
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	PANEL BOARD ID IS MISSING

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
PANEL BOARD	
MOLDED CASE CIRCUIT BREAKER TYPE	
Deficiency Location/Instance	1st, 2nd, 3rd Floor Corridor - East Building, 5th Floor Corridor - West Building, Main Office, Kitchen, Cafeteria
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	1st, 3rd Floor Corridor - East Building, Cafeteria
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
INTRUSION ALARM	Inspected
Central Control Panel	Inspected
Instance	Room 103
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV SYSTEM	Does not exist
SERVICE SWITCH	Inspected
Instance	Closet inside Cafeteria
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Delta Metal Products Co.
EquipmentId	Main Service Switch
Capacity/Size	800 Amps
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Water Penetration In Electrical Room?	No
Number of Spares	5
AIR CIRCUIT BREAKER TYPE	
	Does not exist
FUSED DISCONNECT SWITCH TYPE	
	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDP
Capacity/Size	800 Amps total, 2 sections
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
FUSED KNIFE SWITCH TYPE	
	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	
	Does not exist
TELEPHONE	
	Inspected
PBX/INTERCOM	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
STANDARD	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
LIGHTING	
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Surface Mounted	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
	Does not exist
Surface Mounted	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M132

Question	Response
TOILET ROOM - STAFF	
LIGHTING	
Lighting Fixture - Incandescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
TOILET ROOM - STUDENT	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Master Antenna System Exist?	No
MAIN EQUIPMENT RACK	Does not exist