

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

School: **P.S. 62 - QUEENS, 97-25 108 STREET, QUEENS, NY, 11419**

InspectionId	Inspection Type	Time In	Last Edited
1262102	MECHANICAL	2009-03-19 10:11AM	2009-04-01 03:35PM

***Asset Data***

Question	Answer
Heating Plant Oil Number	2
Have any Systems/Major Building Components been upgraded?	Systems: Heating plant, chilled water system, CSAH's, domestic water heater and pressure booster system. Years: 2002

***Priority Condition***

No condition recorded

***Inspection***

Question	Response
----------	----------

**MECHANICAL**

**AIR CONDITIONING**

Inspected

**Chilled Water System**

Inspected

**Absorption Chiller**

Does not exist

**Air Cooled Chiller**

Inspected

Instance

Penthouse MER

Instance Condition

1- Good

Instance Quantity

1

Instance Quantity Uom

EACH

Manufacturer

York

EquipmentId

Chiller 1

Capacity/Size

86 tons

Installation Year

2002

Deficiency

No deficiencies recorded

Instance

Penthouse MER

Instance Condition

1- Good

Instance Quantity

1

Instance Quantity Uom

EACH

Manufacturer

York

EquipmentId

chiller 2

Capacity/Size

86 tons

Installation Year

2002

Deficiency

No deficiencies recorded

**Air Cooled Condenser**

Inspected

Instance

New wing roof

Instance Condition

1- Good

Instance Quantity

1

Instance Quantity Uom

EACH

Manufacturer

York

EquipmentId

ACC-1

Capacity/Size

86 tons

Installation Year

2002

Deficiency

No deficiencies recorded

Instance

New wing roof

Instance Condition

1- Good

Instance Quantity

1

Instance Quantity Uom

EACH

Manufacturer

York

EquipmentId

ACC-2

Capacity/Size

86 tons

Installation Year

2002

Deficiency

No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Air Separator</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Central Station Air Handler</b>	Inspected
Instance	MER 005
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU -1
Capacity/Size	2400 cfm
Installation Year	2002
Deficiency	No deficiencies recorded
Instance	Cafeteria roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU-4
Capacity/Size	4300 cfm
Installation Year	2002
Deficiency	No deficiencies recorded
Instance	Cafeteria roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU-3
Capacity/Size	8000 cfm
Installation Year	2002
Deficiency	No deficiencies recorded
Instance	MER 005
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU-2
Capacity/Size	13600 cfm
Installation Year	2002
Deficiency	No deficiencies recorded
<b>Chilled Water Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Chilled Water Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Chiller Emergency Stop Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Cold Water Piping (A/C Make-up)</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Cold Water Piping (A/C Make-up)</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Expansion Tank</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Fan Coil Unit</b>	
Condition	Does not exist
<b>Packaged Air Cooled Chiller</b>	
Condition	Does not exist
<b>Water Cooled Chiller</b>	
Condition	Does not exist
<b>Condenser Water Piping</b>	
Condition	Does not exist
<b>Condenser Water Pump</b>	
Condition	Does not exist
<b>Cooling Coils in Ductwork</b>	
Condition	Does not exist
<b>Cooling Tower</b>	
Condition	Does not exist
<b>DX Split System</b>	
<b>Indoor Unit</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Outdoor Unit</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Packaged / Rooftop Unit</b>	
Condition	Does not exist
<b>Packaged Terminal A/C</b>	
Condition	Does not exist
<b>Refrigerant Piping</b>	
Condition	Inspected
Deficiency	1- Good
<b>Return Fan</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
<b>Window Type A/C</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	
Condition	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	
Condition	Inspected
<b>Damper Actuator</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>DDC Computer</b>	
Condition	No deficiencies recorded
<b>Local Control Panel</b>	
Condition	Does not exist
Deficiency	Inspected
Deficiency Location/Instance	2- Between Good and Fair
Deficiency Quantity	NOT IN USE
Quantity Uom	Boiler Room B8 '
Potential Action	1
Urgency of Action	EACH
Purpose of Action	NO ACTION
Violations	PRIORITY 1
	LEVEL 1
	No violations recorded
<b>Pneumatic PRV Station</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Pneumatic Tubing</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
	2- Between Good and Fair
	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>CLIMATE CONTROL SYSTEM</b>	
<b>Refrigerated Air Dryer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Air Compressor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Thermostat</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Zone Valve</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Valve</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Throughout the old wing / (60/76)
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiters</b>	Does not exist
<b>Elevators</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Escalators</b>	Does not exist
<b>Non-auditorium Handicap Lift</b>	Does not exist
<b>Sidewalk / Ash Hoist</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Inspected
Instance	Boiler Room B8
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Canariis
EquipmentId	N/A
Capacity/Size	6.5 HP each (3 Pumps)
Installation Year	2002
Deficiency	No deficiencies recorded
<b>Hydraulic/Pneumatic Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
<b>Service Piping (Water Main)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Main - Double Check Valve</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Main - RPZ</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Cold Water System</b>	
<b>Water Service</b>	
<b>Water Main - RPZ</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Circulating Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room B8
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size	400 gal / 399 MBH input
Installation Year	2002
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>House Trap</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Interior Floor Drain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Interior Storm Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage / Waste Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Room B6
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Sump Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	New wing MER
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
<b>Sump Pump</b>	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Vent Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	
Condition	Does not exist
<b>EMERGENCY GENERATOR</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>FIXTURES</b>	
Condition	Inspected
<b>Staff And Other</b>	
Condition	Inspected
<b>Boiler Room - Eye Wash</b>	
Condition	Does not exist
<b>Janitor Sink</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Toilet</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Urinal</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Location/Instance	DEFECTIVE FLUSHOMETER VALVE
Deficiency Quantity	Men's room in lobby
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
<b>Student</b>	
Condition	No violations recorded
<b>Drinking Fountain</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Locker Room Shower</b>	
Condition	Does not exist
<b>Sink And Fountain Combo Unit</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Toilet</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Urinal</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Location/Instance	DEFECTIVE FLUSHOMETER VALVE
	Boys room on third floor

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Student</b>	
<b>Urinal</b>	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not exist
<b>Gas Meter Room Vent</b>	Does not exist
<b>Gas Pressure Booster</b>	Does not exist
<b>HEATING</b>	Inspected
<b>Baseboard/Fin Tube</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heating Coils In Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hydronic Heating</b>	Does not exist
<b>Radiator / Convector</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Old wing MER
Deficiency Quantity	250
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Condensate Return System</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room / (1/2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>Steam Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>STEAM SUPPLIED BY EXTERNAL SOURCES</b>	
<b>Terminal Fan Coil Unit</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	10,396
Replacement Uom	MBH
<b>Boiler Auxiliaries</b>	Inspected
<b>Boiler Blowdown/Piping System</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Breeching</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Damper (In Breeching)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	Inspected
<b>Boiler Feedwater Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Tank</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Feedwater Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Gas Burner</b>	Does not exist
<b>Boiler Gas/Oil Burner</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Header Valve</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	Inspected
<b>Double Check Valves</b>	Does not exist
<b>RPZ</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Make-up Water Backflow Preventer</b>	
<b>RPZ</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Oil Burner</b>	
	Does not exist
<b>Boiler Room Steam And Condensate Piping</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Safety Valve</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Burner Control Panel</b>	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
<b>Boiler System</b>	
	Inspected
<b>Coal-fired Boiler</b>	
	Does not exist
<b>Hot Water Boiler</b>	
	Does not exist
<b>Modular Boiler</b>	
	Does not exist
<b>Steam Boiler</b>	
	Inspected
Instance	Boiler Room B8
Instance Condition	1- Good
Instance Quantity	5,198
Instance Quantity Uom	MBH
Manufacturer	Easco
EquipmentId	112015-1
Capacity/Size	5198 MBH net
Installation Year	2002
Deficiency	No deficiencies recorded
Instance	Boiler Room B8
Instance Condition	1- Good
Instance Quantity	5,198
Instance Quantity Uom	MBH
Manufacturer	Easco
EquipmentId	112015-2
Capacity/Size	5198 MBH net
Installation Year	2002
Deficiency	No deficiencies recorded
<b>Fuel Systems</b>	
	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO/Gas Leak Detection</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Heater</b>	
	Does not exist
<b>Fuel Oil Level Gauge</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Piping</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Fuel Systems</b>	
<b>Fuel Oil Piping</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Tank</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Transfer Pump</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Oil Leak Detector In Tank Room</b>	
	Does not exist
<b>Overfill Alarm By Oil Fill</b>	
	Does not exist
<b>KITCHEN</b>	
Instance	First floor
<b>CO Detector</b>	
Instance on First floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>CO/Gas Leak Detector</b>	
Instance on First floor	Does not exist
<b>Gas System</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on First floor	Inspected
Instance	Kitchen
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ansul
EquipmentId	N/A
Capacity/Size	3 Gals.
Installation Year	2002

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>Hood Fire Suppression System</b>	
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Kitchen Sink</b>	
Instance on First floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Deluge Valve</b>	Does not exist
<b>Fire Booster Pump Assembly</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Roof Tank</b>	Does not exist
<b>Siamese Connection</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Inspected
<b>Hose Valve Assembly</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Water Gong</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
<b>Duct- Register / Diffuser</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire / Smoke Damper</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q062**

Question	Response
<b>VENTILATION</b>	
<b>Heating And Ventilating Unit</b>	
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Cafeteria roof /
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Metal Ductwork</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Unit Ventilator</b>	
	Does not exist