

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

School: **P.S. 180 - BROOKLYN, 5601 16TH AVENUE, BROOKLYN, NY, 11204**

InspectionId	Inspection Type	Time In	Last Edited
1251020	ELECTRICAL	2008-12-16 08:04AM	2009-07-07 10:52AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: CCA Years: 2000 Systems: Lighting : Toilets- Staff / Student Years: 2000 Systems: Boiler Room - Electrical Upgrade Years: 2000 Systems: Fire Alarm System / Partial Years: 1993 Systems: LAN Years: 1999 Systems: Intrusion Alarm Years: 2005 Systems: Emergency and Exit lighting systems/Partial Years: 2002

**Priority Condition**

Condition Description	Component Affected	Location Description	Person(s) Notified
Water filtration in the Electric Meter Room / Basement	Electrical Service Switches and Switchboards	Electric Meter Room /Basement	Martin Cavanaugh Jr. / Custodian

**Inspection**

Question	Response
<b>ELECTRICAL</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance	First-Floor
<b>House Lighting</b>	
Instance on First-Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on First-Floor	Inspected
<b>Pendant Mounted</b>	
Instance on First-Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on First-Floor	Does not exist
<b>Surface Mounted</b>	
Instance on First-Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on First-Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on First-Floor	Does not exist
<b>Local Sound System</b>	
Instance on First-Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	
<b>Projection System</b>	
Instance on First-Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on First-Floor	Inspected
<b>Dimming System</b>	
Instance on First-Floor	Does not exist
<b>Theater Lighting</b>	
Instance on First-Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	34
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
	Inspected
Condition	3- Fair
Replacement Quantity	121,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
	Inspected
Instance	First Floor
<b>Lighting</b>	
Instance on First Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on First Floor	Inspected
<b>Pendant Mounted</b>	
Instance on First Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on First Floor	Does not exist
<b>Surface Mounted</b>	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on First Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on First Floor	Does not exist
<b>Local Sound System</b>	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CAFETERIA/MULTIPURPOSE ROOM</b>	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>COMPUTER LAB</b>	Inspected
Instance	Room #404
Has LAN/Modem access	Yes
Power Panel?	No
<b>Lighting</b>	
Instance on Room #404	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room #404	Inspected
<b>Pendant Mounted</b>	
Instance on Room #404	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room #404	Does not exist
<b>Surface Mounted</b>	
Instance on Room #404	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room #404	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room #404	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>COMPUTER LAB</b>	
<b>Raceway With Receptacles</b>	
Instance on Room #404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>ELECTRIC SERVICE SWITCH</b>	Inspected
Instance	Electrical Room -Basement
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
Model	American Switchboard Co.
EquipmentId	N/A
Capacity/Size	2000 Amps
Installation Year	1950
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electric Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Connected To Emergency Generator System</b>	Does not exist
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Relay Test Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Connected To Emergency Generator System</b>	Does not exist
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	121,000
Replacement Uom	S.F.
<b>Area Smoke Detector</b>	Does not exist
<b>Bell/Horn</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Duct Smoke Detector</b>	Does not exist
<b>Elevator Recall</b>	Does not exist
<b>Fan Shutdown Control</b>	Does not exist
<b>Fire Alarm Digital Communicator</b>	Does not exist
<b>Fused Cutout Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Does not exist
<b>Magnetic Door Holder Contactor</b>	Does not exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Does not exist
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Boiler Room / Basement
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Fire Alarm Control Panel
Capacity/Size	6 circuits
Installation Year	1963
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Manual Pull Station</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Does not exist
<b>Strobe</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Boiler Room - Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cerberus Pyrotronics
Model	Systems 3 - CP 35
EquipmentId	Strobe Light Control Panel
Capacity/Size	6 zones
Installation Year	1992
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance	3rd Floor
Instance	5th FLOOR
<b>Lighting</b>	
Instance on 3rd Floor	Inspected
Instance on 5th FLOOR	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 3rd Floor	Inspected
Instance on 5th FLOOR	Inspected
<b>Pendant Mounted</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>Recessed Mounted</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>Surface Mounted</b>	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 5th FLOOR	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>Local Sound System</b>	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th FLOOR	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Scoreboard</b>	

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

K180

Question	Response
<b>GYMNASIUM</b>	
<b>Scoreboard</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>Theater Lighting System</b>	
Instance on 3rd Floor	Does not exist
Instance on 5th FLOOR	Does not exist
<b>INTERCOM SYSTEM</b>	
<b>KITCHEN/WARMING PANTRY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
<b>Surface Mounted</b>	
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance	Room #314
Has LAN/Modem access	Yes
Instance	Room #511
Has LAN/Modem access	Yes
<b>Lighting</b>	
Instance on Room #314	Inspected
Instance on Room #511	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room #314	Inspected
Instance on Room #511	Inspected
<b>Pendant Mounted</b>	
Instance on Room #314	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room #511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room #314	Does not exist
Instance on Room #511	Does not exist
<b>Surface Mounted</b>	
Instance on Room #314	Does not exist
Instance on Room #511	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room #314	Does not exist
Instance on Room #511	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room #314	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room #511	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room #314	Does not exist
Instance on Room #511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIGHTING - EXTERIOR SECURITY</b>	Inaccessible
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>LOCKER ROOM/SHOWER ROOM</b>	Inspected
Instance	Room 559M
Alternative Use	Yes
<b>Lighting</b>	
Instance on Room 559M	Not required
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance	First Floor
<b>Lighting</b>	
Instance on First Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on First Floor	Inspected
<b>Pendant Mounted</b>	
Instance on First Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on First Floor	Does not exist
<b>Surface Mounted</b>	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on First Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on First Floor	Does not exist
<b>Local Sound System</b>	
Instance on First Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on First Floor	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	First Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Toggle Switch Type</b>	
Violations	No violations recorded
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	121,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland
Deficiency	AMPLIFIER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	oared Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SECURITY</b>	Inspected
Replacement Quantity	121,000
Replacement Uom	S.F.
<b>Intrusion Alarm</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	First Floor - Utility closet
Instance Condition	1- Good
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**K180**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>Intrusion Alarm</b>	
<b>Central Control Panel</b>	
Instance Quantity Uom	EACH
Model	ADEMCO-VISTA-128B
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	
Condition	Does not exist
<b>IPDVS/CCTV System</b>	
Condition	Does not exist
<b>SWIMMING POOL</b>	
Condition	Does not exist
<b>SWITCHBOARD</b>	
Condition	Inspected
<b>Air Circuit Breaker Type</b>	
Condition	Does not exist
<b>Fused Disconnect Switch Type</b>	
Condition	Inspected
Instance	Electric Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard
EquipmentId	N/A
Capacity/Size	1000 Amps total, 2 sections
Installation Year	1950
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	DP-EM
Capacity/Size	400 Amps total, 2 sections
Installation Year	1992

NYC Department of Education  
 Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

K180

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency	No deficiencies recorded
Instance	Boiler Room - Basement
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard
EquipmentId	N/A
Capacity/Size	469 Amps totals.
Installation Year	1950
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

**K180**

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist
<b>TV SYSTEM</b>	Does not exist