

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

School: P.S. 180 - BROOKLYN, 5601 16TH AVENUE, BROOKLYN, NY, 11204

InspectionId	Inspection Type	Time In	Last Edited
2010019	ELECTRICAL	2010-10-27 08:44AM	2011-05-09 05:50AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fire Alarm System Years: Under Construction Systems: Interior Lighting (All) Years: 2003 Systems: Science Lab. Years: 2009 Systems: Local Sound System in Auditorium Years: 2007 Systems: Projection System Years: 2003-2004 Systems: Smart Boards Years: 2008-2009 Systems: Emergency and Exit Lighting Systems Years: 1998-1999 Systems: LAN I / Local Distribution Frames Years: 2003 and 2009 Systems: LAN Main Distribution Frame Years: 2003 and 2009 Systems: Exterior Security Lighting Years: 2008 Systems: Public Address System (Amplifier, Tuner, Bell System) Years: 2009 Systems: Intrusion Alarm Years: 2006 Systems: Telephone Systems Years: 2004 Systems: Panel Board Fused Disconnect Switch Type / Partial Years: 1992 Systems: Panel Board Molded Case Circuit Breaker Type / Partial Years: 1998 and 2008 Systems: Motor Stater / Contactor - Partial Years: 1991 and 2001
Type of Service	Below Ground

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Local Sound System Not - Connected to Public Address System	Public Address System	Auditorium	Martin Cavanagh Jr., Custodian
Water Penetration	Electrical Switchboards and Service Switch	Electrical Room - Basement	Martin Cavanagh Jr., Custodian

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	1st Floor
HOUSE LIGHTING	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
AUDITORIUM	
HOUSE LIGHTING	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
LOCAL SOUND SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	NOT CONNECTED TO PA SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
PROJECTION SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
THEATER LIGHTING SYSTEM	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	39
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
CAFETERIA	Inspected
Instance	1st Floor
LIGHTING	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
LOCAL SOUND SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
LIGHTING	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
LIGHTING	
Lighting Fixture - Incandescent	
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SMART BOARD	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance	Rooms 404 ,511
Has LAN/Modem access	Yes
Power Panel?	No
LIGHTING	
Instance on Rooms 404 ,511	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 404 ,511	Inspected
Pendant Mounted	
Instance on Rooms 404 ,511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Rooms 404 ,511	Does not exist
Surface Mounted	
Instance on Rooms 404 ,511	Does not exist
Lighting Fixture - HID	
Instance on Rooms 404 ,511	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 404 ,511	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Rooms 404 ,511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
BATTERY PACK	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	3rd Floor Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT LIGHT	Inspected
BATTERY PACK	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Exit Door #9 - 5th Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
AREA SMOKE DETECTOR	Does not exist
BELL/HORN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUCT SMOKE DETECTOR	Does not exist
ELEVATOR RECALL	Does not exist
FAN SHUTDOWN CONTROL	Does not exist
FIRE ALARM DIGITAL COMMUNICATOR	Does not exist
FUSED CUTOFF PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEAT DETECTOR	Does not exist
MAGNETIC DOOR HOLDER CONTACTOR	Does not exist
MAIN PANEL	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
FIRE ALARM SYSTEM	
MAIN PANEL	
Fire Alarm Control Panel (Standard)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Fire Alarm Control Panel
Capacity/Size	6 circuits
Installation Year	1963
Source of Installation Year	Documented
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	121,000
Quantity Uom	S.F.
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MANUAL PULL STATION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
REMOTE ANNUNCIATOR	Does not exist
SPRINKLER FLOW/AIR PRESSURE SWITCH	Does not exist
STROBE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SUB-PANEL	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cerberus Pyrotronics
Model	N/A
EquipmentId	Strobe Light Control Panel
Capacity/Size	6 zones
Installation Year	1992
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
TAMPER FLOW SWITCH/CHAIN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	3rd Floor
Instance	5th Floor
LIGHTING	
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
GYMNASIUM	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
LOCAL SOUND SYSTEM	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCOREBOARD	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
THEATER LIGHTING SYSTEM	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
INTERCOM SYSTEM	
	Does not exist
KITCHEN/WARMING PANTRY	
Instance	Inspected
	1st Floor
LIGHTING	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
KITCHEN/WARMING PANTRY	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
LAN	Inspected
LOCAL DISTRIBUTION FRAME (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MAIN EQUIPMENT RACK (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 314
Has LAN/Modem access	Yes
LIGHTING	
Instance on Room 314	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 314	Inspected
Pendant Mounted	
Instance on Room 314	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 314	Does not exist
Surface Mounted	
Instance on Room 314	Does not exist
Lighting Fixture - HID	
Instance on Room 314	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 314	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 314	Does not exist
SMART BOARD	
Instance on Room 314	Does not exist
LIGHTING - SECURITY LIGHTS	Inspected
Condition	1- Good
Replacement Quantity	22
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Mechanical Space in Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Inspected
Instance	1st Floor - North
Instance	1st Floor - South
LIGHTING	
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - North	Inspected
Instance on 1st Floor - South	Inspected
Pendant Mounted	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Recessed Mounted	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Surface Mounted	
Instance on 1st Floor - North	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
LOCAL SOUND SYSTEM	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
PROJECTION SYSTEM	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
THEATER LIGHTING SYSTEM	
Instance on 1st Floor - North	Does not exist
Instance on 1st Floor - South	Does not exist
PANEL BOARD	Inspected
FUSED DISCONNECT SWITCH TYPE	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
PANEL BOARD	
FUSED DISCONNECT SWITCH TYPE	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUSED KNIFE SWITCH TYPE	
	Does not exist
FUSED TOGGLE SWITCH TYPE	
	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Equipment Room - Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOLDED CASE CIRCUIT BREAKER TYPE	
	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	1st, 2nd, 3rd, 4th, 5th Floor Corridors, Auditorium, Gymnasiums, Cafeteria, Multipurpose Room (North)
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	General Office - Room 212
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	RAULAND SWT425 / MCZ300 / MCB300
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms, Corridors, Administrative
Deficiency Quantity	80
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Rooms 101A, 213, 307,507
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
PUBLIC ADDRESS SYSTEM	
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	
Instance on Room 407	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Room 407	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Room 407	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Room 407	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 407	Inspected
Pendant Mounted	
Instance on Room 407	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 407	Does not exist
Surface Mounted	
Instance on Room 407	Does not exist
Lighting Fixture - HID	
Instance on Room 407	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 407	Does not exist
POWER SUPPLY	
Instance on Room 407	Inspected
Instructor Unit	
Instance on Room 407	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 407	Does not exist
Student Unit	
Instance on Room 407	Does not exist
PROJECTION SYSTEM	
Instance on Room 407	Does not exist
SMART BOARD	
Instance on Room 407	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
INTRUSION ALARM	Inspected
Central Control Panel	Inspected
Instance	Custodial Closet - Near Cafeteria - 1st Floor
Instance Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
SECURITY	
INTRUSION ALARM	
Central Control Panel	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV SYSTEM	Does not exist
SERVICE SWITCH	Inspected
Instance	Electrical Equipment Room in vicinity of Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard Co., Inc.
EquipmentId	N/A
Capacity/Size	2000 Amps
Source of Capacity/Size	Nameplate
Installation Year	1950
Source of Installation Year	Documented
Deficiency	SWITCH ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Water Penetration In Electrical Room?	Yes
Number of Spares	0
AIR CIRCUIT BREAKER TYPE	Does not exist
FUSED DISCONNECT SWITCH TYPE	Inspected
Instance	Electrical Equipment Room in vicinity of Boiler Room
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K180

Question	Response
SWITCHBOARD	
FUSED DISCONNECT SWITCH TYPE	
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co., Inc.
EquipmentId	N/A
Capacity/Size	1000 Amps total, 3 sections
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1950
Source of Installation Year	Documented
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUSED KNIFE SWITCH TYPE	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	Does not exist
TELEPHONE	Inspected
PBX/INTERCOM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
STANDARD	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2010-2011

Electrical Inspection

K180

Question	Response
TOILET ROOM - STUDENT	
LIGHTING	
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Master Antenna System Exist?	No
MAIN EQUIPMENT RACK	Does not exist