

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

School: **P.S. 329 - BROOKLYN, 2929 WEST 30 STREET, BROOKLYN, NY, 11212**

InspectionId	Inspection Type	Time In	Last Edited
1196031	ELECTRICAL	2008-12-24 08:13AM	2009-01-12 05:54PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency Lights and Partial Exit Lights Years: 2007 Systems: Fire Alarm System Years: 2006 Systems: PA and Local Sound Systems Years: 2005 Systems: Intrusion Alarm Years: 2006 Systems: Fluorescent Lighting in Room 123 Years: 2007 Systems: Partial Outside Security Lights Years: 1998 and 2006 Systems: LAN and PBX/ Intercom Years: 2005 Systems: Partial Stage Lighting Years: 2002 Systems: Auditorium Projection System Years: 2005

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	First Floor
House Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Does not exist
Recessed Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on First Floor	Does not exist
Lighting Fixture - HID	
Instance on First Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor	Does not exist
Surface Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on First Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Projection System	
Instance on First Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on First Floor	Inspected
Dimming System	
Instance on First Floor	Does not exist
Theater Lighting	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Replacement Quantity	95,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
CAFETERIA	
Instance	First Floor
Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Does not exist
Recessed Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on First Floor	Does not exist
Lighting Fixture - HID	
Instance on First Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor	Does not exist
Local Sound System	
Instance on First Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Main Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1,230
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Does not exist	
Lighting Fixture - Incandescent	
Inspected	
Pendant Mounted	
Inspected	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	50
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Does not exist	
Surface Mounted	
Inspected	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	
Inspected	
Instance	Rooms 123 and 150
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Rooms 123 and 150	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 123 and 150	Inspected
Pendant Mounted	
Instance on Rooms 123 and 150	Does not exist
Recessed Mounted	
Instance on Rooms 123 and 150	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Rooms 123 and 150	Does not exist
Lighting Fixture - HID	
Instance on Rooms 123 and 150	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 123 and 150	Does not exist
Raceway With Receptacles	
Instance on Rooms 123 and 150	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
Model	Federal Pacific
EquipmentId	Federal Pacific
Capacity/Size	Svce Disco Serving L& PM Swbd
Installation Year	2000 Amps
Deficiency	1973
Instance	No deficiencies recorded
Instance Condition	Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
Model	Federal Pacific
EquipmentId	Federal Pacific
Capacity/Size	Serv Disc Serving Air C Equip PP
Installation Year	1200 Amps
Deficiency	1973
Instance	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
EMERGENCY GENERATOR SET	
Condition	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
Battery Pack	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K329

Question	Response
EMERGENCY LIGHTING	
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Relay Test Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	95,000
Replacement Uom	S.F.
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Magnetic Door Holder Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
Model	EST2
EquipmentId	Fire Alarm Control Panel

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Capacity/Size	5 zones
Installation Year	2006
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
	Does not exist
Manual Pull Station	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Display Monitor	
	Does not exist
Panel	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Printer	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sub-Panel	
	Does not exist
Tamper Flow Switch/Chain	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
	Inspected
Instance	First Floor
Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Does not exist
Lighting Fixture - HID	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor	Does not exist
Surface Mounted	
Instance on First Floor	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K329

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Incandescent	
Instance on First Floor	Does not exist
Local Sound System	
Instance on First Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Scoreboard	
Instance on First Floor	Does not exist
Theater Lighting System	
Instance on First Floor	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	
	Inspected
Instance	Room 228
Has LAN/Modem access	Yes
Lighting	
Instance on Room 228	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 228	Inspected
Pendant Mounted	
Instance on Room 228	Does not exist
Recessed Mounted	
Instance on Room 228	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 228	Does not exist
Lighting Fixture - HID	
Instance on Room 228	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 228	Does not exist
Raceway With Receptacles	
Instance on Room 228	Does not exist
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	3- Fair
Replacement Quantity	40
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Building Perimeter
Deficiency Quantity	31
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Does not exist
MOTOR CONTROL CENTER	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	N/A
Capacity/Size	N/A, 2 sections
Installation Year	1973
Deficiency	MCC ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MCC NAME PLATE IS MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
MOTOR CONTROL CENTER	
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	95,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Replacement Quantity	95,000
Replacement Uom	S.F.
Intrusion Alarm	Inspected
Central Control Panel	Inspected
Instance	Custodians Office
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	VISTA 128B
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
SECURITY	
Intrusion Alarm	
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Does not exist
SWIMMING POOL	
SWITCHBOARD	
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size	1500 Amps total, 2 sections
Installation Year	1973
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Heatg Equip. PP
Capacity/Size	400 Amps total, 1 section
Installation Year	1973
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	DP-EM
Capacity/Size	400 Amps total, 1 section
Installation Year	1992
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	PPH
Capacity/Size	400 Amps total, 1 section
Installation Year	1973
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
SWITCHBOARD	
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K329

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Inspected
Condition	3- Fair
Deficiency	ANTENNA NOT IN USE
Deficiency Location/Instance	Roof
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded