

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

School: **P.S. 332 - BROOKLYN, 51 CHRISTOPHER AVENUE, BROOKLYN, NY, 11212**

InspectionId	Inspection Type	Time In	Last Edited
1193035	MECHANICAL	2009-05-15 11:14AM	2009-05-21 11:26AM

Asset Data

Question	Answer
Heating Plant Oil Number	6
Have any Systems/Major Building Components been upgraded?	Systems: Rooftop/Packaged A/C Climate Control / Dx Split A/C Years: 2006 Systems: Science Lab & Prep Room Years: 2007

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Piping	Does not exist
Condenser Water Pump	Does not exist
Cooling Coils in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Packaged / Rooftop Unit	Inspected
Instance	Lower Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	RTU-1
Capacity/Size	50 Tons
Installation Year	2006
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
Window Type A/C	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 423
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
CLIMATE CONTROL SYSTEM	Inspected
Damper Actuator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DDC Computer	Does not exist
Local Control Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Pneumatic PRV Station	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pneumatic Tubing	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Throughout
Deficiency Quantity	1,000
Quantity Uom	LF
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Refrigerated Air Dryer	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Temperature Control Air Compressor	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Temperature Control Thermostat	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Temperature Control Zone Valve	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Valve	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
CLIMATE CONTROL SYSTEM	
Terminal Unit Thermostatic Valve	
Deficiency	No deficiencies recorded
COMPACTOR	
	Does not exist
CONVEYING	
Dumbwaiters	Does not exist
Elevators	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Escalators	
	Does not exist
Non-auditorium Handicap Lift	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Sidewalk / Ash Hoist	
Condition	Inspected
Condition	3- Fair
Deficiency	TRACTION:NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
DOMESTIC WATER SYSTEM	
	Inspected
Domestic Cold Water System	
	Inspected
Gravity System	
	Does not exist
Pressure Booster System	
	Inspected
Electric Pressure Booster System	
	Does not exist
Hydraulic/Pneumatic Booster System	
	Inspected
Domestic Cold Water Tank	
Condition	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster Pump	
	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Pressure Booster - Compressor	
	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Hydraulic/Pneumatic Booster System	
Water Pressure Booster - Compressor	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
Service Piping (Water Main)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Main - Double Check Valve	Does not exist
Water Main - RPZ	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Circulating Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room / Under Domestic water steam heat exchanger
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
House Trap	Inspected
Condition	4- Between Fair and Poor
Deficiency	DETERIORATED
Deficiency Location/Instance	Room B018
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Interior Floor Drain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage / Waste Piping	Inspected
Condition	3- Fair
Deficiency	CLOGGED

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage / Waste Piping	
Deficiency Location/Instance	Basement / Floods during heavy rain
Deficiency Quantity	150
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LEAKS
Deficiency Location/Instance	3rd Floor Boys Bathroom / leaking from waste pipe above
Deficiency Quantity	15
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LEAKS
Deficiency Location/Instance	2nd Floor Boys Bathroom / leaking from waste pipe above
Deficiency Quantity	15
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sump Pump	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
EMERGENCY GENERATOR	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Boiler Room - Eye Wash	Does not exist
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
FIXTURES	
Staff And Other	
Urinal	
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Inspected
Condition	3- Fair
Alternative Use	Yes
Deficiency	NOT IN USE
Deficiency Location/Instance	Gym
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Room 410
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	3rd Floor Boys Bathroom / Cracked urinal
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
HEATING	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
HEATING	
Baseboard/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heating Coils In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator / Convectector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return System	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
STEAM SUPPLIED BY EXTERNAL SOURCES	
Terminal Fan Coil Unit	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Rooms 110, 109, 108, 107, 106, 104, 103, 101
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Mechanical Inspection

K332

Question	Response
HEATING	
Terminal Fan Coil Unit	
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Room 110
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Unit Heater/Cabinet Heater	
	Does not exist
HEATING PLANT	
	Inspected
Replacement Quantity	12,150
Replacement Uom	MBH
Boiler Auxiliaries	
	Inspected
Boiler Blowdown/Piping System	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Breeching	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Damper (In Breeching)	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
	Inspected
Boiler Feedwater Pump	
	Does not exist
Boiler Feedwater Tank	
	Does not exist
Feedwater Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
	Does not exist
Boiler Gas Burner	
	Does not exist
Boiler Gas/Oil Burner	
	Does not exist
Boiler Header Valve	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
	Does not exist
Boiler Make-up Water Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Oil Burner	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Room Steam And Condensate Piping	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Room Steam And Condensate Piping	
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Burner Control Panel	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler System	
Condition	Inspected
Coal-fired Boiler	
Condition	Does not exist
Hot Water Boiler	
Condition	Does not exist
Modular Boiler	
Condition	Does not exist
Steam Boiler	
Instance	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,050
Instance Quantity Uom	MBH
Manufacturer	Pacific National
EquipmentId	53197-1
Capacity/Size	4050 MBH (Net)
Installation Year	1967
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room / Boiler #53197-1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,050
Instance Quantity Uom	MBH
Manufacturer	Pacific National
EquipmentId	53197-3
Capacity/Size	4050 MBH (Net)
Installation Year	1967
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room / Boiler #53197-3
Deficiency Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,050
Instance Quantity Uom	MBH
Manufacturer	Pacific National
EquipmentId	53197-2
Capacity/Size	4050 MBH (Net)
Installation Year	1967
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room / Boiler #53197-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Systems	Inspected
Boiler Fresh Air Louver/Damper	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fuel Oil Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Level Gauge	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Transfer Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	Does not exist
Oil Leak Detector In Tank Room	Does not exist
Overfill Alarm By Oil Fill	Does not exist
KITCHEN	Inspected
Instance	First Floor
CO Detector	
Instance on First Floor	Does not exist
CO/Gas Leak Detector	
Instance on First Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
KITCHEN	
CO/Gas Leak Detector	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on First Floor	Does not exist
Hot Water Temperature Booster	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Kitchen Sink	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Inspected
Instance	Room 413 (Portable Fume Hood)
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 413 (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	
Instance on Room 413 (Portable Fume Hood)	Does not exist
CO/Gas Leak Detector	
Instance on Room 413 (Portable Fume Hood)	Does not exist
Emergency Shower	
Instance on Room 413 (Portable Fume Hood)	Does not exist
Eye Wash	
Instance on Room 413 (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 413 (Portable Fume Hood)	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K332

Question	Response
SCIENCE LAB	
Hood Exhaust Fan	
Instance on Room 413 (Portable Fume Hood)	Does not exist
Laboratory Hood	
Instance on Room 413 (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Room 413 (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 413 (Portable Fume Hood)	Does not exist
SCIENCE PREP ROOM	
Instance	Inspected
Alternative Use	Room 413A (Portable Fume Hood)
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 413A (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shower	
Instance on Room 413A (Portable Fume Hood)	Does not exist
Eye Wash	
Instance on Room 413A (Portable Fume Hood)	Does not exist
Hood Exhaust Ductwork	
Instance on Room 413A (Portable Fume Hood)	Does not exist
Hood Exhaust Fan	
Instance on Room 413A (Portable Fume Hood)	Does not exist
Laboratory Hood	
Instance on Room 413A (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Room 413A (Portable Fume Hood)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 413A (Portable Fume Hood)	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Deluge Valve	Inspected
Deluge Valve	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Alarm Valve Assembly	Does not exist
Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Piping	
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	
Standpipe System	Does not exist
Water Gong	
Water Gong	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Mechanical Inspection

K332

Question	Response
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Duct- Register / Diffuser	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Lower Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fire / Smoke Damper	Does not exist
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Supply Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Unit Ventilator	Does not exist