

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

School: **P.S. 156 - BROOKLYN, 104 SUTTER AVENUE, BROOKLYN, NY, 11203**

InspectionId	Inspection Type	Time In	Last Edited
2190053	ELECTRICAL	2011-02-09 08:53AM	2011-03-02 10:20PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Systems Years: 2002 Systems: Smart Boards Years: 2008-2009
Type of Service	Below Ground

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Fire Alarm System Fire Alarm Digital Communicator Not-Connected to Central Station	Fire Alarm System	Room C09	JOE NADAL, CUSTODIAN

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	1st Floor
HOUSE LIGHTING	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
LOCAL SOUND SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PROJECTION SYSTEM	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
AUDITORIUM	
PROJECTION SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
THEATER LIGHTING SYSTEM	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance	Inspected
Instance	Room 130
Instance	Room 131
LIGHTING	
Instance on Room 130	Inspected
Instance on Room 131	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 130	Inspected
Instance on Room 131	Inspected
Pendant Mounted	
Instance on Room 130	Does not exist
Instance on Room 131	Does not exist
Recessed Mounted	
Instance on Room 130	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 131	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 130	Does not exist
Instance on Room 131	Does not exist
Lighting Fixture - HID	
Instance on Room 130	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
CAFETERIA	
LIGHTING	
Lighting Fixture - HID	
Instance on Room 131	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 130	Does not exist
Instance on Room 131	Does not exist
LOCAL SOUND SYSTEM	
Instance on Room 130	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 131	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
LIGHTING	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	7
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
LIGHTING	
Lighting Fixture - HID	
Recessed Mounted	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	
Condition	Does not exist
SMART BOARD	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	
Instance	Inspected
Instance	Room 101
Has LAN/Modem access	Yes
Power Panel?	Yes
Instance	Room 422
Has LAN/Modem access	Yes
Power Panel?	No
LIGHTING	
Instance on Room 101	Inspected
Instance on Room 422	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 101	Inspected
Instance on Room 422	Inspected
Pendant Mounted	
Instance on Room 101	Does not exist
Instance on Room 422	Does not exist
Recessed Mounted	
Instance on Room 101	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 422	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 101	Does not exist
Instance on Room 422	Does not exist
Lighting Fixture - HID	
Instance on Room 101	Does not exist
Instance on Room 422	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 101	Does not exist
Instance on Room 422	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 101	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
COMPUTER LAB	
RACEWAY WITH RECEPTACLES	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 422	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
AUTOMATIC TRANSFER SWITCH (ATS)	Inspected
Instance	Room C07
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS-1
Capacity/Size	2000 Amps
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C07
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS-2 / Fire Alarm Panel
Capacity/Size	30 Amps
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C09
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	FIRETROL, INC.
EquipmentId	Fire Pump Power Transfer Switch
Capacity/Size	20 HP
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
BATTERY CHARGER	Inspected
Instance	Room C04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Charles Industries, Ltd..
EquipmentId	Battery Charger
Capacity/Size	5 AmpsDC, 24 VDC
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
DIESEL	Inspected
Instance	Room C04
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
EMERGENCY GENERATOR SET	
DIESEL	
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Emergency Generator
Capacity/Size	750 kVA, 600 kW, 2084 Amps
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
NATURAL GAS	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
BATTERY PACK	Does not exist
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
BATTERY PACK	Does not exist
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
AREA SMOKE DETECTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
BELL/HORN	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUCT SMOKE DETECTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ELEVATOR RECALL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FAN SHUTDOWN CONTROL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM DIGITAL COMMUNICATOR	Inspected
Instance	Room C09
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ADEMCO-5110XM
EquipmentId	Fire Alarm Digital Communicator
Capacity/Size	5 zones
Installation Year	2002
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 5

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
FIRE ALARM SYSTEM	
FIRE ALARM DIGITAL COMMUNICATOR	
Purpose of Action	LEVEL 6
Violations	No violations recorded
FUSED CUTOOUT PANEL	
Condition	Inspected
Deficiency	2- Between Good and Fair
HEAT DETECTOR	
Condition	Inspected
Deficiency	2- Between Good and Fair
MAGNETIC DOOR HOLDER CONTACTOR	
Condition	Inspected
Deficiency	2- Between Good and Fair
MAIN PANEL	
Bell At Panel	Inspected
Condition	Inspected
Deficiency	2- Between Good and Fair
Fire Alarm Control Panel (Electronic)	
Instance	Inspected
Instance Condition	Main Lobby
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
Model	Simplex
EquipmentId	4100
Capacity/Size	Fire Alarm Control Panel
Installation Year	56 zones, 2 sections
Source of Installation Year	2002
Deficiency	Documented
Fire Alarm Control Panel (Standard)	
	Does not exist
MANUAL PULL STATION	
Condition	Inspected
Deficiency	2- Between Good and Fair
REMOTE ANNUNCIATOR	
Display Monitor	Inspected
Panel	Does not exist
Condition	Inspected
Deficiency	2- Between Good and Fair
Printer	
Condition	Inspected
Deficiency	2- Between Good and Fair
Punch Register	
	Does not exist
SPRINKLER FLOW/AIR PRESSURE SWITCH	
Condition	Inspected
Deficiency	2- Between Good and Fair
STROBE	
Condition	Inspected
Deficiency	2- Between Good and Fair
SUB-PANEL	
	Does not exist
TAMPER FLOW SWITCH/CHAIN	
Condition	Inspected
Deficiency	2- Between Good and Fair
GROUNDING SYSTEM	
Condition	Inspected
	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
GROUNDING SYSTEM	
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance	2nd Floor - Room 227
LIGHTING	
Instance on 2nd Floor - Room 227	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Room 227	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor - Room 227	Inspected
Pendant Mounted	
Instance on 2nd Floor - Room 227	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor - Room 227	Does not exist
Surface Mounted	
Instance on 2nd Floor - Room 227	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Room 227	Does not exist
LOCAL SOUND SYSTEM	
Instance on 2nd Floor - Room 227	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCOREBOARD	
Instance on 2nd Floor - Room 227	Does not exist
THEATER LIGHTING SYSTEM	
Instance on 2nd Floor - Room 227	Does not exist
INTERCOM SYSTEM	
	Inspected
ELEVATOR	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
HOLDING AREA	
	Does not exist
KITCHEN/WARMING PANTRY	
Instance	1st Floor - Room 132
LIGHTING	
Instance on 1st Floor - Room 132	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Room 132	Inspected
Pendant Mounted	
Instance on 1st Floor - Room 132	Does not exist
Recessed Mounted	
Instance on 1st Floor - Room 132	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor - Room 132	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Room 132	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
KITCHEN/WARMING PANTRY	
LIGHTING	
Lighting Fixture - Incandescent	
Instance on 1st Floor - Room 132	Does not exist
LAN	Inspected
LOCAL DISTRIBUTION FRAME (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MAIN EQUIPMENT RACK (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 322
Has LAN/Modem access	Yes
LIGHTING	
Instance on Room 322	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 322	Inspected
Pendant Mounted	
Instance on Room 322	Does not exist
Recessed Mounted	
Instance on Room 322	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 322	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 322	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 322	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 322	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SMART BOARD	
Instance on Room 322	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTING - SECURITY LIGHTS	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	32

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
LIGHTING - SECURITY LIGHTS	
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	
Instance on Boys - Room 229	Inspected
Alternative Use	No
Instance on Girls - Room 232	Inspected
Alternative Use	No
LIGHTING	
Instance on Boys - Room 229	Inspected
Instance on Girls - Room 232	Inspected
Lighting Fixture - Fluorescent	
Instance on Boys - Room 229	Inspected
Instance on Girls - Room 232	Inspected
Pendant Mounted	
Instance on Boys - Room 229	Does not exist
Instance on Girls - Room 232	Does not exist
Recessed Mounted	
Instance on Boys - Room 229	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Girls - Room 232	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Boys - Room 229	Does not exist
Instance on Girls - Room 232	Does not exist
Lighting Fixture - HID	
Instance on Boys - Room 229	Does not exist
Instance on Girls - Room 232	Does not exist
Lighting Fixture - Incandescent	
Instance on Boys - Room 229	Does not exist
Instance on Girls - Room 232	Does not exist
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
	Does not exist
PANEL BOARD	
	Inspected
FUSED DISCONNECT SWITCH TYPE	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
FUSED KNIFE SWITCH TYPE	
	Does not exist
FUSED TOGGLE SWITCH TYPE	
	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
PANEL BOARD	
MOLDED CASE CIRCUIT BREAKER TYPE	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
Instance	Room 222
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	RAULAND TC2105
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms, Corridors, Administrative Spaces
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 313	Inspected
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance on Room 414	Inspected
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance on Room 421	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Room 313	Does not exist
Instance on Room 414	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Room 313	Does not exist
Instance on Room 414	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Room 313	Inspected
Instance on Room 414	Inspected
Instance on Room 421	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 313	Inspected

NYC Department of Education
 Building Condition Assessment Survey 2010-2011

Electrical Inspection

K356

Question	Response
SCIENCE LAB	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on Room 414	Inspected
Instance on Room 421	Inspected
Pendant Mounted	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Does not exist
Recessed Mounted	
Instance on Room 313	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 414	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Does not exist
Lighting Fixture - HID	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Does not exist
POWER SUPPLY	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Inspected
Instructor Unit	
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 421	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PROJECTION SYSTEM	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist
Instance on Room 421	Does not exist
SMART BOARD	
Instance on Room 313	Does not exist
Instance on Room 414	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
SCIENCE LAB	
SMART BOARD	
Instance on Room 421	Does not exist
SCIENCE PREP ROOM	
Instance on Room 313A	Inspected
Has LAN/Modem access	No
Power Panel?	No
Alternative Use	No
Instance on Room 421A	Inspected
Has LAN/Modem access	No
Power Panel?	No
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Room 313A	Does not exist
Instance on Room 421A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Room 313A	Does not exist
Instance on Room 421A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Room 313A	Inspected
Instance on Room 421A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 313A	Inspected
Instance on Room 421A	Inspected
Pendant Mounted	
Instance on Room 313A	Does not exist
Instance on Room 421A	Does not exist
Recessed Mounted	
Instance on Room 313A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 421A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 313A	Does not exist
Instance on Room 421A	Does not exist
Lighting Fixture - HID	
Instance on Room 313A	Does not exist
Instance on Room 421A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 313A	Does not exist
Instance on Room 421A	Does not exist
POWER SUPPLY	
Instance on Room 313A	Does not exist
Instance on Room 421A	Does not exist
SECURITY	
INTRUSION ALARM	
Central Control Panel	
Instance	Room 118

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
SECURITY	
INTRUSION ALARM	
Central Control Panel	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	ADEMCO
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV SYSTEM	
	Does not exist
SERVICE SWITCH	
	Inspected
Instance	Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech Service Equipment Corp. / SIEMENS
EquipmentId	Main Distribution A
Capacity/Size	4000 Amps
Source of Capacity/Size	Nameplate
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech Service Equipment Corp. / SIEMENS
EquipmentId	Main Distribution B
Capacity/Size	4000 Amps
Source of Capacity/Size	Nameplate
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Water Penetration In Electrical Room?	No
Number of Spares	0
AIR CIRCUIT BREAKER TYPE	
	Does not exist
FUSED DISCONNECT SWITCH TYPE	
	Inspected
Instance	Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
SWITCHBOARD	
FUSED DISCONNECT SWITCH TYPE	
Manufacturer	Electrotech Service Equipment Corp.
EquipmentId	N/A
Capacity/Size	4000 Amps total, 3 sections
Source of Capacity/Size	Service Switch Size
Installation Year	2002
Source of Installation Year	Documented
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room C05
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech Service Equipment Corp. / Siemens
EquipmentId	N/A
Capacity/Size	4000 Amps total, 3 sections
Source of Capacity/Size	Service Switch Size
Installation Year	2002
Source of Installation Year	Documented
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room C07
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech Service Equipment Corp.
EquipmentId	Emergency Distribution Board
Capacity/Size	2000 Amps total, 2 sections
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K356

Question	Response
SWITCHBOARD	
FUSED KNIFE SWITCH TYPE	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	Does not exist
TELEPHONE	Inspected
PBX/INTERCOM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
STANDARD	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Master Antenna System Exist?	No
MAIN EQUIPMENT RACK	Does not exist