

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

School: **LAFAYETTE HS - K, 2630 BENSON AVENUE, BROOKLYN, NY, 11214**

InspectionId	Inspection Type	Time In	Last Edited
1247141	ELECTRICAL	2009-06-15 01:06PM	2009-06-24 09:02AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	<p>Systems: Science Rooms- Lab, Prep; Raceway Receptacles- Room 419; Partial- Panel Boards (Molded Cases), Motor Starter/Contactor</p> <p>Years: 2005-2006</p> <p>Systems: Auditorium- Theater Lighting System, Projection System</p> <p>Years: 1999-2000</p> <p>Systems: Interior Fluorescent Lighting- Classrooms, Stairs, Corridors, and Some Toilet Rooms; Emergency Lighting</p> <p>Years: 2000</p> <p>Systems: LAN, Telephone System</p> <p>Years: 2003</p> <p>Systems: Fire Alarm System</p> <p>Years: 2008</p> <p>Systems: Intercom System- Elevator; CCTV System</p> <p>Years: 2006</p> <p>Systems: Switchboard- Molded Case</p> <p>Years: 1995</p> <p>Systems: PA and Local Sound Systems</p> <p>Years: 1992</p>

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	First Floor
House Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Does not exist
Lighting Fixture - HID	
Instance on First Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor	Does not exist
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on First Floor	Inspected
Dimming System	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Replacement Quantity	5- Poor
Replacement Uom	270,000
Deficiency	S.F.
Deficiency	GENERAL OFFICE PUSH BUTTON STATION NOT OPERATIONAL
Deficiency Location/Instance	General Office- Room 133
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE STATION
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DOOR PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	
Instance	Inspected
Instance	Basement- Staff Cafeteria
Instance	Basement- Students

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
CAFETERIA	
Lighting	
Instance on Basement- Staff Cafeteria	Inspected
Instance on Basement- Students	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement- Staff Cafeteria	Inspected
Instance on Basement- Students	Inspected
Pendant Mounted	
Instance on Basement- Staff Cafeteria	Does not exist
Instance on Basement- Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement- Staff Cafeteria	Does not exist
Instance on Basement- Students	Does not exist
Surface Mounted	
Instance on Basement- Staff Cafeteria	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement- Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement- Staff Cafeteria	Does not exist
Instance on Basement- Students	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement- Staff Cafeteria	Does not exist
Instance on Basement- Students	Does not exist
Local Sound System	
Instance on Basement- Staff Cafeteria	Does not exist
Instance on Basement- Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Pendant Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	36

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	Inspected
Instance	Room 427
Has LAN/Modem access	Yes
Power Panel?	Yes
Instance	Room 419
Has LAN/Modem access	Yes
Power Panel?	No
Lighting	
Instance on Room 427	Inspected
Instance on Room 419	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 427	Inspected
Instance on Room 419	Inspected
Pendant Mounted	
Instance on Room 427	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 419	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 427	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room 419	Does not exist
Surface Mounted	
Instance on Room 427	Does not exist
Instance on Room 419	Does not exist
Lighting Fixture - HID	
Instance on Room 427	Does not exist
Instance on Room 419	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 427	Does not exist
Instance on Room 419	Does not exist
Raceway With Receptacles	
Instance on Room 427	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 419	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	
Instance	Inspected
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Boltswitch, Inc
Model	Boltswitch, Inc
EquipmentId	Main Service Switch
Capacity/Size	1600 Amps
Installation Year	1953
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Meter Room (Near Room B43)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Boltswitch, Inc
Model	Boltswitch, Inc
EquipmentId	N/A
Capacity/Size	1600 Amps
Installation Year	1953
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Meter Room (Near Room B43)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
ELECTRIC SERVICE SWITCH	
Deficiency	SWITCH ID IS MISSING
Deficiency Location/Instance	Electrical Meter Room (Near Room B43)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	First Floor- Main Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Relay Test Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	3- Fair
Deficiency	BULB NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, and Room 365
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BULB
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	
Does not exist	
Fused Cutout Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	
Does not exist	
Magnetic Door Holder Contactor	
Does not exist	
Main Panel	
Inspected	
Bell At Panel	
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
Instance	Main Entrance Lobby- Near Auditorium
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
Model	MPC-6000
EquipmentId	Fire Alarm Control Panel
Capacity/Size	24 zones
Installation Year	2008
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
Does not exist	
Manual Pull Station	
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	
Inspected	
Display Monitor	
Does not exist	
Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	
Does not exist	
Sprinkler Flow/Air Pressure Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	
Condition	1- Good
Deficiency	No deficiencies recorded
Sub-Panel	
Does not exist	
Tamper Flow Switch/Chain	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Room 466
Instance	Room 465
Instance	First Floor- Main Gymnasium
Lighting	
Instance on Room 466	Inspected
Instance on Room 465	Inspected
Instance on First Floor- Main Gymnasium	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Does not exist
Lighting Fixture - HID	
Instance on Room 466	Inspected
Instance on Room 465	Inspected
Instance on First Floor- Main Gymnasium	Inspected
Pendant Mounted	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Does not exist
Recessed Mounted	
Instance on Room 466	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 465	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Recessed Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on First Floor- Main Gymnasium	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Does not exist
Local Sound System	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Room 466	Does not exist
Instance on Room 465	Does not exist
Instance on First Floor- Main Gymnasium	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
KITCHEN/WARMING PANTRY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 368
Has LAN/Modem access	Yes
Lighting	
Instance on Room 368	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 368	Inspected
Pendant Mounted	
Instance on Room 368	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 368	Does not exist
Surface Mounted	
Instance on Room 368	Does not exist
Lighting Fixture - HID	
Instance on Room 368	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 368	Does not exist
Raceway With Receptacles	
Instance on Room 368	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	50
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	Third Floor- Rooms 366, 365

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
LOCKER ROOM/SHOWER ROOM	
Alternative Use	No
Lighting	
Instance on Third Floor- Rooms 366, 365	Inspected
Lighting Fixture - Fluorescent	
Instance on Third Floor- Rooms 366, 365	Inspected
Pendant Mounted	
Instance on Third Floor- Rooms 366, 365	Does not exist
Recessed Mounted	
Instance on Third Floor- Rooms 366, 365	Does not exist
Surface Mounted	
Instance on Third Floor- Rooms 366, 365	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Third Floor- Rooms 366, 365	Does not exist
Lighting Fixture - Incandescent	
Instance on Third Floor- Rooms 366, 365	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room, Fan Rooms, and Penthouse
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Penthouse and Fan Rooms
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement, Corridors, Cafeteria, Kitchen
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	270,000

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Uom	S.F.
Instance	Principal Office- Room 133
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter IV
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
	Inspected
Instance	Rooms 352, 350, 348, 317, 313, 302, 213, 208, 115, 105
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	Yes
Instance	Rooms 315, 202
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Rooms 352, 350, 348, 317, 313, 302, 213, 208, 115, 105	Does not exist
Instance on Rooms 315, 202	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 352, 350, 348, 317, 313, 302, 213, 208, 115, 105	Does not exist
Instance on Rooms 315, 202	Does not exist
Lighting	
Instance on Rooms 352, 350, 348, 317, 313, 302, 213, 208, 115, 105	Not required
Instance on Rooms 315, 202	Not required
Power Supply	
Instance on Rooms 352, 350, 348, 317, 313, 302, 213, 208, 115, 105	Does not exist
Instance on Rooms 315, 202	Does not exist
SCIENCE LAB	
	Inspected
Instance	Room 309
Has LAN/Modem access	No
Power Panel?	Yes
Alternative Use	No
Instance	Rooms 306, 205, 109
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 309	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 309	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 309	Inspected
Instance on Rooms 306, 205, 109	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 309	Inspected
Instance on Rooms 306, 205, 109	Inspected
Pendant Mounted	
Instance on Room 309	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 309	Does not exist
Instance on Rooms 306, 205, 109	Does not exist
Surface Mounted	
Instance on Room 309	Does not exist
Instance on Rooms 306, 205, 109	Does not exist
Lighting Fixture - HID	
Instance on Room 309	Does not exist
Instance on Rooms 306, 205, 109	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 309	Does not exist
Instance on Rooms 306, 205, 109	Does not exist
Power Supply	
Instance on Room 309	Inspected
Instance on Rooms 306, 205, 109	Inspected
Instructor Unit	
Instance on Room 309	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 309	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 309	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 306, 205, 109	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance	Inspected
Instance	Room 308
Has LAN/Modem access	No
Power Panel?	Yes
Alternative Use	No
Instance	Rooms 209, 109A
Has LAN/Modem access	No
Power Panel?	No
Alternative Use	No
Instance	Room 305
Has LAN/Modem access	No
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 308	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 209, 109A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 308	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 209, 109A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 308	Inspected
Instance on Rooms 209, 109A	Inspected
Instance on Room 305	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 308	Inspected
Instance on Rooms 209, 109A	Inspected
Instance on Room 305	Inspected
Pendant Mounted	
Instance on Room 308	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 209, 109A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 308	Does not exist
Instance on Rooms 209, 109A	Does not exist
Instance on Room 305	Does not exist
Surface Mounted	
Instance on Room 308	Does not exist
Instance on Rooms 209, 109A	Does not exist
Instance on Room 305	Does not exist
Lighting Fixture - HID	
Instance on Room 308	Does not exist
Instance on Rooms 209, 109A	Does not exist
Instance on Room 305	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 308	Does not exist
Instance on Rooms 209, 109A	Does not exist
Instance on Room 305	Does not exist
Power Supply	
Instance on Room 308	Does not exist
Instance on Rooms 209, 109A	Does not exist
Instance on Room 305	Inspected
Instructor Unit	
Instance on Room 305	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SECURITY	Inspected
Replacement Quantity	270,000
Replacement Uom	S.F.
Intrusion Alarm	
Central Control Panel	
Instance	Custodian Office- Room 143
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Ademco
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
SECURITY	
Intrusion Alarm	
Ultrasonic Sensor	
Condition	3- Fair
Deficiency	SENSOR NOT IN USE
Deficiency Location/Instance	First Floor- Corridor
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
IPDVS/CCTV System	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric Co.
EquipmentId	Main Switchboard A
Capacity/Size	1600 Amps total, 4 sections
Installation Year	1953
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric Co.
EquipmentId	Main Switchboard B
Capacity/Size	1600 Amps total, 4 sections
Installation Year	1953
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Inspected
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard Co.
EquipmentId	CDP
Capacity/Size	400 Amps total, 1 section
Installation Year	1995
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Near Room B43)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard Co.
EquipmentId	Computer Distribution Panel
Capacity/Size	400 Amps total, 1 section
Installation Year	1995
Deficiency	No deficiencies recorded
TELEPHONE	
	Inspected
PBX/Intercom	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
	Does not exist
Surface Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TOILET ROOM - STUDENT	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K400

Question	Response
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Does not exist