

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

School: SAMUEL J. TILDEN HS - K, 5800 TILDEN AVENUE, BROOKLYN, NY, 11203

InspectionId	Inspection Type	Time In	Last Edited
1254152	ELECTRICAL	2009-05-21 08:39AM	2009-06-03 11:38AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Telephone System, Scoreboard Years: 2008 Systems: Fire Alarm System Years: Main Panel: 2008; Others: 1994 Systems: Lighting(except incandescent), Emergency/Exit lights and Panel, LAN Years: 2001 Systems: Intrusion Alarm System Years: 2002 Systems: Security Cameras Years: 2004 Systems: Generator System, PA System, Local Sound System Years: 1993 Systems: Exterior Lighting Years: 1997 Systems: Dimming System, Theater Lighting, Main Service Years: 1991 Systems: Panel Boards, Main Service, Switchboard Years: 1991 and 2005 Systems: Science Rooms Years: Demo: 2003; Labs and Prep: 2007

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	First Floor
House Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Does not exist
Recessed Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - HID	
Instance on First Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Does not exist
Recessed Mounted	
Instance on First Floor	Does not exist
Surface Mounted	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on First Floor	Inspected
Instance Condition	5- Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on First Floor	Inspected
Dimming System	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on First Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Replacement Quantity	3- Fair
Replacement Uom	244,000
Deficiency	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	
Instance	Inspected
Instance	Basement
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
COMPUTER LAB	Inspected
Instance	Room 119,203,204
Has LAN/Modem access	Yes
Power Panel?	Yes
Instance	Room 321
Has LAN/Modem access	Yes
Power Panel?	No
Lighting	
Instance on Room 119,203,204	Inspected
Instance on Room 321	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 119,203,204	Inspected
Instance on Room 321	Inspected
Pendant Mounted	
Instance on Room 119,203,204	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 321	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 119,203,204	Does not exist
Instance on Room 321	Does not exist
Surface Mounted	
Instance on Room 119,203,204	Does not exist
Instance on Room 321	Does not exist
Lighting Fixture - HID	
Instance on Room 119,203,204	Does not exist
Instance on Room 321	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 119,203,204	Does not exist
Instance on Room 321	Does not exist
Raceway With Receptacles	
Instance on Room 119,203,204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 321	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Outside Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
Model	Metropolitan
EquipmentId	Service Switch
Capacity/Size	5000 Amps
Installation Year	1991
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	N/A
Capacity/Size	70 Amps
Installation Year	1993
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	N/A
Capacity/Size	600 Amps
Installation Year	1993
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	N/A
Capacity/Size	400 Amps
Installation Year	1993
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	ATS(FA)
Capacity/Size	70 Amps
Installation Year	1993
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size	10 AmpsDC, 24 VDC
Installation Year	1993
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Generator
Capacity/Size	219 kVA, 175 kW
Installation Year	1993
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
Replacement Quantity	244,000
Replacement Uom	S.F.
Area Smoke Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Bell/Horn	
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
	Does not exist
Elevator Recall	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
	Does not exist
Fire Alarm Digital Communicator	
	Does not exist
Fused Cutout Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder Contactor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Panel	
Bell At Panel	
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
Instance	Main Lobby
Instance Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	Notifier
EquipmentId	FACP
Capacity/Size	8 zones
Installation Year	2008
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	MSS Engineering System
Model	MSS
EquipmentId	Fire Control Panel
Capacity/Size	2 zones
Installation Year	1994
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance	First Floor-Gym 3
Instance	First Floor-Gym 1 and Gym 2
Lighting	
Instance on First Floor-Gym 3	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
GYMNASIUM	
Lighting	
Instance on First Floor-Gym 1 and Gym 2	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor-Gym 3	Inspected
Instance on First Floor-Gym 1 and Gym 2	Does not exist
Pendant Mounted	
Instance on First Floor-Gym 3	Does not exist
Recessed Mounted	
Instance on First Floor-Gym 3	Does not exist
Surface Mounted	
Instance on First Floor-Gym 3	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on First Floor-Gym 3	Inspected
Instance on First Floor-Gym 1 and Gym 2	Inspected
Pendant Mounted	
Instance on First Floor-Gym 3	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on First Floor-Gym 1 and Gym 2	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor-Gym 3	Does not exist
Instance on First Floor-Gym 1 and Gym 2	Does not exist
Surface Mounted	
Instance on First Floor-Gym 3	Does not exist
Instance on First Floor-Gym 1 and Gym 2	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor-Gym 3	Inspected
Instance on First Floor-Gym 1 and Gym 2	Does not exist
Pendant Mounted	
Instance on First Floor-Gym 3	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor-Gym 3	Does not exist
Surface Mounted	
Instance on First Floor-Gym 3	Does not exist
Local Sound System	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
GYMNASIUM	
Local Sound System	
Instance on First Floor-Gym 3	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on First Floor-Gym 1 and Gym 2	Inspected
Instance Condition	5- Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Scoreboard	
Instance on First Floor-Gym 3	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on First Floor-Gym 1 and Gym 2	Does not exist
Theater Lighting System	
Instance on First Floor-Gym 3	Does not exist
Instance on First Floor-Gym 1 and Gym 2	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
	Inspected
Instance	Room 306
Has LAN/Modem access	Yes
Lighting	
Instance on Room 306	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 306	Inspected
Pendant Mounted	

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

K415

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 306	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 306	Does not exist
Lighting Fixture - HID	
Instance on Room 306	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 306	Does not exist
Raceway With Receptacles	
Instance on Room 306	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	
Condition	Inspected
Replacement Quantity	2- Between Good and Fair
Replacement Uom	35
Deficiency	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not exist
LOCKER ROOM/SHOWER ROOM	
	Inspected
Instance	Basement-Boys
Alternative Use	No
Instance	Basement-Girls
Alternative Use	No
Lighting	
Instance on Basement-Boys	Inspected
Instance on Basement-Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement-Boys	Inspected
Instance on Basement-Girls	Inspected
Pendant Mounted	
Instance on Basement-Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement-Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K415

Question	Response
LOCKER ROOM/SHOWER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Basement-Boys	Does not exist
Instance on Basement-Girls	Does not exist
Surface Mounted	
Instance on Basement-Boys	Does not exist
Instance on Basement-Girls	Does not exist
Lighting Fixture - HID	
Instance on Basement-Boys	Does not exist
Instance on Basement-Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement-Boys	Does not exist
Instance on Basement-Girls	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	244,000
Replacement Uom	S.F.
Instance	Room 129
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC4001
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance	Room 138,139,141,339
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SCIENCE DEMO ROOM	
Instance	Room 238
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance	Room 329
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance	Room 341
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Emergency Shut-Off Power	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Lighting	
Instance on Room 138,139,141,339	Inspected
Instance on Room 238	Inspected
Instance on Room 329	Inspected
Instance on Room 341	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 138,139,141,339	Inspected
Instance on Room 238	Inspected
Instance on Room 329	Inspected
Instance on Room 341	Inspected
Pendant Mounted	
Instance on Room 138,139,141,339	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 238	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 329	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Surface Mounted	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Lighting Fixture - HID	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Does not exist
Instance on Room 329	Does not exist
Instance on Room 341	Does not exist
Power Supply	
Instance on Room 138,139,141,339	Inspected
Instance on Room 238	Inspected
Instance on Room 329	Does not exist
Instance on Room 341	Inspected
Instructor Unit	
Instance on Room 138,139,141,339	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 238	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 138,139,141,339	Does not exist
Instance on Room 238	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 341	Does not exist
SCIENCE LAB	
Instance	Room 140,241, 340
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Instance	Room 240
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 140,241, 340	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Instance on Room 140,241, 340	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 140,241, 340	Inspected
Instance on Room 240	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 140,241, 340	Inspected
Instance on Room 240	Inspected
Pendant Mounted	
Instance on Room 140,241, 340	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 140,241, 340	Does not exist
Instance on Room 240	Does not exist
Surface Mounted	
Instance on Room 140,241, 340	Does not exist
Instance on Room 240	Does not exist
Lighting Fixture - HID	
Instance on Room 140,241, 340	Does not exist
Instance on Room 240	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 140,241, 340	Does not exist
Instance on Room 240	Does not exist
Power Supply	
Instance on Room 140,241, 340	Inspected
Instance on Room 240	Inspected
Instructor Unit	
Instance on Room 140,241, 340	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 140,241, 340	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 140,241, 340	Does not exist
Instance on Room 240	Inspected
Instance Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	Inspected
Instance	Room 140A,240A,340A,239
Has LAN/Modem access	No
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 140A,240A,340A,239	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 140A,240A,340A,239	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 140A,240A,340A,239	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 140A,240A,340A,239	Inspected
Pendant Mounted	
Instance on Room 140A,240A,340A,239	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 140A,240A,340A,239	Does not exist
Surface Mounted	
Instance on Room 140A,240A,340A,239	Does not exist
Lighting Fixture - HID	
Instance on Room 140A,240A,340A,239	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 140A,240A,340A,239	Does not exist
Power Supply	
Instance on Room 140A,240A,340A,239	Does not exist
SECURITY	Inspected
Replacement Quantity	244,000
Replacement Uom	S.F.
Intrusion Alarm	Inspected
Central Control Panel	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Ademco
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SECURITY	
Intrusion Alarm	
Remote Annunciator	
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Inspected
Instance	Basement
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	
	Inspected
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Manufacturer	MacPower
EquipmentId	Emergency Service Panel
Capacity/Size	800 Amps total, 1 section
Installation Year	1991
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electotech
EquipmentId	DP-PN
Capacity/Size	800 Amps total, 1 section
Installation Year	2005
Deficiency	No deficiencies recorded
Instance	Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	MacPower
EquipmentId	Computer Dist. Panel
Capacity/Size	400 Amps total, 1 section
Installation Year	1991
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size	5000 Amps total, 7 sections
Installation Year	1991
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K415

Question	Response
TELEPHONE	
Standard	
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Inspected
Condition	5- Poor
Deficiency	ANTENNA NOT OPERATIONAL
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded