

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

**Electrical Inspection**

**K496**

**School: SHEEPSHEAD BAY AF - BROOKLYN, 3000 AVENUE X, BROOKLYN, NY, 11235**

InspectionId	Inspection Type	Time In	Last Edited
1620080	ELECTRICAL	2011-01-11 08:54AM	2011-01-27 02:03PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Local Sound System. Years: 1995 Systems: All Other Systems & Components. Years: 2004
Type of Service	Below Ground

**Priority Condition**

No condition recorded

**Inspection**

Question	Response
<b>ELECTRICAL</b>	
<b>ATHLETIC FIELD</b>	Inspected
<b>EXTERIOR LIGHTING</b>	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	4
Replacement Uom	EACH
Deficiency	No deficiencies recorded
<b>LOCAL SOUND SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SCOREBOARD</b>	Inspected
Instance	Batchelder Street Side
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>AUDITORIUM</b>	Does not exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Does not exist
<b>CAFETERIA</b>	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>LIGHTING</b>	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>SMART BOARD</b>	Does not exist
<b>COMPUTER LAB</b>	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not exist
<b>EMERGENCY LIGHTING</b>	Does not exist
<b>EXIT LIGHT</b>	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Electrical Inspection***

**K496**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	Does not exist
<b>GROUNDING SYSTEM</b>	Does not exist
<b>GYMNASIUM</b>	Does not exist
<b>INTERCOM SYSTEM</b>	Does not exist
<b>KITCHEN/WARMING PANTRY</b>	Does not exist
<b>LAN</b>	Does not exist
<b>LIBRARY</b>	Does not exist
<b>LIGHTING - SECURITY LIGHTS</b>	Does not exist
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>LOCKER ROOM</b>	Does not exist
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>FUSED DISCONNECT SWITCH TYPE</b>	Does not exist
<b>FUSED KNIFE SWITCH TYPE</b>	Does not exist
<b>FUSED TOGGLE SWITCH TYPE</b>	Does not exist
<b>MOLDED CASE CIRCUIT BREAKER TYPE</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SECURITY</b>	Does not exist
<b>SERVICE SWITCH</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Does not exist
<b>TELEPHONE</b>	Does not exist
<b>TOILET ROOM - STAFF</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist
<b>TV SYSTEM</b>	Does not exist