

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

School: CLARA BARTON HS - K, 901 CLASSON AVENUE, BROOKLYN, NY, 11225

InspectionId	Inspection Type	Time In	Last Edited
1261053	MECHANICAL	2009-02-03 08:34AM	2009-02-23 09:57AM

Asset Data

Question	Answer
Heating Plant Oil Number	6
Have any Systems/Major Building Components been upgraded?	Systems: Heating system;Boiler # 4 retubbed. Boiler #1 had refractory changed. Years: 2006 Systems: Fuel Oil Tanks Years: 2008. Systems: Steam condensate system; New vacuum steam condensate unit installed. Years: 2008. Systems: Laboratories; new laboratories added and upgraded. Years: 2006. Systems: Boiler feedwater pump replaced. Years: 2006.

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Piping	Does not exist
Condenser Water Pump	Does not exist
Cooling Coils in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
Window Type A/C	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Booms # 339,333.
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
CLIMATE CONTROL SYSTEM	Inspected
Damper Actuator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DDC Computer	Does not exist
Local Control Panel	Does not exist
Pneumatic PRV Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Pneumatic Tubing	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Refrigerated Air Dryer	Does not exist
Temperature Control Air Compressor	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler room. one of two units was not in operation.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Temperature Control Thermostat	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Various locations.
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Temperature Control Zone Valve	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Valve	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiters	Does not exist
Elevators	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Escalators	Does not exist
Non-auditorium Handicap Lift	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sidewalk / Ash Hoist	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Service Piping (Water Main)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Main - Double Check Valve	Does not exist
Water Main - RPZ	Does not exist
Domestic Hot Water System	
Domestic Hot Water Circulating Pump	
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Hot Water Remote Storage Tank	
Domestic Water Heat Exchanger	
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REMOVE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 1
Violations	No violations recorded
Electric Domestic Water Heater	
Gas Fired Domestic Water Heater	
Oil Fired Domestic Water Heater	
Domestic Water Distribution Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
House Trap	
Condition	3- Fair
Deficiency	No deficiencies recorded
Interior Floor Drain	
Condition	3- Fair
Deficiency	No deficiencies recorded
Interior Storm Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage / Waste Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	
Sump Pump	
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Vent Piping	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Vent Piping	
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
	Does not exist
EMERGENCY GENERATOR	
	Does not exist
FIXTURES	
Staff And Other	Inspected
Boiler Room - Eye Wash	Does not exist
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	CLOGGED/DIRTY/LEAKING
Deficiency Location/Instance	Boiler room. Staff bathroom leaking faucet.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room # B 60; toilet has been removed.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	
	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Inspected
Condition	3- Fair
Alternative Use	Yes
Deficiency	NOT IN USE
Deficiency Location/Instance	Gym's locker rooms on the 3rd floor. Rooms # 375 A and # 375.
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
FIXTURES	
Student	
Toilet	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room # B 41; Toilet has been removed.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
HEATING	Inspected
Baseboard/Fin Tube	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heating Coils In Ductwork	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Various locations.
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydronic Heating	Does not exist
Radiator / Convector	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	through-out the building.
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
HEATING	
Steam Heating	
MER Steam and Condensate Piping	
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Through-out building.
Deficiency Quantity	3,500
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return System	
Condition	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE PUMP
Deficiency Location/Instance	Boiler room. Leaking vacuum pump.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	3,500
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STEAM SUPPLIED BY EXTERNAL SOURCES	
Condition	Does not exist
Terminal Fan Coil Unit	
Condition	Does not exist
Unit Heater/Cabinet Heater	
Condition	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
HEATING PLANT	Inspected
Replacement Quantity	24,224
Replacement Uom	MBH
Boiler Auxiliaries	Inspected
Boiler Blowdown/Piping System	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Breeching	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Damper (In Breeching)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	Inspected
Boiler Feedwater Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Feedwater Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	Does not exist
Boiler Gas Burner	Does not exist
Boiler Gas/Oil Burner	Does not exist
Boiler Header Valve	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	Inspected
Double Check Valves	Does not exist
RPZ	Does not exist
Boiler Make-up Water Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Oil Burner	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boils room.
Deficiency Quantity	350
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	Inspected
Condition	3- Fair
Deficiency	MISSING SAFETY VALVE PIPING
Deficiency Location/Instance	Boiler room.

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Safety Valve	
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Burner Control Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	
Condition	Inspected
Coal-fired Boiler	
Condition	Does not exist
Hot Water Boiler	
Condition	Does not exist
Modular Boiler	
Condition	Does not exist
Steam Boiler	
Instance	Boiler room.
Instance Condition	3- Fair
Instance Quantity	6,056
Instance Quantity Uom	MBH
Manufacturer	Farrar & Trefts, Inc.
EquipmentId	7707-1.
Capacity/Size	65 GPH
Installation Year	1939
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler room.
Instance Condition	3- Fair
Instance Quantity	6,056
Instance Quantity Uom	MBH
Manufacturer	Farrar & Trefts, Inc.
EquipmentId	7707-2.
Capacity/Size	65 GPH .
Installation Year	1939
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler room.
Instance Condition	3- Fair
Instance Quantity	6,056
Instance Quantity Uom	MBH
Manufacturer	Farrar & Trefts, Inc.
EquipmentId	7707-3
Capacity/Size	65 GPH .

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Installation Year	1939
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler room.
Instance Condition	3- Fair
Instance Quantity	6,056
Instance Quantity Uom	MBH
Manufacturer	Farrar & Trefts, Inc.
EquipmentId	7707-4.
Capacity/Size	65 GPH .
Installation Year	1939
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Systems	Inspected
Boiler Fresh Air Louver/Damper	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Does not exist
Fuel Oil Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Level Gauge	Inspected
Condition	2- Between Good and Fair
Deficiency	CALIBRATION REQUIRED
Deficiency Location/Instance	Boiler room.
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fuel Oil Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fuel Transfer Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
HEATING PLANT	
Fuel Systems	
Oil Leak Detector In Tank Room	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Overfill Alarm By Oil Fill	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
KITCHEN	
Instance	Inspected
Instance	kitchen of cafeteria, basement level.
CO Detector	
Instance on kitchen of cafeteria, basement level.	Does not exist
CO/Gas Leak Detector	
Instance on kitchen of cafeteria, basement level.	Does not exist
Gas System	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance	Basement level; kitchen of cafeteria.
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ansul
EquipmentId	N/A
Capacity/Size	3 Gallons.
Installation Year	1975
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on kitchen of cafeteria, basement level.	Does not exist
Kitchen Sink	
Instance on kitchen of cafeteria, basement level.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance	Inspected
Instance	Rooms # 438, 440, 443, 445, 447, and 457.
Alternative Use	No

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
SCIENCE DEMO ROOM	
Instance	Rooms # 433, 435. used as a Math classroom.
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Rooms # 438, 440, 443, 445, 447, and 457.	Does not exist
Instance on Rooms # 433, 435. used as a Math classroom.	Does not exist
Emergency Shower	
Instance on Rooms # 438, 440, 443, 445, 447, and 457.	Does not exist
Instance on Rooms # 433, 435. used as a Math classroom.	Does not exist
Eye Wash	
Instance on Rooms # 438, 440, 443, 445, 447, and 457.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms # 433, 435. used as a Math classroom.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Laboratory Hood	
Instance on Rooms # 438, 440, 443, 445, 447, and 457.	Does not exist
Instance on Rooms # 433, 435. used as a Math classroom.	Does not exist
Laboratory Sink	
Instance on Rooms # 438, 440, 443, 445, 447, and 457.	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms # 433, 435. used as a Math classroom.	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Rooms # 433, 435
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
SCIENCE LAB	
Instance	Inspected
Instance	Room # 437.
Alternative Use	No
Instance	Room # 333, 350, and 450.
Alternative Use	No
Instance	Rooms # 339, and 449.
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room # 437.	Does not exist
Instance on Room # 333, 350, and 450.	Does not exist
Instance on Rooms # 339, and 449.	Does not exist
CO Detector	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CO/Gas Leak Detector	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
SCIENCE LAB	
CO/Gas Leak Detector	
Instance on Room # 437.	Does not exist
Instance on Room # 333, 350, and 450.	Does not exist
Instance on Rooms # 339, and 449.	Does not exist
Emergency Shower	
Instance on Room # 437.	Does not exist
Instance on Room # 333, 350, and 450.	Does not exist
Instance on Rooms # 339, and 449.	Does not exist
Eye Wash	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Hood	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Room # 437.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room # 333, 350, and 450.	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
SCIENCE LAB	
Laboratory Sink	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room # 437.	Does not exist
Instance on Room # 333, 350, and 450.	Does not exist
Instance on Rooms # 339, and 449.	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance	Inspected
Alternative Use	Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)
	No
Acid Waste Neutralizing Tank	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Does not exist
Emergency Shower	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Eye Wash	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Hood	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms # 337, 348, 448, and 453. (number 337 was changed From # 335.)	Under construction
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Deluge Valve	Inspected
Fire Booster Pump Assembly	Does not exist
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

K600

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Duct- Register / Diffuser	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire / Smoke Damper	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Supply Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	throughout the building.
Deficiency Quantity	61
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded