

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

School: P.S. 77 ANNEX - BROOKLYN, 62 PARK PLACE, BROOKLYN, NY, 11217

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 2140084 | ELECTRICAL | 2011-01-24 12:32PM | 2011-02-02 04:06PM |

Asset Data

| Question | Answer |
|---|--|
| Have any Systems/Major Building Components been upgraded? | Systems: Smart Boards Years: 2010- 2008 Systems: Security (exterior) lighting Years: 2008 Systems: LAN System Years: 2004 Systems: Telephone System Years: 2004 Systems: Most electrical systems & components Years: 1996 |
| Type of Service | Below Ground |

Priority Condition

No condition recorded

Inspection

| Question | Response |
|--|---------------------------|
| ELECTRICAL | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Does not exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| CAFETERIA | Inspected |
| Instance | Basement |
| LIGHTING | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| LOCAL SOUND SYSTEM | |
| Instance on Basement | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|--|---|
| CITY FIRE ALARM SYSTEM | Does not exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| LIGHTING | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 4- Between Fair and Poor |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 8 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SMART BOARD | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| COMPUTER LAB | Inspected |
| Instance | Room 216 |
| Has LAN/Modem access | Yes |
| Power Panel? | Yes |
| LIGHTING | |
| Instance on Room 216 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 216 | Inspected |
| Pendant Mounted | |
| Instance on Room 216 | Inspected |
| Instance Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|---|--------------------------|
| COMPUTER LAB | |
| LIGHTING | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 216 | Does not exist |
| Surface Mounted | |
| Instance on Room 216 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 216 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 216 | Does not exist |
| RACEWAY WITH RECEPTACLES | |
| Instance on Room 216 | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | NOT OPERATIONAL |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| BATTERY PACK | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| BATTERY PACK | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Does not exist |
| FIRE ALARM SYSTEM | Inspected |
| AREA SMOKE DETECTOR | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| BELL/HORN | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| DUCT SMOKE DETECTOR | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| ELEVATOR RECALL | Does not exist |

NYC Department of Education
Building Condition Assessment Survey 2010-2011

Electrical Inspection

K902

| Question | Response |
|--|--------------------------|
| FIRE ALARM SYSTEM | |
| FAN SHUTDOWN CONTROL | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM DIGITAL COMMUNICATOR | Does not exist |
| FUSED CUTOOUT PANEL | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| HEAT DETECTOR | Does not exist |
| MAGNETIC DOOR HOLDER CONTACTOR | Does not exist |
| MAIN PANEL | Inspected |
| Bell At Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Basement - Meter room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Simplex |
| Model | Simplex 4100 |
| EquipmentId | Fire Alarm Control |
| Capacity/Size | 32 zone |
| Installation Year | 1996 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| MANUAL PULL STATION | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| REMOTE ANNUNCIATOR | Inspected |
| Display Monitor | Does not exist |
| Panel | Does not exist |
| Printer | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not exist |
| SPRINKLER FLOW/AIR PRESSURE SWITCH | Does not exist |
| STROBE | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SUB-PANEL | Does not exist |
| TAMPER FLOW SWITCH/CHAIN | Does not exist |
| GROUNDING SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Inspected |
| Instance | Basement |
| LIGHTING | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Inspected |
| Pendant Mounted | |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|--|---|
| GYMNASIUM | |
| LIGHTING | |
| Lighting Fixture - HID | |
| Pendant Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| LOCAL SOUND SYSTEM | |
| Instance on Basement | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SCOREBOARD | |
| Instance on Basement | Does not exist |
| THEATER LIGHTING SYSTEM | |
| Instance on Basement | Does not exist |
| INTERCOM SYSTEM | |
| Instance | Does not exist |
| KITCHEN/WARMING PANTRY | |
| Instance | Inspected |
| LIGHTING | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | LIGHTING FIXTURE LENS MISSING |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL LENS |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Surface Mounted | |
| Instance on Basement | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|---|--|
| KITCHEN/WARMING PANTRY | |
| LIGHTING | |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| LAN | Inspected |
| LOCAL DISTRIBUTION FRAME (I/LDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| MAIN EQUIPMENT RACK (MDF) | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIBRARY | Inspected |
| Instance | Room 215 |
| Has LAN/Modem access | Yes |
| LIGHTING | |
| Instance on Room 215 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 215 | Inspected |
| Pendant Mounted | |
| Instance on Room 215 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 215 | Does not exist |
| Surface Mounted | |
| Instance on Room 215 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 215 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 215 | Does not exist |
| RACEWAY WITH RECEPTACLES | |
| Instance on Room 215 | Does not exist |
| SMART BOARD | |
| Instance on Room 215 | Does not exist |
| LIGHTING - SECURITY LIGHTS | Inspected |
| Condition | 1- Good |
| Replacement Quantity | 14 |
| Replacement Uom | EACH |
| Deficiency | LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL |
| Deficiency Location/Instance | Side entrance on Park Pl. |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| LIGHTNING PROTECTION | Does not exist |
| LOCKER ROOM | Does not exist |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|--|--|
| MULTIPURPOSE ROOM | Inspected |
| Instance | 1st floor |
| LIGHTING | |
| Instance on 1st floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st floor | Inspected |
| Pendant Mounted | |
| Instance on 1st floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Instance on 1st floor | Does not exist |
| Surface Mounted | |
| Instance on 1st floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING |
| Deficiency Quantity | 25 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lighting Fixture - Incandescent | |
| Instance on 1st floor | Does not exist |
| LOCAL SOUND SYSTEM | |
| Instance on 1st floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| PROJECTION SYSTEM | |
| Instance on 1st floor | Does not exist |
| THEATER LIGHTING SYSTEM | |
| Instance on 1st floor | Inspected |
| Dimming System | |
| Instance on 1st floor | Does not exist |
| Theater Lighting | |
| Instance on 1st floor | Does not exist |
| PANEL BOARD | Inspected |
| FUSED DISCONNECT SWITCH TYPE | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Basement - Meter room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| FUSED KNIFE SWITCH TYPE | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|---|--|
| PANEL BOARD | |
| FUSED TOGGLE SWITCH TYPE | Does not exist |
| MOLDED CASE CIRCUIT BREAKER TYPE | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE |
| Deficiency Location/Instance | Basement - Kitchen |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| | Inspected |
| Instance | Room 301 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Rauland - Telecenter 21 |
| Deficiency | No deficiencies recorded |
| SCIENCE DEMO ROOM | |
| Instance on Room 302 | Inspected |
| Has LAN/Modem access | Yes |
| Power Panel? | No |
| Alternative Use | No |
| EMERGENCY GAS SHUT-OFF VALVE | |
| Instance on Room 302 | Does not exist |
| EMERGENCY SHUT-OFF POWER | |
| Instance on Room 302 | Does not exist |
| LIGHTING | |
| Instance on Room 302 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 302 | Inspected |
| Pendant Mounted | |
| Instance on Room 302 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 302 | Does not exist |
| Surface Mounted | |
| Instance on Room 302 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 302 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 302 | Does not exist |
| POWER SUPPLY | |
| Instance on Room 302 | Does not exist |
| PROJECTION SYSTEM | |
| Instance on Room 302 | Does not exist |
| SMART BOARD | |
| Instance on Room 302 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| SCIENCE LAB | |
| | Does not exist |
| SCIENCE PREP ROOM | |
| | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|---------------------------------------|------------------------------|
| SECURITY | Inspected |
| INTRUSION ALARM | Inspected |
| Central Control Panel | Inspected |
| Instance | Custodian Office |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista 50P |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 5- Poor |
| Deficiency | SIREN/STROBE NOT OPERATIONAL |
| Deficiency Location/Instance | Main Entrance on Park Pl. |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Ultrasonic Sensor | Does not exist |
| IPDVS/CCTV SYSTEM | Does not exist |
| SERVICE SWITCH | Inspected |
| Instance | Basement - Meter room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Gallagher Switchboard Co. |
| EquipmentId | Main Service |
| Capacity/Size | 2000 Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1996 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SWIMMING POOL | Does not exist |
| SWITCHBOARD | Inspected |
| Water Penetration In Electrical Room? | No |
| Number of Spares | 0 |
| AIR CIRCUIT BREAKER TYPE | Does not exist |
| FUSED DISCONNECT SWITCH TYPE | Inspected |
| Instance | Basement - Meter room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Gallagher Switchboard Co. |
| EquipmentId | No ID |
| Capacity/Size | 2000 Amps total, 2 sections |

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

K902

| Question | Response |
|---|-----------------------------------|
| SWITCHBOARD | |
| FUSED DISCONNECT SWITCH TYPE | |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 1996 |
| Source of Installation Year | Documented |
| Deficiency | SWITCHBOARD ID IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | SWITCHBOARD NAME PLATE IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| FUSED KNIFE SWITCH TYPE | Does not exist |
| MOLDED CASE CIRCUIT BREAKER TYPE | Does not exist |
| TELEPHONE | Inspected |
| PBX/INTERCOM | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| STANDARD | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TOILET ROOM - STAFF | Inspected |
| LIGHTING | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| LIGHTING | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| TRANSFORMER | Does not exist |
| TV SYSTEM | Inspected |
| Cable System Exist? | Yes |

NYC Department of Education
Building Condition Assessment Survey 2010-2011

Electrical Inspection

K902

| Question | Response |
|------------------------------|----------------|
| TV SYSTEM | |
| Operational? | No |
| Master Antenna System Exist? | No |
| MAIN EQUIPMENT RACK | Does not exist |