

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

School: **EBC HS FOR PUB. SERV. - BUSHWICK-K, 1155 DEKALB AVENUE, BROOKLYN, NY, 11221**

InspectionId	Inspection Type	Time In	Last Edited
1251152	ELECTRICAL	2009-05-28 10:21AM	2009-06-03 11:10AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Emergency Generator Not - Operational	Emergency Generator	Room 119B	Bermal Nadden, Custodian

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	65,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance	Room 131
Lighting	
Instance on Room 131	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 131	Inspected
Pendant Mounted	
Instance on Room 131	Does not exist
Recessed Mounted	
Instance on Room 131	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 131	Does not exist
Lighting Fixture - HID	
Instance on Room 131	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 131	Does not exist
Local Sound System	
Instance on Room 131	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
COMPUTER LAB	Inspected
Instance	Room 339
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Room 339	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 339	Inspected
Pendant Mounted	
Instance on Room 339	Does not exist
Recessed Mounted	
Instance on Room 339	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 339	Does not exist
Lighting Fixture - HID	
Instance on Room 339	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 339	Does not exist
Raceway With Receptacles	
Instance on Room 339	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical Room (Room 101A)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ELECTROTECH
Model	ELECTROTECH
EquipmentId	QMQB
Capacity/Size	1600 Amps
Installation Year	1998
Deficiency	SWITCH NAME PLATE IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room 103
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Master Control Systems
EquipmentId	ATS
Capacity/Size	25 HP
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Room 101A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	ATS/GTS SYSTEMS
Capacity/Size	420 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Room 101A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	Fire Control Panel
Capacity/Size	105 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Room 119B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	Battery Charger
Capacity/Size	10 AmpsDC, 24VDC
Installation Year	1998
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Room 119B
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac GTS Systems Inc.
EquipmentId	Emergency Generator
Capacity/Size	187.5 kVA, 150 kW, 520.4 Amps
Installation Year	1998
Deficiency	GENERATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Inspected
Condition	2- Between Good and Fair
Deficiency	BULB NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BULB
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Connected To Emergency Light/Exit Light Panel	Does not exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	65,000
Replacement Uom	S.F.
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder Contactor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
Model	N/A
EquipmentId	Fire Alarm Control
Capacity/Size	14 zones

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Installation Year	1998
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
	Does not exist
Manual Pull Station	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Remote Annunciator	
	Inspected
Display Monitor	
	Does not exist
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Printer	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	PRINTER NOT OPERATIONAL
Deficiency Quantity	Custodian Office
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 5
Violations	LEVEL 2
	No violations recorded
Punch Register	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Sub-Panel	
	Does not exist
Tamper Flow Switch/Chain	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
GYMNASIUM	
Instance	Inspected
	Room 415
Lighting	
Instance on Room 415	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 415	Does not exist
Lighting Fixture - HID	
Instance on Room 415	Inspected
Pendant Mounted	
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Pendant Mounted	
Violations	No violations recorded
Recessed Mounted	
Instance on Room 415	Does not exist
Surface Mounted	
Instance on Room 415	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 415	Does not exist
Local Sound System	
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Room 415	Does not exist
Theater Lighting System	
Instance on Room 415	Does not exist
INTERCOM SYSTEM	
Elevator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
	Inspected
Instance	Room 115
Has LAN/Modem access	Yes
Lighting	
Instance on Room 115	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 115	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 115	Does not exist
Recessed Mounted	
Instance on Room 115	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 115	Does not exist
Lighting Fixture - HID	
Instance on Room 115	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 115	Does not exist
Raceway With Receptacles	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	13
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	Boys and Girls (Rooms 421 and 445)
Alternative Use	No
Lighting	
Instance on Boys and Girls (Rooms 421 and 445)	Inspected
Lighting Fixture - Fluorescent	
Instance on Boys and Girls (Rooms 421 and 445)	Inspected
Pendant Mounted	
Instance on Boys and Girls (Rooms 421 and 445)	Does not exist
Recessed Mounted	
Instance on Boys and Girls (Rooms 421 and 445)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Boys and Girls (Rooms 421 and 445)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Boys and Girls (Rooms 421 and 445)	Does not exist
Lighting Fixture - Incandescent	
Instance on Boys and Girls (Rooms 421 and 445)	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
MOTOR STARTER/CONTACTOR	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Inspected
Instance	Room 315
Lighting	
Instance on Room 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 315	Does not exist
Recessed Mounted	
Instance on Room 315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 315	Does not exist
Lighting Fixture - HID	
Instance on Room 315	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 315	Does not exist
Local Sound System	
Instance on Room 315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Room 315	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	65,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	RAULAND 2490
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridor (Near Room 239)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Inspected
Instance	Room 441
Has LAN/Modem access	Yes

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

K913

Question	Response
SCIENCE DEMO ROOM	
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 441	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 441	Inspected
Pendant Mounted	
Instance on Room 441	Does not exist
Recessed Mounted	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 441	Does not exist
Lighting Fixture - HID	
Instance on Room 441	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 441	Does not exist
Power Supply	
Instance on Room 441	Inspected
Instructor Unit	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance	Room 431
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Instance	Doom 439
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Doom 439	Does not exist
Emergency Shut-Off Power	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

K913

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Instance on Doom 439	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 431	Inspected
Instance on Doom 439	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 431	Inspected
Instance on Doom 439	Inspected
Pendant Mounted	
Instance on Room 431	Does not exist
Instance on Doom 439	Does not exist
Recessed Mounted	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Doom 439	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 431	Does not exist
Instance on Doom 439	Does not exist
Lighting Fixture - HID	
Instance on Room 431	Does not exist
Instance on Doom 439	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 431	Does not exist
Instance on Doom 439	Does not exist
Power Supply	
Instance on Room 431	Inspected
Instance on Doom 439	Inspected
Instructor Unit	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Doom 439	Does not exist
Meter Demonstration Unit	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Doom 439	Does not exist
Student Unit	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Doom 439	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance	Room 437
Has LAN/Modem access	No

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
SCIENCE PREP ROOM	
Power Panel?	No
Alternative Use	Yes
Instance	Room 437 A
Has LAN/Modem access	No
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 437	Does not exist
Instance on Room 437 A	Does not exist
Emergency Shut-Off Power	
Instance on Room 437	Does not exist
Instance on Room 437 A	Does not exist
Lighting	
Instance on Room 437	Not required
Instance on Room 437 A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 437 A	Inspected
Pendant Mounted	
Instance on Room 437 A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 437 A	Does not exist
Surface Mounted	
Instance on Room 437 A	Does not exist
Lighting Fixture - HID	
Instance on Room 437 A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 437 A	Does not exist
Power Supply	
Instance on Room 437	Does not exist
Instance on Room 437 A	Does not exist
SECURITY	
Replacement Quantity	65,000
Replacement Uom	S.F.
Intrusion Alarm	
Central Control Panel	
Instance	Custodian Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	ADEMCO-VISTA 50P/VISTA 50PUL
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
SECURITY	
Intrusion Alarm	
Siren/Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
	Does not exist
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room (Room 101A)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MSB-A
Capacity/Size	1600 Amps total, 2 sections
Installation Year	1998
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room (Room 101A)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ELECTROTECH
EquipmentId	MSA
Capacity/Size	1600 Amps total, 1 section
Installation Year	1998
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room 119
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ELECTROTECH
EquipmentId	N/A
Capacity/Size	N/A, 1 sections
Installation Year	1998
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room 119
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ELECTROTECH
EquipmentId	N/A
Capacity/Size	N/A,1 section
Installation Year	1998
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room 119
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ELECTROTECH
EquipmentId	N/A
Capacity/Size	N/A
Installation Year	1998
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE	Inspected
PBX/Intercom	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K913

Question	Response
TELEPHONE	
PBX/Intercom	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Inspected
Condition	3- Fair
Deficiency	ANTENNA NOT IN USE
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded