

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

School: P.S. 92 - MANHATTAN, 222 WEST 134 STREET, MANHATTAN, NY, 10030

InspectionId	Inspection Type	Time In	Last Edited
1183006	ELECTRICAL	2008-11-17 08:36AM	2009-06-17 12:10PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fluorescent lighting in the: Stairs, Toilets, Library, Cafeteria, Auditorium. Emergency lighting panel, Emergency and Exit Lighting, LAN, Security Alarm, Telephone System, Fire Alarm Sub-Panels, 60% of Exterior lighting. CCTV Years: 1999 Systems: Elevator Intercom Underconstruction Years: 2009

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	1st floor
House Lighting	
Instance on 1st floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st floor	Inspected
Pendant Mounted	
Instance on 1st floor	Does not exist
Recessed Mounted	
Instance on 1st floor	Does not exist
Surface Mounted	
Instance on 1st floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st floor	Inspected
Pendant Mounted	
Instance on 1st floor	Does not exist
Recessed Mounted	
Instance on 1st floor	Does not exist
Surface Mounted	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on 1st floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
AUDITORIUM	
Local Sound System	
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st floor	Inspected
Dimming System	
Instance on 1st floor	Does not exist
Theater Lighting	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	94
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
	Inspected
Condition	3- Fair
Replacement Quantity	99,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected
Instance	1st floor
Lighting	
Instance on 1st floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st floor	Inspected
Pendant Mounted	
Instance on 1st floor	Does not exist
Recessed Mounted	
Instance on 1st floor	Does not exist
Surface Mounted	
Instance on 1st floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st floor	Does not exist
Local Sound System	
Instance on 1st floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
CAFETERIA	
Local Sound System	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MICROPHONE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	890
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	102
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Recessed Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	31
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	
Instance	Inspected
Instance	Room 222
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Room 222	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 222	Inspected
Pendant Mounted	
Instance on Room 222	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 222	Does not exist
Surface Mounted	
Instance on Room 222	Does not exist
Lighting Fixture - HID	
Instance on Room 222	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 222	Does not exist
Raceway With Receptacles	
Instance on Room 222	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	
Instance	Inspected
Instance	Electrical room
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
ELECTRIC SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
Model	Metropolitan
EquipmentId	MSS
Capacity/Size	2000 Amps
Installation Year	1964
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	
	Does not exist
Connected To Emergency Light/Exit Light Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Behind Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Connected To Emergency Generator System	
	Does not exist
Connected To Emergency Light/Exit Light Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Replacement Quantity	99,000
Replacement Uom	S.F.
Area Smoke Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	
	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	
Condition	Does not exist
Fused Cutout Panel	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	
Condition	Does not exist
Magnetic Door Holder Contactor	
Condition	Does not exist
Main Panel	
Bell At Panel	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
Condition	Does not exist
Fire Alarm Control Panel (Standard)	
Instance	Inspected
Instance Condition	Boiler room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	ACME
Capacity/Size	Fire Alarm Control Panel
Installation Year	6 circuits
Deficiency	1964
Deficiency Quantity	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE-UPGRADE
Purpose of Action	PRIORITY 1
Violations	LEVEL 2
Violations	No violations recorded
Manual Pull Station	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Display Monitor	
Condition	Does not exist
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
Condition	Does not exist
Punch Register	
Condition	Does not exist
Sprinkler Flow/Air Pressure Switch	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Strobe	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
Model	EST 2
EquipmentId	Elevator Smoke Detection Recall
Capacity/Size	14 zones
Installation Year	1999
Deficiency	No deficiencies recorded
Instance	Boiler room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pyrotronics
Model	System 3
EquipmentId	Smoke detection panel
Capacity/Size	24 zones
Installation Year	1999
Deficiency	No deficiencies recorded
Instance	Boiler room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
Model	EST
EquipmentId	Strobe lighting panel
Capacity/Size	14 zones
Installation Year	1990
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm Control Board.
Capacity/Size	2 circuits
Installation Year	1964
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	1st floor
Lighting	
Instance on 1st floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st floor	Does not exist
Lighting Fixture - HID	
Instance on 1st floor	Inspected
Pendant Mounted	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st floor	Does not exist
Surface Mounted	
Instance on 1st floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st floor	Does not exist
Local Sound System	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	SYSTEM BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Scoreboard	
Instance on 1st floor	Does not exist
Theater Lighting System	
Instance on 1st floor	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Under construction
Holding Area	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
KITCHEN/WARMING PANTRY	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
KITCHEN/WARMING PANTRY	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 204
Has LAN/Modem access	Yes
Lighting	
Instance on Room 204	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 204	Inspected
Pendant Mounted	
Instance on Room 204	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 204	Does not exist
Surface Mounted	
Instance on Room 204	Does not exist
Lighting Fixture - HID	
Instance on Room 204	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 204	Does not exist
Raceway With Receptacles	
Instance on Room 204	Does not exist
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	3- Fair
Replacement Quantity	39
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Roof and Exterior walls
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
LIGHTING - EXTERIOR SECURITY	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	1st floor, close to the GYM
Alternative Use	Yes
Lighting	
Instance on 1st floor, close to the GYM	Not required
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Mechanical spaces
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Corridors and Mechanical spaces
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Quantity	99,000
Replacement Uom	S.F.
Instance	Main office, 1st floor
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Sound systems, inc
Deficiency	AMPLIFIER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Main office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Main office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance	Room 322
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 322	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 322	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 322	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 322	Inspected
Pendant Mounted	
Instance on Room 322	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 322	Does not exist
Surface Mounted	
Instance on Room 322	Does not exist
Lighting Fixture - HID	
Instance on Room 322	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 322	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
SCIENCE LAB	
Power Supply	
Instance on Room 322	Inspected
Instructor Unit	
Instance on Room 322	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 322	Does not exist
Student Unit	
Instance on Room 322	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
	Inspected
Replacement Quantity	99,000
Replacement Uom	S.F.
Intrusion Alarm	
	Inspected
Central Control Panel	
	Inspected
Instance	1st floor, Custodian office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	ADEMCO
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
	Inspected
Condition	5- Poor
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Corridors, 1st floor
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	MONITOR NOT OPERATIONAL
Deficiency Location/Instance	1st floor, Security desk
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
SWIMMING POOL	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M092

Question	Response
SWITCHBOARD	Inspected
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Main SWBD
Capacity/Size	1000 Amps total, 3 sections
Installation Year	1964
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Does not exist
Master Antenna System	Does not exist