

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

School: **EDWARD A. REYNOLDS WEST SIDE HS-M, 140 WEST 102 STREET, MANHATTAN, NY, 10025**

InspectionId	Inspection Type	Time In	Last Edited
2010029	ELECTRICAL	2010-12-10 09:32AM	2010-12-17 05:11PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Smart Boards in Science Rooms Years: 2006-2007 Systems: Smart Boards in Library Years: 2006-2007 Systems: Smart Boards in Classrooms Years: 2006/ 2007/ 2008/2009 Systems: IPDVS / Close Circuit TV System Years: 2010
Type of Service	Below Ground

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Intercom in Elevator Not-Operational	Elevator	Elevator Cab	Ali Turat, Fireman

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance	Basement
LIGHTING	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
LOCAL SOUND SYSTEM	
Instance on Basement	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
CAFETERIA	
LOCAL SOUND SYSTEM	
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
LIGHTING	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
SMART BOARD	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance	Room 203
Has LAN/Modem access	Yes
Power Panel?	No
Instance	Rooms 227, 327
Has LAN/Modem access	Yes
Power Panel?	Yes
LIGHTING	
Instance on Room 203	Inspected
Instance on Rooms 227, 327	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 203	Inspected
Instance on Rooms 227, 327	Inspected
Pendant Mounted	
Instance on Room 203	Does not exist
Instance on Rooms 227, 327	Does not exist
Recessed Mounted	
Instance on Room 203	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 227, 327	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 203	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 227, 327	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
COMPUTER LAB	
LIGHTING	
Lighting Fixture - HID	
Instance on Room 203	Does not exist
Instance on Rooms 227, 327	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 203	Does not exist
Instance on Rooms 227, 327	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 203	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 227, 327	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
AUTOMATIC TRANSFER SWITCH (ATS)	
Instance	Electrical Equipment Room - Room B2A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	CUMMINS-ONAN
EquipmentId	N/A
Capacity/Size	40 Amps
Installation Year	1999
Source of Installation Year	Documented
Deficiency	ATS ID MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Equipment Room - Room B2A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	CUMMINS-ONAN
EquipmentId	N/A
Capacity/Size	600 Amps
Installation Year	1999
Source of Installation Year	Documented
Deficiency	ATS ID MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
BATTERY CHARGER	
Instance	Inspected
Instance	Electrical Room 313
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	CUMMINS-ONAN

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
EMERGENCY GENERATOR SET	
BATTERY CHARGER	
EquipmentId	Battery Charger
Capacity/Size	10 AmpsDC, 12 VDC
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
DIESEL	Inspected
Instance	Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	CUMMINS-ONAN
EquipmentId	Emergency Generator
Capacity/Size	187.5 kVA, 150 kW, 520.5 Amps
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
NATURAL GAS	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
BATTERY PACK	Does not exist
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
BATTERY PACK	Does not exist
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
AREA SMOKE DETECTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
BELL/HORN	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUCT SMOKE DETECTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ELEVATOR RECALL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FAN SHUTDOWN CONTROL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM DIGITAL COMMUNICATOR	Does not exist
FUSED CUTOOUT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
HEAT DETECTOR	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
FIRE ALARM SYSTEM	
HEAT DETECTOR	
Deficiency	No deficiencies recorded
MAGNETIC DOOR HOLDER CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MAIN PANEL	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards Systems Technology
Model	N/A
EquipmentId	Fire Alarm Control Panel
Capacity/Size	12 zones
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
MANUAL PULL STATION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
REMOTE ANNUNCIATOR	Inspected
Display Monitor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
SPRINKLER FLOW/AIR PRESSURE SWITCH	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
STROBE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SUB-PANEL	Does not exist
TAMPER FLOW SWITCH/CHAIN	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Basement
LIGHTING	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
GYMNASIUM	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
LOCAL SOUND SYSTEM	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCOREBOARD	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
THEATER LIGHTING SYSTEM	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
GYMNASIUM	
THEATER LIGHTING SYSTEM	
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
ELEVATOR	Inspected
Condition	5- Poor
Deficiency	STAFF STATION NOT OPERATIONAL
Deficiency Location/Instance	Elevator Cab
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
HOLDING AREA	Does not exist
KITCHEN/WARMING PANTRY	Inspected
Instance	Basement
LIGHTING	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
LAN	Inspected
LOCAL DISTRIBUTION FRAME (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MAIN EQUIPMENT RACK (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 100
Has LAN/Modem access	Yes
LIGHTING	
Instance on Room 100	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
LIBRARY	
LIGHTING	
Lighting Fixture - Fluorescent	
Instance on Room 100	Inspected
Pendant Mounted	
Instance on Room 100	Does not exist
Recessed Mounted	
Instance on Room 100	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 100	Does not exist
Lighting Fixture - HID	
Instance on Room 100	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 100	Does not exist
RACEWAY WITH RECEPTACLES	
Instance on Room 100	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SMART BOARD	
Instance on Room 100	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTING - SECURITY LIGHTS	
Condition	2- Between Good and Fair
Replacement Quantity	44
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not exist
LOCKER ROOM	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Inspected
Alternative Use	No
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Inspected
Alternative Use	No
LIGHTING	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Inspected
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Inspected
Lighting Fixture - Fluorescent	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Inspected
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Inspected
Pendant Mounted	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Does not exist
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Does not exist
Recessed Mounted	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
LOCKER ROOM	
LIGHTING	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Does not exist
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Does not exist
Lighting Fixture - Incandescent	
Instance on Girls Locker Room - Room B12 (in vicinity of Gymnasium)	Does not exist
Instance on Boys Locker Room - Room B22 (in vicinity of Gymnasium)	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
FUSED DISCONNECT SWITCH TYPE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FUSED KNIFE SWITCH TYPE	Does not exist
FUSED TOGGLE SWITCH TYPE	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office -Room 130/130 A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	RAULAND TC2100 / TC2105 / FAX 250
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Room 218	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Instance on Rooms 214, 216	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SCIENCE DEMO ROOM	
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Room 218	Inspected
Instance on Rooms 214, 216	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 218	Inspected
Instance on Rooms 214, 216	Inspected
Pendant Mounted	
Instance on Room 218	Does not exist
Instance on Rooms 214, 216	Does not exist
Recessed Mounted	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 218	Does not exist
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 218	Does not exist
Instance on Rooms 214, 216	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 218	Does not exist
Instance on Rooms 214, 216	Does not exist
POWER SUPPLY	
Instance on Room 218	Inspected
Instance on Rooms 214, 216	Inspected
Instructor Unit	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SCIENCE DEMO ROOM	
POWER SUPPLY	
Instructor Unit	
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PROJECTION SYSTEM	
Instance on Room 218	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SMART BOARD	
Instance on Room 218	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Rooms 214, 216	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance on Rooms 202	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Instance on Room 210	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Rooms 202	Inspected
Instance on Room 210	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 202	Inspected
Instance on Room 210	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SCIENCE LAB	
LIGHTING	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Rooms 202	Does not exist
Instance on Room 210	Does not exist
Recessed Mounted	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Does not exist
Lighting Fixture - HID	
Instance on Rooms 202	Does not exist
Instance on Room 210	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 202	Does not exist
Instance on Room 210	Does not exist
POWER SUPPLY	
Instance on Rooms 202	Inspected
Instance on Room 210	Inspected
Instructor Unit	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 210	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PROJECTION SYSTEM	
Instance on Rooms 202	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 210	Does not exist
SMART BOARD	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SCIENCE LAB	
SMART BOARD	
Instance on Rooms 202	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 210	Does not exist
SCIENCE PREP ROOM	
Instance on Room 206	Inspected
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
EMERGENCY GAS SHUT-OFF VALVE	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY SHUT-OFF POWER	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING	
Instance on Room 206	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 206	Inspected
Pendant Mounted	
Instance on Room 206	Does not exist
Recessed Mounted	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 206	Does not exist
Lighting Fixture - HID	
Instance on Room 206	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 206	Does not exist
POWER SUPPLY	
Instance on Room 206	Inspected
Instructor Unit	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SECURITY	
INTRUSION ALARM	
Central Control Panel	
Instance	Custodian Office
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	ADEMCO VISTA 50P
Deficiency	PANEL NOT OPERATIONAL
Deficiency Location/Instance	Custodian Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SECURITY	
INTRUSION ALARM	
Central Control Panel	
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	
Condition	Inspected
Deficiency	2- Between Good and Fair
Panic Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
Remote Annunciator	
Condition	Inspected
Deficiency	2- Between Good and Fair
Siren/Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
Ultrasonic Sensor	
Condition	Does not exist
IPDVS/CCTV SYSTEM	
Condition	Inspected
Deficiency	1- Good
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Equipment Room-B2A
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Cutler Hammer
Capacity/Size	Main
Source of Capacity/Size	4000 Amps
Installation Year	Nameplate
Source of Installation Year	1999
Deficiency	Documented
SWIMMING POOL	
Condition	Does not exist
SWITCHBOARD	
Water Penetration In Electrical Room?	Inspected
Number of Spares	No
AIR CIRCUIT BREAKER TYPE	
Condition	0
FUSED DISCONNECT SWITCH TYPE	
Condition	Does not exist
Instance	Inspected
Instance Condition	Electrical Equipment Room-B2A
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Cutler Hammer
Capacity/Size	N/A
Source of Capacity/Size	4000 Amps total, 3 sections
Installation Year	Service Switch Size
Source of Installation Year	1999
Deficiency	Documented
Deficiency Quantity	SWITCHBOARD ID IS MISSING
Quantity Uom	1
Potential Action	EACH
Urgency of Action	MAINTENANCE
	PRIORITY 2

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Electrical Inspection

M506

Question	Response
SWITCHBOARD	
FUSED DISCONNECT SWITCH TYPE	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUSED KNIFE SWITCH TYPE	Does not exist
MOLDED CASE CIRCUIT BREAKER TYPE	Does not exist
TELEPHONE	Inspected
PBX/INTERCOM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
STANDARD	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
LIGHTING	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist