

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

School: **THURGOOD MARSHALL ACAD. - M, 200-214 WEST 135TH STREET, MANHATTAN, NY, 10030**

InspectionId	Inspection Type	Time In	Last Edited
1196008	ELECTRICAL	2008-11-21 10:00AM	2009-06-17 01:19PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Electrical Systems Years: 2003

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	78,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance	Basement
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
COMPUTER LAB	Inspected
Instance	Room 112
Has LAN/Modem access	Yes
Power Panel?	No
Lighting	
Instance on Room 112	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 112	Inspected
Pendant Mounted	
Instance on Room 112	Does not exist
Recessed Mounted	
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 112	Does not exist
Lighting Fixture - HID	
Instance on Room 112	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 112	Does not exist
Raceway With Receptacles	
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	Siemens
EquipmentId	Service Disconnect
Capacity/Size	1200 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	Siemens
EquipmentId	Service Disconnect
Capacity/Size	4000 Amps
Installation Year	2003
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
ELECTRIC SERVICE SWITCH	
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	Siemens
EquipmentId	Switchboard 1600 SW
Capacity/Size	1600 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Inspected
Automatic Transfer Switch (ATS)	
	Inspected
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	ATS-1
Capacity/Size	70 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	ATS-2
Capacity/Size	150 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Room 0113 A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	ATS-4
Capacity/Size	70 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Room 016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	ATS-6
Capacity/Size	150 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Room 016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Firetrol

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
EquipmentId	Fire Pump Power Transfer Switch
Capacity/Size	30 HP
Installation Year	2003
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	24V Battery Float Charger
Capacity/Size	10 AmpsDC, 24 VDC
Installation Year	2003
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins
EquipmentId	Emergency Generator
Capacity/Size	375 kVA, 300 kW, 1139.5 Amps
Installation Year	2003
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Elevator Recall	
Condition	Inspected
Deficiency	2- Between Good and Fair
Fan Shutdown Control	
Condition	Inspected
Deficiency	2- Between Good and Fair
Fire Alarm Digital Communicator	
Instance	Inspected
Instance Condition	Room 016
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	ADEMCO
Capacity/Size	Communicator
Installation Year	2 zones
Deficiency	2003
Fused Cutout Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Heat Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Magnetic Door Holder Contactor	
Condition	Does not exist
Main Panel	
Condition	Inspected
Bell At Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Fire Alarm Control Panel (Electronic)	
Instance	Inspected
Instance Condition	Main Entrance
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
Model	Edwards
EquipmentId	EST2
Capacity/Size	Fire Alarm Control Panel
Installation Year	32 zones
Deficiency	2003
Fire Alarm Control Panel (Standard)	
Condition	Does not exist
Manual Pull Station	
Condition	Inspected
Deficiency	2- Between Good and Fair
Remote Annunciator	
Condition	Inspected
Display Monitor	
Condition	Inspected
Deficiency	3- Fair
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Room 017
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	VIKING
Model	E-1
EquipmentId	Pre Action Control Panel
Capacity/Size	16 zones
Installation Year	2003
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Sixth Floor
Lighting	
Instance on Sixth Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Sixth Floor	Does not exist
Lighting Fixture - HID	
Instance on Sixth Floor	Inspected
Pendant Mounted	
Instance on Sixth Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Sixth Floor	Does not exist
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Surface Mounted	
Instance on Sixth Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Sixth Floor	Does not exist
Local Sound System	
Instance on Sixth Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Sixth Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Sixth Floor	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
	Inspected
Instance	Room 311
Has LAN/Modem access	Yes
Lighting	
Instance on Room 311	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 311	Inspected
Pendant Mounted	
Instance on Room 311	Does not exist
Recessed Mounted	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 311	Does not exist
Lighting Fixture - HID	
Instance on Room 311	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 311	Does not exist
Raceway With Receptacles	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	24
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	Boys Room 601
Alternative Use	No
Instance	Girls Room 604
Alternative Use	No
Lighting	
Instance on Boys Room 601	Inspected
Instance on Girls Room 604	Inspected
Lighting Fixture - Fluorescent	
Instance on Boys Room 601	Inspected
Instance on Girls Room 604	Inspected
Pendant Mounted	
Instance on Boys Room 601	Does not exist
Instance on Girls Room 604	Does not exist
Recessed Mounted	
Instance on Boys Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Girls Room 604	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Boys Room 601	Does not exist
Instance on Girls Room 604	Does not exist
Lighting Fixture - HID	
Instance on Boys Room 601	Does not exist
Instance on Girls Room 604	Does not exist
Lighting Fixture - Incandescent	
Instance on Boys Room 601	Does not exist
Instance on Girls Room 604	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
MOTOR STARTER/CONTACTOR	
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Instance	Room 213 A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter TC2100
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance	Room 403
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance	Room 412
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Instance	Room 415
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

M970

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 403	Inspected
Instance on Room 412	Inspected
Instance on Room 415	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 403	Inspected
Instance on Room 412	Inspected
Instance on Room 415	Inspected
Pendant Mounted	
Instance on Room 403	Does not exist
Instance on Room 412	Does not exist
Instance on Room 415	Does not exist
Recessed Mounted	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 403	Does not exist
Instance on Room 412	Does not exist
Instance on Room 415	Does not exist
Lighting Fixture - HID	
Instance on Room 403	Does not exist
Instance on Room 412	Does not exist
Instance on Room 415	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 403	Does not exist
Instance on Room 412	Does not exist
Instance on Room 415	Inspected
Pendant Mounted	
Instance on Room 415	Does not exist
Recessed Mounted	
Instance on Room 415	Does not exist
Surface Mounted	
Instance on Room 415	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 403	Inspected
Instance on Room 412	Does not exist
Instance on Room 415	Does not exist
Instructor Unit	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Meter Demonstration Unit	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance	Inspected
Instance	Room 407
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Instance	Room 411
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 407	Inspected
Instance on Room 411	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 407	Inspected
Instance on Room 411	Inspected
Pendant Mounted	
Instance on Room 407	Does not exist
Instance on Room 411	Does not exist
Recessed Mounted	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 407	Does not exist
Instance on Room 411	Does not exist
Lighting Fixture - HID	
Instance on Room 407	Does not exist
Instance on Room 411	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 407	Inspected
Instance on Room 411	Inspected

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

M970

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on Room 407	Does not exist
Instance on Room 411	Does not exist
Recessed Mounted	
Instance on Room 407	Does not exist
Instance on Room 411	Does not exist
Surface Mounted	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 407	Inspected
Instance on Room 411	Does not exist
Instructor Unit	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance	Inspected
Has LAN/Modem access	Room 409
Power Panel?	Yes
Alternative Use	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 409	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 409	Inspected
Pendant Mounted	
Instance on Room 409	Does not exist
Recessed Mounted	
Instance on Room 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

M970

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 409	Does not exist
Lighting Fixture - HID	
Instance on Room 409	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 409	Does not exist
Power Supply	
Instance on Room 409	Does not exist
SECURITY	Inspected
Replacement Quantity	78,000
Replacement Uom	S.F.
Intrusion Alarm	Inspected
Central Control Panel	Inspected
Instance	Custodians Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	VISTA 128B
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Does not exist
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	EM-PP-HVAC-R
Capacity/Size	400 Amps total, 1 section
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
EquipmentId	N/A
Capacity/Size	1200 Amps total, 3 sections
Installation Year	2003
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	N/A
Capacity/Size	1200 Amps total, 2 sections
Installation Year	2003
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	SS1
Capacity/Size	4000 Amps total, 3 sections
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Room 016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	DP-HV-EM-1
Capacity/Size	400 Amps total, 1 section
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Fed From Generator
Capacity/Size	400 Amps total, 1 section
Installation Year	2003
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Inspected
Dry Type	Inspected
Instance	Penthouse
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	OLSUN
EquipmentId	N/A
Capacity/Size	15 kVA
Installation Year	2003
Deficiency	TRANSFORMER ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Elevator Machine Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	NYC ELEV ID# 1P42745
Capacity/Size	27 kVA
Installation Year	2003
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

M970

Question	Response
TRANSFORMER	
Dry Type	
Instance	Elevator Machine Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	NYC ELEV ID# 1P42744
Capacity/Size	27 kVA
Installation Year	2003
Deficiency	No deficiencies recorded
Instance	Electrical Room 013 Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	OLSUN
EquipmentId	N/A
Capacity/Size	1000 kVA
Installation Year	2003
Deficiency	TRANSFORMER ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room 016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	OLSUN
EquipmentId	N/A
Capacity/Size	16 kVA
Installation Year	2003
Deficiency	TRANSFORMER ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room 016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	OLSUN
EquipmentId	N/A
Capacity/Size	75 kVA
Installation Year	2003
Deficiency	TRANSFORMER ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

M970

Question	Response
TRANSFORMER	
Liquid Type	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Master Antenna System	Does not exist