

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Mechanical Inspection**

**Q485**

School: **GROVER CLEVELAND HS - Q, 21-27 HIMROD STREET, QUEENS, NY, 11385**

InspectionId	Inspection Type	Time In	Last Edited
1264175	MECHANICAL	2009-06-15 11:40AM	2009-06-24 01:32PM

**Asset Data**

Question	Answer
Heating Plant Oil Number	2
Have any Systems/Major Building Components been upgraded?	Systems: Boiler # 1 re-tube . Years: 2005 Systems: DX split system Years: 2006 Systems: DX split Years: 2008

**Priority Condition**

No condition recorded

**Inspection**

Question	Response
<b>MECHANICAL</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Piping</b>	Does not exist
<b>Condenser Water Pump</b>	Does not exist
<b>Cooling Coils in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	UP TO 5 TONS:DEFECTIVE UNIT
Deficiency Location/Instance	MDF room #210
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Outdoor Unit</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Packaged / Rooftop Unit</b>	Does not exist
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not exist
<b>Window Type A/C</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Various locations
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	
Deficiency	No deficiencies recorded
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>Damper Actuator</b>	Does not exist
<b>DDC Computer</b>	Does not exist
<b>Local Control Panel</b>	Does not exist
<b>Pneumatic PRV Station</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Pneumatic Tubing</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Throughout (Except /Fan Rooms)
Deficiency Quantity	2,500
Quantity Uom	LF
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Refrigerated Air Dryer</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Air Compressor</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Temperature Control Thermostat</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Throughout the school
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Temperature Control Zone Valve</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Pool mechanical equipment space
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Terminal Unit Thermostatic Valve</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiters</b>	Does not exist
<b>Elevators</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Escalators</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>CONVEYING</b>	
<b>Non-auditorium Handicap Lift</b>	Does not exist
<b>Sidewalk / Ash Hoist</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Does not exist
<b>Hydraulic/Pneumatic Booster System</b>	Inspected
<b>Domestic Cold Water Tank</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Pressure Booster Pump</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Water Pressure Booster - Compressor</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Water Service</b>	Inspected
<b>Service Piping (Water Main)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Water Main - Double Check Valve</b>	Does not exist
<b>Water Main - RPZ</b>	Does not exist
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Circulating Pump</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Gas Fired Domestic Water Heater</b>	
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size	600 MBH /600 Gal.
Installation Year	1990
Deficiency	DEFECTIVE UNIT
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O.Smith
EquipmentId	N/A
Capacity/Size	275 MBH /100 Gal.
Installation Year	2004
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>House Trap</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Interior Floor Drain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Interior Storm Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage / Waste Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Vent Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>EMERGENCY GENERATOR</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Boiler Room - Eye Wash</b>	Does not exist
<b>Janitor Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	3- Fair
Deficiency	CLOGGED/DIRTY/LEAKING
Deficiency Location/Instance	Basement /cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Inspected
Condition	3- Fair
Alternative Use	No
Deficiency	No deficiencies recorded
<b>Sink And Fountain Combo Unit</b>	Does not exist
<b>Toilet</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Vent</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Pressure Booster</b>	Does not exist
<b>HEATING</b>	Inspected
<b>Baseboard/Fin Tube</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Heating Coils In Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan Rooms
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	Fan room above library / leaks
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement fan room / auditorium blower
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Hydronic Heating</b>	Does not exist
<b>Radiator / Convectector</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	175
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Fan rooms
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>MER Steam and Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Fan rooms
Deficiency Quantity	600
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>MER Steam and Condensate Piping</b>	
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	3,000
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return System</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Pool mechanical area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Throughout
Deficiency Quantity	3,000
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Terminal Unit Thermostatic Trap</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>STEAM SUPPLIED BY EXTERNAL SOURCES</b>	
Condition	Does not exist
<b>Terminal Fan Coil Unit</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Unit Heater/Cabinet Heater</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	
Condition	Inspected
Replacement Quantity	27,504
Replacement Uom	MBH

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	Inspected
<b>Boiler Blowdown/Piping System</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Breeching</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Damper (In Breeching)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	Inspected
<b>Boiler Feedwater Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Tank</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Feedwater Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	Does not exist
<b>Boiler Gas Burner</b>	Does not exist
<b>Boiler Gas/Oil Burner</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Header Valve</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	Inspected
<b>Double Check Valves</b>	Does not exist
<b>RPZ</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Oil Burner</b>	Does not exist
<b>Boiler Room Steam And Condensate Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Safety Valve</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Burner Control Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler System</b>	Inspected
<b>Coal-fired Boiler</b>	Does not exist
<b>Hot Water Boiler</b>	Does not exist
<b>Modular Boiler</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Mechanical Inspection**

**Q485**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Steam Boiler</b>	Inspected
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	6,876
Instance Quantity Uom	MBH
Manufacturer	BURNHAM
EquipmentId	8555-1
Capacity/Size	8857 MBH - Gross
Installation Year	1990
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	6,876
Instance Quantity Uom	MBH
Manufacturer	BURNHAM
EquipmentId	8555-2
Capacity/Size	8857 MBH -Gross
Installation Year	1990
Deficiency	PLUGGED TUBES
Deficiency Location/Instance	Basement
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	6,876
Instance Quantity Uom	MBH
Manufacturer	BURNHAM
EquipmentId	8555-3
Capacity/Size	8857 MBH - Gross
Installation Year	1990
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	6,876
Instance Quantity Uom	MBH
Manufacturer	BURNHAM
EquipmentId	8555-4
Capacity/Size	8857 MBH-Gross
Installation Year	1990
Deficiency	No deficiencies recorded
<b>Fuel Systems</b>	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE ACTUATOR
Deficiency Location/Instance	Boiler room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>HEATING PLANT</b>	
<b>Fuel Systems</b>	
<b>Boiler Fresh Air Louver/Damper</b>	
Violations	No violations recorded
<b>CO/Gas Leak Detection</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Heater</b>	Does not exist
<b>Fuel Oil Level Gauge</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Tank</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Transfer Pump</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Gas Trains And Vent At The Boiler</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Oil Leak Detector In Tank Room</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Overfill Alarm By Oil Fill</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	Inspected
Instance	Basement
<b>CO Detector</b>	
Instance on Basement	Does not exist
<b>CO/Gas Leak Detector</b>	
Instance on Basement	Does not exist
<b>Gas System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>Hood Exhaust Ductwork</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on Basement	Inspected
Instance	Kitchen
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PYROCHIEM
EquipmentId	N/A
Capacity/Size	3 Gal.
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	
Instance on Basement	Does not exist
<b>Kitchen Sink</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
Instance	Inspected
Instance	Room # 139 ,141, 231,238,338 ,341 ,343
Alternative Use	No
Instance	Room # 138 ,240
Alternative Use	Yes
Instance	Room # 229
Alternative Use	Yes
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room # 139 ,141, 231,238,338 ,341 ,343	Does not exist
Instance on Room # 138 ,240	Does not exist
Instance on Room # 229	Does not exist
<b>Emergency Shower</b>	
Instance on Room # 139 ,141, 231,238,338 ,341 ,343	Does not exist
Instance on Room # 138 ,240	Does not exist
Instance on Room # 229	Does not exist
<b>Eye Wash</b>	
Instance on Room # 139 ,141, 231,238,338 ,341 ,343	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 138 ,240	Does not exist
Instance on Room # 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Laboratory Hood</b>	
Instance on Room # 139 ,141, 231,238,338 ,341 ,343	Does not exist
Instance on Room # 138 ,240	Does not exist
Instance on Room # 229	Does not exist
<b>Laboratory Sink</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Laboratory Sink</b>	
Instance on Room # 139 ,141, 231,238,338 ,341 ,343	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 138 ,240	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room # 138, 240
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room # 229	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room # 229
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>SCIENCE LAB</b>	
Instance	Inspected
Alternative Use	Room # 235
Instance	No
Alternative Use	No
Instance	Room # 241
Alternative Use	No
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>CO Detector</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>CO/Gas Leak Detector</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>Emergency Shower</b>	
Instance on Room # 235	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE SHOWER
Deficiency Location/Instance	Room # 235
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room # 241	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Eye Wash</b>	
Instance on Room # 235	Inspected
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Eye Wash</b>	
Deficiency	No deficiencies recorded
Instance on Room # 241	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>Laboratory Hood</b>	
Instance on Room # 235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 241	Does not exist
<b>Laboratory Sink</b>	
Instance on Room # 235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 241	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	
Instance on Room # 235	Does not exist
Instance on Room # 241	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance	Room # 339
Alternative Use	Yes
Instance	Room # 140A
Alternative Use	No
Instance	Room # 238A
Alternative Use	No
Instance	Room # 239
Alternative Use	No
<b>Acid Waste Neutralizing Tank</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>Emergency Shower</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>Eye Wash</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 238A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Eye Wash</b>	
Instance on Room # 239	Does not exist
<b>Hood Exhaust Ductwork</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>Laboratory Hood</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>Laboratory Sink</b>	
Instance on Room # 339	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room # 339
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room # 140A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 238A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room # 239	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	
Instance on Room # 339	Does not exist
Instance on Room # 140A	Does not exist
Instance on Room # 238A	Does not exist
Instance on Room # 239	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Deluge Valve</b>	Does not exist
<b>Fire Booster Pump Assembly</b>	Does not exist
<b>Roof Tank</b>	Does not exist
<b>Siamese Connection</b>	Does not exist
<b>Sprinkler Alarm Valve Assembly</b>	Does not exist
<b>Sprinkler Head</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Sprinkler Piping</b>	
Deficiency Location/Instance	Boiler Room / leaks
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Standpipe System</b>	Does not exist
<b>Water Gong</b>	Does not exist
<b>SWIMMING POOL</b>	Inspected
Instance	Basement
<b>Filter</b>	
Replacement Quantity	3
Replacement Uom	EACH
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heater</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Pumps</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>VENTILATION</b>	Inspected
<b>Duct- Register / Diffuser</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Exhaust Fan</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Basement fan room / house exhaust
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fire / Smoke Damper</b>	Does not exist
<b>Heating And Ventilating Unit</b>	Does not exist
<b>Metal Ductwork</b>	Inspected
Condition	3- Fair
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	Fan rooms
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Supply Fan</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

***Mechanical Inspection***

**Q485**

<b>Question</b>	<b>Response</b>
<b>VENTILATION</b>	
<b>Supply Fan</b>	
Deficiency Location/Instance	Basement fan room /shop blower
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Unit Ventilator</b>	
Condition	Inspected
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Class rooms and other locations
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded