

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

School: AVIATION HS - Q, 45-30 36 STREET, QUEENS, NY, 11101

InspectionId	Inspection Type	Time In	Last Edited
1250026	ELECTRICAL	2008-12-30 08:24AM	2009-01-16 02:49PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: HID Lights in Gym and Auditorium Years: 2007 Systems: LAN, Emerg.& Exit lights partial, Science (Labs, Demo & Prep) Rooms excluding lights. Years: 2006 Systems: Intrusion Alarm Years: 2004 Systems: Telephone, Intercom Years: 2000 Systems: PA (except clocks) Years: 1995 Systems: CCTV Years: 2001

Priority Condition

Condition Description	Component Affected	Location Description	Person(s) Notified
Water penetration into light fixture from drain pipe	Light fixture	Room 612	ERNIE VIDA (Handyman)

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance	2nd floor
House Lighting	
Instance on 2nd floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd floor	Inspected
Pendant Mounted	
Instance on 2nd floor	Does not exist
Recessed Mounted	
Instance on 2nd floor	Does not exist
Surface Mounted	
Instance on 2nd floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd floor	Inspected
Pendant Mounted	
Instance on 2nd floor	Does not exist
Recessed Mounted	
Instance on 2nd floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd floor	Does not exist
Local Sound System	
Instance on 2nd floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
AUDITORIUM	
Local Sound System	
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd floor	Does not exist
Theater Lighting System	
Instance on 2nd floor	Inspected
Dimming System	
Instance on 2nd floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 2nd floor	Inspected
Instance Condition	5- Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	154
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Replacement Quantity	262,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	
Instance	Ground Floor, for Students
Instance	Ground Floor, for Teachers
Lighting	
Instance on Ground Floor, for Students	Inspected
Instance on Ground Floor, for Teachers	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor, for Students	Inspected
Instance on Ground Floor, for Teachers	Inspected
Pendant Mounted	
Instance on Ground Floor, for Students	Does not exist
Instance on Ground Floor, for Teachers	Does not exist
Recessed Mounted	
Instance on Ground Floor, for Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor, for Teachers	Does not exist
Surface Mounted	
Instance on Ground Floor, for Students	Does not exist
Instance on Ground Floor, for Teachers	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - HID	
Instance on Ground Floor, for Students	Does not exist
Instance on Ground Floor, for Teachers	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor, for Students	Does not exist
Instance on Ground Floor, for Teachers	Does not exist
Local Sound System	
Instance on Ground Floor, for Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor, for Teachers	Does not exist
CAFETERIA/MULTIPURPOSE ROOM	
	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	7

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q610

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPUTER LAB	Inspected
Instance	Rooms: 612, 530, 238
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Rooms: 612, 530, 238	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms: 612, 530, 238	Inspected
Pendant Mounted	
Instance on Rooms: 612, 530, 238	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms: 612, 530, 238	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms: 612, 530, 238	Does not exist
Lighting Fixture - HID	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - HID	
Instance on Rooms: 612, 530, 238	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms: 612, 530, 238	Does not exist
Raceway With Receptacles	
Instance on Rooms: 612, 530, 238	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical Room, Basement
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric Co.
Model	Lexington Electric Co.
EquipmentId	Section "A" and Section "B"
Capacity/Size	3000 Amps
Installation Year	1957
Deficiency	SWITCH NAME PLATE IS MISSING
Deficiency Location/Instance	Electrical Room, Basement
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCH BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Electrical Room, Basement
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
EXIT LIGHT	
Battery Pack	
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Replacement Quantity	262,000
Replacement Uom	S.F.
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm
Capacity/Size	14 circuits
Installation Year	1957
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Punch Register	
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
Model	Faraday
EquipmentId	Elevator Recall Control Panel
Capacity/Size	12 zones
Installation Year	1991
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Capacity/Size	2 circuis
Installation Year	1957
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Hanger
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Capacity/Size	2 circuits
Installation Year	1957
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Hanger
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Deluge Rectifier
Capacity/Size	2 circuits
Installation Year	1957
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Register Control Board
Capacity/Size	2 circuits
Installation Year	1957
Deficiency	PANEL BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Ground Floor
Lighting	
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Does not exist
Lighting Fixture - HID	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist
Recessed Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
GYMNASIUM	
Local Sound System	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Ground Floor	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
Condition	Inspected
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
LIBRARY	
	Inspected
Instance	Room 234
Has LAN/Modem access	Yes
Lighting	
Instance on Room 234	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 234	Inspected
Pendant Mounted	
Instance on Room 234	Does not exist
Recessed Mounted	
Instance on Room 234	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q610

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 234	Does not exist
Lighting Fixture - HID	
Instance on Room 234	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 234	Does not exist
Raceway With Receptacles	
Instance on Room 234	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	3- Fair
Replacement Quantity	65
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	Ground Floor (boys & girls)
Alternative Use	No
Lighting	
Instance on Ground Floor (boys & girls)	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor (boys & girls)	Inspected
Pendant Mounted	
Instance on Ground Floor (boys & girls)	Does not exist
Recessed Mounted	
Instance on Ground Floor (boys & girls)	Does not exist
Surface Mounted	
Instance on Ground Floor (boys & girls)	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Ground Floor (boys & girls)	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor (boys & girls)	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Mechanical Spacs
Deficiency Quantity	45
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
MOTOR STARTER/CONTACTOR	
Violations	No violations recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Gym; Cafeteria, Auditorium, Kitchen, Basement
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Corridors, Workshops, Mechanical spaces
Deficiency Quantity	78
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	262,000
Replacement Uom	S.F.
Instance	Room 344
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	BOGAN, Rauland
Deficiency	MASTER CLOCK BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	All around the building
Deficiency Quantity	50
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
PUBLIC ADDRESS SYSTEM	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
Instance	Inspected
Has LAN/Modem access	Rooms: 637, 635, 631, 537, 536, 535
Power Panel?	Yes
Alternative Use	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Pendant Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Does not exist
Surface Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Pendant Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Does not exist
Recessed Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Does not exist
Surface Mounted	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Power Supply	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instructor Unit	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	1- Good

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q610

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms: 637, 635, 631, 537, 536, 535	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE LAB	
	Inspected
Instance	Rooms: 630, 634
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms: 630, 634	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms: 630, 634	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms: 630, 634	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms: 630, 634	Inspected
Pendant Mounted	
Instance on Rooms: 630, 634	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms: 630, 634	Does not exist
Surface Mounted	
Instance on Rooms: 630, 634	Does not exist
Lighting Fixture - HID	
Instance on Rooms: 630, 634	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms: 630, 634	Does not exist
Power Supply	
Instance on Rooms: 630, 634	Inspected
Instructor Unit	
Instance on Rooms: 630, 634	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms: 630, 634	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms: 630, 634	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
	Inspected
Instance	Rooms: 628, 636
Has LAN/Modem access	No

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
SCIENCE PREP ROOM	
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms: 628, 636	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms: 628, 636	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms: 628, 636	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms: 628, 636	Inspected
Pendant Mounted	
Instance on Rooms: 628, 636	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms: 628, 636	Does not exist
Surface Mounted	
Instance on Rooms: 628, 636	Does not exist
Lighting Fixture - HID	
Instance on Rooms: 628, 636	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms: 628, 636	Does not exist
Power Supply	
Instance on Rooms: 628, 636	Does not exist
SECURITY	
Replacement Quantity	262,000
Replacement Uom	S.F.
Intrusion Alarm	
Inspected	Inspected
Central Control Panel	
Inspected	Inspected
Instance	Custodian's office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Ademco, VISTA-128B
Deficiency	No deficiencies recorded
Infrared Sensor	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Does not exist	Does not exist
IPDVS/CCTV System	
Inspected	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
SECURITY	
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric Co.
EquipmentId	N/A
Capacity/Size	3000 Amps total, 4 sections
Installation Year	1957
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Fan Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	SubDist. Panel A and Sub Dist. Panel B
Capacity/Size	N/A, 2 sections
Installation Year	1957
Deficiency	SWITCHBOARD BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q610

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room, Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard Co.
EquipmentId	N/A
Capacity/Size	600 Amps total, 1 section
Installation Year	1996
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room, Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard Co.
EquipmentId	DP-EM
Capacity/Size	400 Amps total, 3 sections
Installation Year	1996
Deficiency	No deficiencies recorded
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q610

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist