

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

School: **GATEWAY TO HEALTH & SCI (DASNY)-Q, 150-91 87TH ROAD, QUEENS, NY, 11433**

InspectionId	Inspection Type	Time In	Last Edited
1247132	ELECTRICAL	2009-06-08 12:00PM	2009-06-17 02:33PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: LAN, Intercom System- Elevator Years: 2006 Systems: Other Electrical Systems and Components Years: 1998

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	55,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance	Second Floor- Room 216
Lighting	
Instance on Second Floor- Room 216	Inspected
Lighting Fixture - Fluorescent	
Instance on Second Floor- Room 216	Inspected
Pendant Mounted	
Instance on Second Floor- Room 216	Does not exist
Recessed Mounted	
Instance on Second Floor- Room 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Second Floor- Room 216	Does not exist
Lighting Fixture - HID	
Instance on Second Floor- Room 216	Does not exist
Lighting Fixture - Incandescent	
Instance on Second Floor- Room 216	Does not exist
Local Sound System	
Instance on Second Floor- Room 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
COMPUTER LAB	Inspected
Instance	Room 418
Has LAN/Modem access	Yes
Power Panel?	Yes
Lighting	
Instance on Room 418	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 418	Inspected
Pendant Mounted	
Instance on Room 418	Does not exist
Recessed Mounted	
Instance on Room 418	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 418	Does not exist
Lighting Fixture - HID	
Instance on Room 418	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 418	Does not exist
Raceway With Receptacles	
Instance on Room 418	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ELECTRIC SERVICE SWITCH	Inspected
Instance	Electrical Meter Room- Room 122
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pringle
Model	Pringle
EquipmentId	SSW-1
Capacity/Size	3000 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Meter Room- Room 122
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
EquipmentId	ATS 1
Capacity/Size	600 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Pump Room- Room B14A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Master Control Systems, Inc
EquipmentId	Automatic Transfer Switch
Capacity/Size	20 HP
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Boiler Room- Room B4
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS EPP-BR
Capacity/Size	400 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room- Room 122
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel
EquipmentId	ATS 1
Capacity/Size	70 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Penthouse- Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel
EquipmentId	Automatic Battery Charger
Capacity/Size	10 AmpsDC, 26 VDC
Installation Year	1998
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Penthouse- Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel
EquipmentId	Emergency Generator
Capacity/Size	288 kVA, 230 kW, 798 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Relay Test Switch	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Connected To Emergency Generator System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Light/Exit Light Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Boys Locker Room- Room 102 and Room B14
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	55,000
Replacement Uom	S.F.
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Pump Room- Room B14A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Silent Knight
EquipmentId	Control Communicator
Capacity/Size	4 zones
Installation Year	1998
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Lobby- Near General Office (Room 221)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards Systems Technology
Model	EST
EquipmentId	Fire Alarm Control
Capacity/Size	16 zones
Installation Year	1998
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance	Basement- Room B15
Lighting	
Instance on Basement- Room B15	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement- Room B15	Inspected
Pendant Mounted	
Instance on Basement- Room B15	Does not exist
Recessed Mounted	
Instance on Basement- Room B15	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement- Room B15	Does not exist
Lighting Fixture - HID	
Instance on Basement- Room B15	Inspected
Pendant Mounted	
Instance on Basement- Room B15	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement- Room B15	Does not exist
Surface Mounted	
Instance on Basement- Room B15	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement- Room B15	Does not exist
Local Sound System	
Instance on Basement- Room B15	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Basement- Room B15	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on Basement- Room B15	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN/WARMING PANTRY	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance	Room 316
Has LAN/Modem access	Yes
Lighting	
Instance on Room 316	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 316	Inspected
Pendant Mounted	
Instance on Room 316	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 316	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 316	Does not exist
Lighting Fixture - HID	
Instance on Room 316	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 316	Does not exist
Raceway With Receptacles	
Instance on Room 316	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTING - EXTERIOR SECURITY	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	15
Replacement Uom	EACH
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Inspected
Instance	Boys- Room 102, and Girls- Room 116
Alternative Use	No
Lighting	
Instance on Boys- Room 102, and Girls- Room 116	Inspected
Lighting Fixture - Fluorescent	
Instance on Boys- Room 102, and Girls- Room 116	Inspected
Pendant Mounted	
Instance on Boys- Room 102, and Girls- Room 116	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Boys- Room 102, and Girls- Room 116	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
LOCKER ROOM/SHOWER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Boys- Room 102, and Girls- Room 116	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Boys- Room 102, and Girls- Room 116	Does not exist
Lighting Fixture - Incandescent	
Instance on Boys- Room 102, and Girls- Room 116	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	55,000
Replacement Uom	S.F.
Instance	Principal Office- Inside Room 221
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance	Room 426 and Room 424
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 426 and Room 424	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 426 and Room 424	Inspected
Pendant Mounted	
Instance on Room 426 and Room 424	Does not exist
Recessed Mounted	

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q680

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 426 and Room 424	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 426 and Room 424	Does not exist
Power Supply	
Instance on Room 426 and Room 424	Inspected
Instructor Unit	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 426 and Room 424	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance	Inspected
Has LAN/Modem access	Room 322 and Room 318
Power Panel?	Yes
Alternative Use	Yes
	No
Emergency Gas Shut-Off Valve	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 322 and Room 318	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 322 and Room 318	Inspected
Pendant Mounted	
Instance on Room 322 and Room 318	Does not exist
Recessed Mounted	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 322 and Room 318	Does not exist

NYC Department of Education
 Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q680

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 322 and Room 318	Does not exist
Power Supply	
Instance on Room 322 and Room 318	Inspected
Instructor Unit	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 322 and Room 318	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance	Room 320
Has LAN/Modem access	No
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 320	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 320	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 320	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 320	Inspected
Pendant Mounted	
Instance on Room 320	Does not exist
Recessed Mounted	
Instance on Room 320	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 320	Does not exist
Lighting Fixture - HID	
Instance on Room 320	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 320	Does not exist
Power Supply	
Instance on Room 320	Does not exist
SECURITY	
Replacement Quantity	55,000
Replacement Uom	S.F.
Intrusion Alarm	
Central Control Panel	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
SECURITY	
Intrusion Alarm	
Central Control Panel	
Instance	Custodian Office- Room 119
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Ademco
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	Inspected
Deficiency	2- Between Good and Fair
Panic Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
Remote Annunciator	
Condition	Inspected
Deficiency	2- Between Good and Fair
Siren/Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
Ultrasonic Sensor	
Condition	Does not exist
IPDVS/CCTV System	
Condition	Does not exist
SWIMMING POOL	
Condition	Does not exist
SWITCHBOARD	
Air Circuit Breaker Type	
Condition	Does not exist
Fused Disconnect Switch Type	
Instance	Inspected
Instance	Penthouse- Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Challenger- Power Master
EquipmentId	RFPP Sec 1
Capacity/Size	600 Amps total, 1 section
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room- Room 122
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Challenger- Power Master
EquipmentId	MDB Section 1 & MDB Section 2
Capacity/Size	3000 Amps total, 2 sections
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room- Room 122
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Challenger- Power Master
EquipmentId	EDP
Capacity/Size	800 Amps total, 1 section
Installation Year	1998
Deficiency	No deficiencies recorded
Instance	Penthouse- Roof

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

Q680

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Challenger- Power Master
EquipmentId	RFPP Sec II
Capacity/Size	800 Amps total, 1 section
Installation Year	1998
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable Service	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Master Antenna System	Inspected
Condition	3- Fair
Deficiency	ANTENNA NOT IN USE
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2008-2009

Electrical Inspection

Q680

Question	Response
TV SYSTEM	
Master Antenna System	
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded