

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

School: **P.S. 811 (OLD I84) - BRONX, 1434 LONGFELLOW AVENUE, BRONX, NY, 10459**

InspectionId	Inspection Type	Time In	Last Edited
1250138	ELECTRICAL	2009-05-06 09:08AM	2009-05-13 11:57AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: External Security Lights Years: 2008 ( 9 on the roof), 2003 (20 on the walls) Systems: Fire Alarm System Years: Under Construction Systems: PA, LAN Years: 2007 Systems: Telephone, Intrusion Alarm Years: 2004 Systems: Emergency / Exit Lights partially Years: 2003 Systems: Panel Boards partly Years: 2002 Systems: Local Sound System, Fluorescent lights partly Years: 1999 Systems: Switchboard Years: 1998 Systems: Emergency Generator, ATS and Battery Charger Years: 1993

**Priority Condition**

No condition recorded

**Inspection**

Question	Response
<b>ELECTRICAL</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance	3rd floor
<b>House Lighting</b>	
Instance on 3rd floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 3rd floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 3rd floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 3rd floor	Inspected
<b>Pendant Mounted</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Recessed Mounted</b>	
Deficiency Quantity	78
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Local Sound System</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 3rd floor	Inspected
<b>Dimming System</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Theater Lighting</b>	
Instance on 3rd floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	66
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
	Inspected
Condition	3- Fair
Replacement Quantity	176,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
	Inspected
Instance	1st floor
<b>Lighting</b>	
Instance on 1st floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	174
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 1st floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA/MULTIPURPOSE ROOM</b>	
	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1,088
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	122
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	376
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	126
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE LAMP NOT OPERATIONAL/MISSING
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	INSTALL NEW LAMP
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	88
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>COMPUTER LAB</b>	Inspected
Instance	Room 404
Has LAN/Modem access	Yes
Power Panel?	No
Instance	Room 325
Has LAN/Modem access	Yes
Power Panel?	Yes
<b>Lighting</b>	
Instance on Room 404	Inspected
Instance on Room 325	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 404	Inspected
Instance on Room 325	Inspected
<b>Pendant Mounted</b>	
Instance on Room 404	Inspected
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 325	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on Room 404	Does not exist
Instance on Room 325	Does not exist
<b>Surface Mounted</b>	
Instance on Room 404	Does not exist
Instance on Room 325	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 404	Does not exist
Instance on Room 325	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 404	Does not exist
Instance on Room 325	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 404	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 325	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>ELECTRIC SERVICE SWITCH</b>	
Instance	Inspected
Instance	Electrical Room, Basement.
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pringle Elect. Mfg. Co.
Model	Pringle Elect. Mfg. Co.
EquipmentId	SERVICE SWITCH
Capacity/Size	4000 Amps
Installation Year	1998
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
Does not exist	
<b>EMERGENCY GENERATOR SET</b>	
Inspected	
<b>Automatic Transfer Switch (ATS)</b>	
Inspected	
Instance	Emergency Generator Room

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	KOHLER
EquipmentId	Transfer Switch
Capacity/Size	800 Amps.
Installation Year	1993
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Emergency Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	KOHLER
EquipmentId	Charger
Capacity/Size	10 Amps DC, 24V DC.
Installation Year	1993
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Emergency Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	KOHLER
EquipmentId	GENERATOR
Capacity/Size	288 kVA, 230 kW, 798 Amps.
Installation Year	1993
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Connected To Emergency Generator System</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Relay Test Switch</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	Inspected
<b>Connected To Emergency Generator System</b>	Does not exist
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	Under construction
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance	1st floor
<b>Lighting</b>	
Instance on 1st floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 1st floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	
Instance on 1st floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st floor	Does not exist
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Under construction
<b>Holding Area</b>	Does not exist
<b>KITCHEN/WARMING PANTRY</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>KITCHEN/WARMING PANTRY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	Inspected
Instance	Room 305
Has LAN/Modem access	Yes
<b>Lighting</b>	
Instance on Room 305	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 305	Inspected
<b>Pendant Mounted</b>	
Instance on Room 305	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on Room 305	Does not exist
<b>Surface Mounted</b>	
Instance on Room 305	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 305	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 305	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 305	Inspected
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Raceway With Receptacles</b>	
Deficiency	No deficiencies recorded
<b>LIGHTING - EXTERIOR SECURITY</b>	
Condition	Inspected
Replacement Quantity	3- Fair
Replacement Uom	54
Deficiency	EACH
Deficiency Location/Instance	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	canopy at main door
Quantity Uom	25
Potential Action	EACH
Urgency of Action	REPLACE-UPGRADE
Purpose of Action	PRIORITY 1
Violations	LEVEL 3
Deficiency	No violations recorded
Deficiency Location/Instance	TIME CLOCK NOT OPERATIONAL
Deficiency Quantity	Basement
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 4
Violations	LEVEL 3
Violations	No violations recorded
<b>LIGHTNING PROTECTION</b>	
	Does not exist
<b>LOCKER ROOM/SHOWER ROOM</b>	
	Inspected
Instance	1st floor, Boys
Alternative Use	No
Instance	1st floor, Girls
Alternative Use	Yes
<b>Lighting</b>	
Instance on 1st floor, Boys	Inspected
Instance on 1st floor, Girls	Not required
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st floor, Boys	Inspected
<b>Pendant Mounted</b>	
Instance on 1st floor, Boys	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st floor, Boys	Does not exist
<b>Surface Mounted</b>	
Instance on 1st floor, Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st floor, Boys	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st floor, Boys	Inspected
<b>Pendant Mounted</b>	
Instance on 1st floor, Boys	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>LOCKER ROOM/SHOWER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 1st floor, Boys	Does not exist
<b>Surface Mounted</b>	
Instance on 1st floor, Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>MOTOR CONTROL CENTER</b>	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Standard Products Co.
EquipmentId	Motor Control Center No.1
Capacity/Size	400 Amps, 2 sections.
Installation Year	1972
Deficiency	No deficiencies recorded
Instance	Room 129
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Standard Products Co.
EquipmentId	Motor Control Center No.2
Capacity/Size	400 Amps, 1 section.
Installation Year	1972
Deficiency	No deficiencies recorded
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Toggle Switch Type</b>	
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	176,000
Replacement Uom	S.F.
Instance	General Office, Room 227
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	DUKANE 250, MPA 250
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SECURITY</b>	Inspected
Replacement Quantity	176,000
Replacement Uom	S.F.
<b>Intrusion Alarm</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office, Room 100
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	VISTA-128B (Ademco)
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not exist
<b>IPDVS/CCTV System</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Inspected
<b>Air Circuit Breaker Type</b>	Does not exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room, Basement.
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE
EquipmentId	N/A
Capacity/Size	4000 Amps total, 4 sections.

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Installation Year	1972
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room, Basement.
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pringle Elect. Mfg. Co.
EquipmentId	N/A
Capacity/Size	800 Amps total, 3 sections.
Installation Year	1998
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room, Basement.
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Corp.
EquipmentId	DP-EM
Capacity/Size	400 Amps total, 1 section.
Installation Year	1972
Deficiency	No deficiencies recorded
Instance	Room 129
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric Products Co.
EquipmentId	N/A
Capacity/Size	1200 Amps total, 2 sections.
Installation Year	1972
Deficiency	SWITCHBOARD ID IS MISSING

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**X084**

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Fan room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE
EquipmentId	EMP
Capacity/Size	400 Amps total, 1section.
Installation Year	1972
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE LENS MISSING
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist
<b>TV SYSTEM</b>	Inspected
<b>Cable Service</b>	Inspected

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

X084

Question	Response
<b>TV SYSTEM</b>	
<b>Cable Service</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack</b>	Does not exist
<b>Master Antenna System</b>	Does not exist