

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

School: **I.S. 125 - BRONX, 1111 PUGSLEY AVENUE, BRONX, NY, 10472**

InspectionId	Inspection Type	Time In	Last Edited
1640085	MECHANICAL	2010-11-23 08:13AM	2011-04-21 11:03AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: MDF & IDF Room DX Split Systems Years: 2010 Systems: Water Main (1/2), Sprinkler Alarm Valve Assembly. Years: 2008 Systems: MDF Room DX Split System Years: 2006 Systems: Fuel Oil Storage System, Sewage Ejector Pumps Years: 2005
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	20,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Underneath Auditorium & Room B25
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
CLIMATE CONTROL SYSTEM	Inspected
DDC SYSTEM	Does not exist
ELECTRIC SYSTEM	Does not exist
HYBRID SYSTEM	Does not exist
PNEUMATIC SYSTEM	Inspected
Instance	Throughout (excluding hallways, stairwells, and bathrooms)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
ASH HOIST	Does not exist
DUMBWAITERS	Does not exist
ELEVATORS	Does not exist
ESCALATORS	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
SIDEWALK ELEVATOR	Inspected
Condition	4- Between Fair and Poor

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
CONVEYING	
SIDEWALK ELEVATOR	
Deficiency	HYDRAULIC:DEFECTIVE
Deficiency Location/Instance	Kitchen & Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DOMESTIC WATER SYSTEM	
	Inspected
DOMESTIC COLD WATER SYSTEM	
	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Service Piping (Water Main)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Water Main - Double Check Valve	Does not exist
Water Main - RPZ	Does not exist
DOMESTIC HOT WATER SYSTEM	
	Inspected
Domestic Hot Water Circulating Pump	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	4- Between Fair and Poor
Deficiency	DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE REGULATOR
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
DOMESTIC WATER DISTRIBUTION PIPING	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
HOUSE TRAP	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERIOR FLOOR DRAIN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERIOR STORM PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SEWAGE / WASTE PIPING	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room/ Waste line from bathroom above leaking.
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SEWAGE EJECTOR PUMP	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SUMP PUMP	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
VENT PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
STAFF AND OTHER	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
STUDENT	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
FIXTURES	
STUDENT	
Lavatory/Sink	
Deficiency	NOT IN USE
Deficiency Location/Instance	Room B 31
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Locker Room Shower	
	Inspected
Instance on Basement (Inside Gym)	Inspected
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative Use	Yes
Deficiency	NOT IN USE
Deficiency Location/Instance	Basement (Inside Gym)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room B31	Inspected
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative Use	No
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	
	Does not exist
Toilet	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	
	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Inside Gym (Boys' locker Room Shower)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
GAS FIRED FURNACE	
	Does not exist
GAS SERVICE	
	Inspected
CO/GAS LEAK DETECTION	
	Does not exist
GAS DISTRIBUTION PIPING	
	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement/ Gas line to science labs corroded and valved off.
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
GAS SERVICE	
GAS DISTRIBUTION PIPING	
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS METER ROOM EXHAUST FAN	Does not exist
GAS METER ROOM VENT	Does not exist
GAS PRESSURE BOOSTER	Does not exist
HEATING	Inspected
BASEBOARD/FIN TUBE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING COILS IN DUCTWORK	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Rooms 257 (2/4) & B37 (2/4)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HYDRONIC HEATING	Does not exist
RADIATOR / CONVECTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STEAM HEATING	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Rooms 329, 322,335, 364, 257,235, 229,135, 129, B37, B 11
Deficiency Quantity	660
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Custodian Locker Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
HEATING	
STEAM HEATING	
Terminal Unit Thermostatic Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STEAM SUPPLIED BY EXTERNAL SOURCES	Does not exist
UNIT HEATER/CABINET HEATER	Does not exist
HEATING PLANT	Inspected
Replacement Quantity	13,509
Replacement Uom	MBH
Instance	Basement
Burner Type	Oil
Heating Plant Oil Number	4
BOILER AUXILIARIES	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Does not exist
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	300
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
BOILER SYSTEM	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
HEATING PLANT	
BOILER SYSTEM	
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	4,503
Instance Quantity Uom	MBH
Manufacturer	Ferrar & Trefts
EquipmentId	41150-1
Capacity/Size	50 GPH
Installation Year	1952
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	4,503
Instance Quantity Uom	MBH
Manufacturer	Ferrar & Trefts
EquipmentId	41150-2
Capacity/Size	50 GPH
Installation Year	1952
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	4,503

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
HEATING PLANT	
BOILER SYSTEM	
Steam Boiler	
Instance Quantity Uom	MBH
Manufacturer	Ferrar & Trefts
EquipmentId	41150-3
Capacity/Size	50 GPH
Installation Year	1952
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUEL SYSTEMS	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BURNER CONTROL PANEL:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	OIL BURNER:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
IDF (ENCLOSED ROOMS)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
IDF (ENCLOSED ROOMS)	
Instance	Room 227
A/C EQUIPMENT	
Instance on Room 227	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
VENTILATION EQUIPMENT	
Instance on Room 227	Does not exist
KITCHEN	Inspected
Instance	Basement
CO DETECTOR	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS SYSTEM	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GREASE TRAP	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE/CLOGGED
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HOOD	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD EXHAUST DUCTWORK	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD EXHAUST FAN	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD FIRE SUPPRESSION SYSTEM	
Instance on Basement	Does not exist
HOT WATER TEMPERATURE BOOSTER	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
KITCHEN SINK	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
KITCHEN	
KITCHEN SINK	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF ROOM	
Instance	Inspected
Instance	Room 237
A/C EQUIPMENT	
Instance on Room 237	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
VENTILATION EQUIPMENT	
Instance on Room 237	Does not exist
SCIENCE DEMO ROOM	
Instance on Rooms 347, 349, 351	Inspected
Alternative Use	Yes
Instance on Room 249	Inspected
Alternative Use	No
ACID WASTE NEUTRALIZING TANK	
Instance on Rooms 347, 349, 351	Does not exist
Instance on Room 249	Does not exist
EMERGENCY SHOWER	
Instance on Rooms 347, 349, 351	Does not exist
Instance on Room 249	Does not exist
EYE WASH	
Instance on Rooms 347, 349, 351	Does not exist
Instance on Room 249	Does not exist
FIXED LABORATORY HOOD	
Instance on Rooms 347, 349, 351	Does not exist
Instance on Room 249	Does not exist
LABORATORY SINK	
Instance on Rooms 347, 349, 351	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Rooms 349, 347, 351
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room 249	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
PORTABLE LABORATORY HOOD	
Instance on Rooms 347, 349, 351	Does not exist
Instance on Room 249	Does not exist
SCIENCE LAB	
Instance on Rooms 343, 243	Inspected
Alternative Use	No
Instance on Rooms 326	Inspected
Alternative Use	Yes
Instance on Room 247	Inspected
Alternative Use	Yes

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
SCIENCE LAB	
ACID WASTE NEUTRALIZING TANK	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
CO DETECTOR	
Instance on Rooms 343, 243	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DETECTOR MISSING
Deficiency Location/Instance	Rooms 343, 243
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance on Rooms 326	Not required
Instance on Room 247	Not required
EMERGENCY SHOWER	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
EYE WASH	
Instance on Rooms 343, 243	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Rooms 343, 243
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms 326	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room 326
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room 247	Does not exist
FIXED LABORATORY HOOD	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
HOOD EXHAUST DUCTWORK	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
HOOD EXHAUST FAN	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
SCIENCE LAB	
LABORATORY SINK	
Instance on Rooms 343, 243	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 326	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Rooms 326
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Instance on Room 247	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room 247
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
MAKE-UP AIR UNIT	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
PORTABLE LABORATORY HOOD	
Instance on Rooms 343, 243	Does not exist
Instance on Rooms 326	Does not exist
Instance on Room 247	Does not exist
SCIENCE PREP ROOM	
Instance on Rooms 245,345	Inspected
Alternative Use	No
ACID WASTE NEUTRALIZING TANK	
Instance on Rooms 245,345	Does not exist
EMERGENCY SHOWER	
Instance on Rooms 245,345	Does not exist
EYE WASH	
Instance on Rooms 245,345	Does not exist
FIXED LABORATORY HOOD	
Instance on Rooms 245,345	Does not exist
HOOD EXHAUST DUCTWORK	
Instance on Rooms 245,345	Does not exist
HOOD EXHAUST FAN	
Instance on Rooms 245,345	Does not exist
LABORATORY SINK	
Instance on Rooms 245,345	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MAKE-UP AIR UNIT	
Instance on Rooms 245,345	Does not exist
PORTABLE LABORATORY HOOD	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X125

Question	Response
SCIENCE PREP ROOM	
PORTABLE LABORATORY HOOD	
Instance on Rooms 245,345	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
DELUGE VALVE	Does not exist
FIRE BOOSTER PUMP ASSEMBLY	Does not exist
ROOF TANK	Does not exist
SIAMESE CONNECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SPRINKLER ALARM VALVE ASSEMBLY	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SPRINKLER HEAD	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SPRINKLER PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STANDPIPE SYSTEM	Does not exist
WATER GONG	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
EXHAUST FAN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING AND VENTILATING UNIT	Does not exist
METAL DUCTWORK	Inspected
Condition	3- Fair
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	Room 257 (Gir'l's Gym Blower)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SUPPLY FAN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
UNIT VENTILATOR	Does not exist