

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

School: P.S. 161 - BRONX, 628 TINTON AVENUE, BRONX, NY, 10455

InspectionId	Inspection Type	Time In	Last Edited
1640086	MECHANICAL	2010-11-24 08:08AM	2010-12-06 02:23PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Climate Control System Compressor, Air Dryers and PRV Station Years: 2009 Systems: Boiler Refractory Lining Repair. Years: 2009 Systems: DX Split System for MDF Room Years: 2005
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
DDC SYSTEM	Does not exist
ELECTRIC SYSTEM	Does not exist
HYBRID SYSTEM	Does not exist
PNEUMATIC SYSTEM	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	PNEUMATIC TUBING:DEFECTIVE/LEAKS AIR
Deficiency Location/Instance	Rooms 405, 420, 325 (Pneumatic Tubes missing)
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT THERMOSTATIC VALVE
Deficiency Location/Instance	Dooms 405, 420, 325
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
ASH HOIST	Inspected
Condition	3- Fair
Deficiency	NOT IN USE

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
CONVEYING	
ASH HOIST	
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
DUMBWAITERS	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
ELEVATORS	Does not exist
ESCALATORS	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
SIDEWALK ELEVATOR	Does not exist
DOMESTIC WATER SYSTEM	Inspected
DOMESTIC COLD WATER SYSTEM	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Service Piping (Water Main)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Main - Double Check Valve	Does not exist
Water Main - RPZ	Does not exist
DOMESTIC HOT WATER SYSTEM	Inspected
Domestic Hot Water Circulating Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE TEMPERATURE REGULATOR
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
DOMESTIC WATER DISTRIBUTION PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
HOUSE TRAP	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERIOR FLOOR DRAIN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
INTERIOR STORM PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SEWAGE / WASTE PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SEWAGE EJECTOR PUMP	Does not exist
SUMP PUMP	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
VENT PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
STAFF AND OTHER	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STUDENT	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
GAS SERVICE	Inspected
CO/GAS LEAK DETECTION	Does not exist
GAS DISTRIBUTION PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS METER ROOM EXHAUST FAN	Does not exist
GAS METER ROOM VENT	Does not exist
GAS PRESSURE BOOSTER	Does not exist
HEATING	Inspected
BASEBOARD/FIN TUBE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING COILS IN DUCTWORK	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HYDRONIC HEATING	Does not exist
RADIATOR / CONVECTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STEAM HEATING	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement (Fan Room B8)
Deficiency Quantity	225
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement (Boiler Room)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement (Behind wall of Room B5 and Supply line from Header between Boilers))
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
HEATING	
STEAM HEATING	
Steam Piping	
Violations	No violations recorded
Terminal Unit Thermostatic Trap	
Condition	3- Fair
Deficiency	No deficiencies recorded
STEAM SUPPLIED BY EXTERNAL SOURCES	
UNIT HEATER/CABINET HEATER	
HEATING PLANT	
Replacement Quantity	9,774
Replacement Uom	MBH
Instance	Basement
Burner Type	Oil
Heating Plant Oil Number	6
BOILER AUXILIARIES	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Does not exist
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Does not exist
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
BOILER SYSTEM	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
HEATING PLANT	
BOILER SYSTEM	
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	4,887
Instance Quantity Uom	MBH
Manufacturer	Federal Boiler Corp.
EquipmentId	53862-1
Capacity/Size	4887 MBH (Net)
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	4,887
Instance Quantity Uom	MBH
Manufacturer	Federal Boiler Corp.
EquipmentId	53862-2
Capacity/Size	4887 MBH (Net)
Installation Year	1968
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PLUGGED TUBES
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
FUEL SYSTEMS	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
HEATING PLANT	
FUEL SYSTEMS	
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BURNER CONTROL PANEL:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	OIL BURNER:BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BURNER CONTROL PANEL:DEFECTIVE
Deficiency Location/Instance	Basement (Pilot Burner Control)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
IDF (ENCLOSED ROOMS)	
Does not exist	
KITCHEN	
Inspected	
Instance	1st Floor
CO DETECTOR	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS SYSTEM	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GREASE TRAP	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD	

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
KITCHEN	
HOOD	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD EXHAUST DUCTWORK	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD EXHAUST FAN	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
HOOD FIRE SUPPRESSION SYSTEM	
Instance on 1st Floor	Does not exist
HOT WATER TEMPERATURE BOOSTER	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
KITCHEN SINK	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF ROOM	Inspected
Instance	Room 121
A/C EQUIPMENT	
Instance on Room 121	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
VENTILATION EQUIPMENT	
Instance on Room 121	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
DELUGE VALVE	Does not exist
FIRE BOOSTER PUMP ASSEMBLY	Does not exist
ROOF TANK	Does not exist
SIAMESE CONNECTION	Does not exist
SPRINKLER ALARM VALVE ASSEMBLY	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SPRINKLER HEAD	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SPRINKLER PIPING	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
STANDPIPE SYSTEM	Does not exist
WATER GONG	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
EXHAUST FAN	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2010-2011**

Mechanical Inspection

X161

Question	Response
VENTILATION	
EXHAUST FAN	
Deficiency	No deficiencies recorded
HEATING AND VENTILATING UNIT	Inspected
Condition	3- Fair
Deficiency	BEYOND USEFUL LIFE - NON DEFECTIVE
Deficiency Location/Instance	Basement (Fan Room B8)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NOT IN USE
Deficiency Location/Instance	Roof
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
METAL DUCTWORK	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SUPPLY FAN	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
UNIT VENTILATOR	Does not exist