

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K866

School: **I.S. 364 AX (POOL&GYM)-BROOKLYN, 1540 VAN SICLEN AVE, BROOKLYN, NY, 11239**

InspectionId	Inspection Type	Time In	Last Edited
1294085	ELECTRICAL	2009-03-24 01:59PM	2009-03-31 03:02PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded

Priority Condition

No condition recorded

Inspection

Question	Response
ELECTRICAL	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
CAFETERIA	Does not exist
CAFETERIA/MULTIPURPOSE ROOM	Does not exist
CITY FIRE ALARM SYSTEM	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not exist
ELECTRIC SERVICE SWITCH	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Does not exist
Relay Test Switch	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Connected To Emergency Generator System	Does not exist
Connected To Emergency Light/Exit Light Panel	Does not exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	5,000
Replacement Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K866

Question	Response
FIRE ALARM SYSTEM	
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Does not exist
Heat Detector	Does not exist
Magnetic Door Holder Contactor	Does not exist
Main Panel	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Does not exist
GYMNASIUM	Inspected
Instance	First Floor
Lighting	
Instance on First Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on First Floor	Does not exist
Lighting Fixture - HID	
Instance on First Floor	Inspected
Pendant Mounted	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on First Floor	Does not exist
Surface Mounted	
Instance on First Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on First Floor	Does not exist
Local Sound System	
Instance on First Floor	Does not exist
Scoreboard	
Instance on First Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Electrical Inspection

K866

Question	Response
GYMNASIUM	
Theater Lighting System	
Instance on First Floor	Does not exist
INTERCOM SYSTEM	Does not exist
KITCHEN/WARMING PANTRY	Does not exist
LAN	Does not exist
LIBRARY	Does not exist
LIGHTING - EXTERIOR SECURITY	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM/SHOWER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Does not exist
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Does not exist
PUBLIC ADDRESS SYSTEM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Replacement Quantity	5,000
Replacement Uom	S.F.
Intrusion Alarm	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist