

**NYC Department of Education  
Building Condition Assessment Survey 2010-2011**

***Mechanical Inspection***

**Q466**

**School:** FAR ROCKAWAY AF - QUEENS, 821 BEACH 25 STREET, QUEENS, NY, 11691

InspectionId	Inspection Type	Time In	Last Edited
1580115	MECHANICAL	2011-02-16 12:50PM	2011-02-23 03:22PM

***Asset Data***

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No

***Priority Condition***

No condition recorded

***Inspection***

Question	Response
<b>MECHANICAL</b>	
<b>AIR CONDITIONING</b>	Does not exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Does not exist
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Does not exist
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Does not exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>FIXTURES</b>	Does not exist
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Does not exist
<b>HEATING</b>	Does not exist
<b>HEATING PLANT</b>	Does not exist
<b>IDF (ENCLOSED ROOMS)</b>	Does not exist
<b>KITCHEN</b>	Does not exist
<b>MDF ROOM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Does not exist