

**NYC Department of Education
Building Condition Assessment Survey 2008-2009**

Mechanical Inspection

Q487

School: CLEVELAND AF NO. 1 - QUEENS, 21-27 HIMROD STREET, QUEENS, NY, 11385

InspectionId	Inspection Type	Time In	Last Edited
1264176	MECHANICAL	2009-06-15 11:41AM	2009-06-23 03:54PM

Asset Data

Question	Answer
Heating Plant Oil Number	N/A
Have any Systems/Major Building Components been upgraded?	No System Upgraded

Priority Condition

No condition recorded

Inspection

Question	Response
MECHANICAL	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Does not exist
DRAIN/WASTE/VENT AND STORM SYSTEM	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
EMERGENCY GENERATOR	Does not exist
FIXTURES	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
HEATING	Does not exist
HEATING PLANT	Does not exist
KITCHEN	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Does not exist