

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

School: **HS FOR CONST.TRADES,ENGG.,& ARCH-Q, 94-06 104TH STREET, QUEENS, NY, 11416**

InspectionId	Inspection Type	Time In	Last Edited
1254098	ELECTRICAL	2009-03-24 08:45AM	2009-04-01 10:46AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded

**Priority Condition**

No condition recorded

**Inspection**

Question	Response
<b>ELECTRICAL</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance	1st Floor
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	1- Good
Replacement Quantity	137,000
Replacement Uom	S.F.
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance	Basement-Student
<b>Lighting</b>	
Instance on Basement-Student	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement-Student	Inspected
<b>Pendant Mounted</b>	
Instance on Basement-Student	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement-Student	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement-Student	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement-Student	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement-Student	Does not exist
<b>Local Sound System</b>	
Instance on Basement-Student	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>CAFETERIA/MULTIPURPOSE ROOM</b>	
	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
	Does not exist
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	Inspected
<b>Pendant Mounted</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>COMPUTER LAB</b>	Inspected
Instance	Room 208,224,352,356,424
Has LAN/Modem access	Yes
Power Panel?	Yes
<b>Lighting</b>	
Instance on Room 208,224,352,356,424	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 208,224,352,356,424	Inspected
<b>Pendant Mounted</b>	
Instance on Room 208,224,352,356,424	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 208,224,352,356,424	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 208,224,352,356,424	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 208,224,352,356,424	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 208,224,352,356,424	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 208,224,352,356,424	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>ELECTRIC SERVICE SWITCH</b>	Inspected
Instance	Room B8
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
Model	All City Switchboard
EquipmentId	Service Switchboard "B"
Capacity/Size	4000 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B8
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
Model	All City Switchboard
EquipmentId	Service Switchboard "A"
Capacity/Size	4000 Amps
Installation Year	2006
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Room B8
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	ATS#3
Capacity/Size	600 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B10A
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	N/A
Capacity/Size	800 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B10A
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	N/A
Capacity/Size	400 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B10A
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	Fire Alarm ATS
Capacity/Size	104 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B10B
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron
EquipmentId	Fire Pump ATS
Capacity/Size	150 Amps
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Generator Enclosure
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	Battery Charger

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

Q650

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Battery Charger</b>	
Capacity/Size	15 AmpsDC, 50 VDC
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	School Yard Enclosure
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler
EquipmentId	Generator
Capacity/Size	402 kW
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Does not exist
<b>Connected To Emergency Generator System</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Relay Test Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Connected To Emergency Generator System</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Connected To Emergency Light/Exit Light Panel</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	137,000
Replacement Uom	S.F.
<b>Area Smoke Detector</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Bell/Horn</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	1- Good

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Elevator Recall</b>	
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Room B10B
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ademco
EquipmentId	Fire Alarm Communicator
Capacity/Size	5 zones
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder Contactor</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Lobby
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
Model	EST3
EquipmentId	Fire Alarm Control Panel/ Purge Panel
Capacity/Size	12 zones
Installation Year	2006
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Manual Pull Station</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	1- Good

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sprinkler Flow/Air Pressure Switch</b>	
Deficiency	No deficiencies recorded
<b>Strobe</b>	
Condition	Inspected
Deficiency	1- Good
<b>Sub-Panel</b>	
Deficiency	No deficiencies recorded
<b>Bell At Panel</b>	
Condition	Inspected
Deficiency	1- Good
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance	No deficiencies recorded
Instance Condition	Inspected
Instance Quantity	Main Lobby
Instance Quantity Uom	1- Good
Manufacturer	1
Model	EACH
EquipmentId	Edwards
Capacity/Size	EST3
Installation Year	Horn Panel/Strobe Panel
Deficiency	N/A
<b>Fire Alarm Control Panel (Standard)</b>	
Instance	2006
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	
Condition	Does not exist
Deficiency	Inspected
<b>GROUNDING SYSTEM</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance	Inspected
<b>Lighting</b>	
Instance on Basement	Basement
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Local Sound System</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on Basement	Does not exist
<b>INTERCOM SYSTEM</b>	
	Inspected
<b>Elevator</b>	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
<b>Holding Area</b>	
	Does not exist
<b>KITCHEN/WARMING PANTRY</b>	
	Inspected
<b>Lighting</b>	
	Inspected
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
	Does not exist
<b>Recessed Mounted</b>	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
<b>Surface Mounted</b>	
	Does not exist
<b>Lighting Fixture - HID</b>	
	Does not exist
<b>Lighting Fixture - Incandescent</b>	
	Does not exist
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
	Inspected
Instance	Room 305
Has LAN/Modem access	Yes
<b>Lighting</b>	
Instance on Room 305	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 305	Inspected
<b>Pendant Mounted</b>	
Instance on Room 305	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 305	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 305	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 305	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 305	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 305	Inspected



**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>LOCKER ROOM/SHOWER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Basement-Male(B34)	Does not exist
Instance on Basement-Visitor(B43)	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Basement-Female(B36)	Does not exist
Instance on Basement-Male(B34)	Does not exist
Instance on Basement-Visitor(B43)	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement-Female(B36)	Does not exist
Instance on Basement-Male(B34)	Does not exist
Instance on Basement-Visitor(B43)	Does not exist
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	137,000
Replacement Uom	S.F.
Instance	Room 133
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance	Room 310,316,332,336
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Room 310,316,332,336	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 310,316,332,336	Inspected
<b>Pendant Mounted</b>	
Instance on Room 310,316,332,336	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

Q650

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 310,316,332,336	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 310,316,332,336	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 310,316,332,336	Inspected
<b>Pendant Mounted</b>	
Instance on Room 310,316,332,336	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 310,316,332,336	Does not exist
<b>Surface Mounted</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 310,316,332,336	Inspected
<b>Instructor Unit</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 310,316,332,336	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE LAB</b>	Inspected
Instance	Room 320, 328
Has LAN/Modem access	Yes
Power Panel?	Yes
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Room 320, 328	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 320, 328	Inspected
<b>Pendant Mounted</b>	
Instance on Room 320, 328	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

NYC Department of Education  
Building Condition Assessment Survey 2008-2009

*Electrical Inspection*

Q650

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 320, 328	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 320, 328	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 320, 328	Inspected
<b>Pendant Mounted</b>	
Instance on Room 320, 328	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 320, 328	Does not exist
<b>Surface Mounted</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 320, 328	Inspected
<b>Instructor Unit</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 320, 328	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	Inspected
Instance	Room 324
Has LAN/Modem access	Yes
Power Panel?	No
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 324	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 324	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Room 324	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 324	Inspected
<b>Pendant Mounted</b>	
Instance on Room 324	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 324	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 324	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 324	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 324	Does not exist
<b>Power Supply</b>	
Instance on Room 324	Inspected
<b>Instructor Unit</b>	
Instance on Room 324	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
Replacement Quantity	137,000
Replacement Uom	S.F.
<b>Intrusion Alarm</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Custodian Office
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Ademco Vista-250BP
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not exist
<b>IPDVS/CCTV System</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Inspected
<b>Air Circuit Breaker Type</b>	Does not exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Room B8
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size	4000 Amps total, 5 sections
Installation Year	2006

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room B8
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size	4000 Amps total, 5 sections
Installation Year	2006
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SWITCHBOARD NAME PLATE IS MISSING
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room B10A
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	EDP
Capacity/Size	800 Amps total, 2 sections
Installation Year	2006
Deficiency	No deficiencies recorded
Instance	Room B7
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size	1200 Amps total, 1 section
Installation Year	2006
Deficiency	SWITCHBOARD ID IS MISSING
Deficiency Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2008-2009**

**Electrical Inspection**

**Q650**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist
<b>TV SYSTEM</b>	Inspected
<b>Cable Service</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Master Antenna System</b>	Does not exist